

7:19:17.125: DVDRSYS.DLL: Going to resize device driver data array to 1 items
7:19:17.234: DVDRSYS.DLL: Going to use device driver data on index: 0
7:19:17.234: DVDRSYS.DLL: Going to call LoadLibrary for the 1th time
7:19:17.234: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE
Development\RadiMation\Version 5.8.37\ARAMP.DLL
7:19:17.296: DVDRSYS.DLL: Going to create device driver: AR150W1000
7:19:17.359: DVDRSYS.DLL: Going to call 'Registered' of the device driver
7:19:17.359: DVDRSYS.DLL: RegisterDeviceDriver((Device) AR150W1000, (DLL)
C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL) returns (ID) 0
7:19:17.359: DVDRSYS.DLL: LoadConfiguration((ID) 0, (FileName) C:\Programme\DARE
Development\RadiMation\CONFDVDR\RDC813.INI)
7:19:17.375: DVDRSYS.DLL: InitDevice((ID) 0)
7:19:17.500: NIGPIBDD: SendGPIB: R

7:19:17.500: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:17.515: DVDRSYS.DLL: Going to resize device driver data array to 2 items
7:19:17.515: DVDRSYS.DLL: Going to use device driver data on index: 1
7:19:17.515: DVDRSYS.DLL: Going to call LoadLibrary for the 2th time
7:19:17.515: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE
Development\RadiMation\Version 5.8.37\ARAMP.DLL
7:19:17.531: DVDRSYS.DLL: Going to create device driver: AR150W1000
7:19:17.531: DVDRSYS.DLL: Going to call 'Registered' of the device driver
7:19:17.546: DVDRSYS.DLL: RegisterDeviceDriver((Device) AR150W1000, (DLL)
C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL) returns (ID)
65537
7:19:17.546: DVDRSYS.DLL: LoadConfiguration((ID) 65537, (FileName)
C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC18772.INI)
7:19:17.562: DVDRSYS.DLL: InitDevice((ID) 65537)
7:19:17.562: NIGPIBDD: SendGPIB: R

7:19:17.578: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:17.578: DVDRSYS.DLL: Going to resize device driver data array to 3 items
7:19:17.578: DVDRSYS.DLL: Going to use device driver data on index: 2
7:19:17.593: DVDRSYS.DLL: Going to call LoadLibrary for the 3th time
7:19:17.593: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE
Development\RadiMation\Version 5.8.37\ARAMP.DLL
7:19:17.593: DVDRSYS.DLL: Going to create device driver: AR150W1000
7:19:17.609: DVDRSYS.DLL: Going to call 'Registered' of the device driver
7:19:17.609: DVDRSYS.DLL: RegisterDeviceDriver((Device) AR150W1000, (DLL)
C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL) returns (ID)
131074
7:19:17.609: DVDRSYS.DLL: LoadConfiguration((ID) 131074, (FileName)
C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC25244.INI)
7:19:17.625: DVDRSYS.DLL: InitDevice((ID) 131074)
7:19:17.640: NIGPIBDD: SendGPIB: R

7:19:17.640: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:17.656: DVDRSYS.DLL: Going to resize device driver data array to 4 items
7:19:17.656: DVDRSYS.DLL: Going to use device driver data on index: 3
7:19:17.671: DVDRSYS.DLL: Going to call LoadLibrary for the 4th time

7:19:17.671: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL
7:19:17.687: DVDRSYS.DLL: Going to create device driver: AR150A100BC
7:19:17.687: DVDRSYS.DLL: Going to call 'Registered' of the device driver
7:19:17.703: DVDRSYS.DLL: RegisterDeviceDriver((Device) AR150A100BC, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL) returns (ID) 196611
7:19:17.703: DVDRSYS.DLL: LoadConfiguration((ID) 196611, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC79755.INI)
7:19:17.718: DVDRSYS.DLL: InitDevice((ID) 196611)
7:19:17.734: NIGPIBDD: SendGPIB: R

7:19:17.734: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:22.734: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:22.734: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:22.734: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:22.734: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:27.750: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:27.750: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:27.750: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:27.750: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:32.781: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:32.781: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:32.781: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:32.781: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:37.796: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:37.796: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:37.796: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:37.796: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:42.812: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:42.812: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:42.812: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:42.812: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:47.843: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:47.843: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:47.843: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:47.843: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:52.875: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:52.875: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:52.875: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:52.875: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:19:57.890: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:19:57.890: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:19:57.890: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:19:57.890: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:20:02.906: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:20:02.906: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:20:02.906: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
7:20:02.906: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
7:20:07.921: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
7:20:07.921: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
7:20:07.921: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

8:11:22.312: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:11:27.328: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:11:27.328: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:11:27.328: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:11:27.328: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:11:32.343: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:11:32.343: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:11:32.343: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:11:32.343: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:11:37.359: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:11:37.359: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:11:37.359: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:11:37.359: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:11:42.375: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:11:42.375: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:11:42.375: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:11:42.375: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:11:48.765: DVDRSYS.DLL: Going to resize device driver data array to 5 items
8:11:48.765: DVDRSYS.DLL: Going to use device driver data on index: 4
8:11:48.781: DVDRSYS.DLL: Going to call LoadLibrary for the 5th time
8:11:48.781: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE
Development\RadiMation\Version 5.8.37\RADSWTCH.DLL
8:11:48.906: DVDRSYS.DLL: Going to create device driver: RADICENTREMULTISWITCH
8:11:48.906: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:11:48.953: DVDRSYS.DLL: RegisterDeviceDriver((Device)
RADICENTREMULTISWITCH, (DLL) C:\Programme\DARE
Development\RadiMation\Version 5.8.37\RADSWTCH.DLL) returns (ID) 262144
8:11:48.953: DVDRSYS.DLL: LoadConfiguration((ID) 262144, (FileName)
C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC44757.INI)
8:11:49.015: DVDRSYS.DLL: CheckDevice((ID) 262144)
8:11:50.171: NIGPIBDD: SendGPIB: S2:*IDN?

8:11:50.234: NIGPIBDD: ReceiveGPIB: RSW1002A, Version 2.0.12

8:11:50.281: NIGPIBDD: SendGPIB: S2LOCAL

8:11:50.859: NIGPIBDD: ReceiveGPIB: OK

8:11:52.093: NIGPIBDD: SendGPIB: S3:*IDN?

8:11:52.156: NIGPIBDD: ReceiveGPIB: RSW1004A, Version 2.0.12

8:11:52.187: NIGPIBDD: SendGPIB: S3LOCAL

8:11:52.437: NIGPIBDD: ReceiveGPIB: OK

8:11:53.671: NIGPIBDD: SendGPIB: S4:*IDN?

8:11:53.734: NIGPIBDD: ReceiveGPIB: RSW1002A, Version 3.2.0

8:11:53.781: NIGPIBDD: SendGPIB: S4LOCAL

8:11:54.046: NIGPIBDD: ReceiveGPIB: OK

8:11:54.125: DVDRSYS.DLL: InitDevice((ID) 262144)

8:11:57.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.2039E-045, (Data2) 0)

8:11:57.578: NIGPIBDD: SendGPIB: S2:INT_RELAY_A_NO

8:11:57.671: NIGPIBDD: ReceiveGPIB: NO

8:11:57.703: NIGPIBDD: SendGPIB: S2:INT_RELAY_B_NO

8:11:57.781: NIGPIBDD: ReceiveGPIB: NO

8:11:57.812: NIGPIBDD: SendGPIB: S3:INT_RELAY_A_NO

8:11:58.078: NIGPIBDD: ReceiveGPIB: NO

8:11:58.093: NIGPIBDD: SendGPIB: S3:INT_RELAY_B_NO

8:11:58.171: NIGPIBDD: ReceiveGPIB: NO

8:11:58.203: NIGPIBDD: SendGPIB: S4:INT_RELAY_A_NC

8:11:58.312: NIGPIBDD: ReceiveGPIB: NC

8:11:58.328: NIGPIBDD: SendGPIB: S4:INT_RELAY_B_NC

8:11:58.406: NIGPIBDD: ReceiveGPIB: NC

8:11:58.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)

8:11:58.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)

8:11:58.437: DVDRSYS.DLL: Going to resize device driver data array to 6 items

8:11:58.453: DVDRSYS.DLL: Going to use device driver data on index: 5

8:11:58.453: DVDRSYS.DLL: Going to call LoadLibrary for the 6th time

8:11:58.468: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADRSSG.DLL

8:11:58.750: DVDRSYS.DLL: Going to create device driver: RSSMA100A

8:11:58.765: DVDRSYS.DLL: Going to call 'Registered' of the device driver

8:11:58.765: DVDRSYS.DLL: RegisterDeviceDriver((Device) RSSMA100A, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADRSSG.DLL) returns (ID) 327680

8:11:58.781: DVDRSYS.DLL: LoadConfiguration((ID) 327680, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC78466.INI)

8:11:58.781: DVDRSYS.DLL: CheckDevice((ID) 327680)

8:11:58.812: NIGPIBDD: SendGPIB: *CLS

8:11:58.828: NIGPIBDD: SendGPIB: *SRE 48

8:11:58.828: NIGPIBDD: SendGPIB: *ESE 1

8:11:58.828: NIGPIBDD: SaveSendGPIB function entered

8:11:58.843: NIGPIBDD: Assigning zero string to sCommand

8:11:58.843: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:11:58.859: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:11:58.859: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 100
 8:11:58.859: NIGPIBDD: SendGPIB: *IDN?

 8:11:58.859: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:11:58.875: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
 8:11:58.875: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
 8:11:58.875: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:11:58.890: NIGPIBDD::SRQHandler: mlSuggestedReadSize: 100
 8:11:58.890: NIGPIBDD::SaveSendGPIB: mlSendTimeoutMilliseconds: 10000
 8:11:58.890: NIGPIBDD: ReceiveGPIB:
 Rohde&Schwarz,SMA100A,1400.0000k02/100580,2.2.2.3-2.05.220.02 (Release)

 8:11:58.906: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:11:58.906: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:11:58.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:11:58.906: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:11:58.906: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:11:58.921: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:11:58.937: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:11:58.937: NIGPIBDD: Just before returning the error code
 8:11:58.937: NIGPIBDD: SendGPIB: *SRE 0
 8:11:58.937: NIGPIBDD: SendGPIB: *ESE 0
 8:11:58.953: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3001) returned: 9000
 8:11:58.953: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3002) returned: 6E+009
 8:11:58.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:11:58.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:11:58.984: DVDRSYS.DLL: Going to resize device driver data array to 7 items
 8:11:58.984: DVDRSYS.DLL: Going to use device driver data on index: 6
 8:11:58.984: DVDRSYS.DLL: Going to call LoadLibrary for the 7th time
 8:11:59.000: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADEEMPTY.DLL
 8:11:59.062: DVDRSYS.DLL: Going to create device driver: CONFIGCO
 8:11:59.078: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:11:59.078: DVDRSYS.DLL: RegisterDeviceDriver((Device) CONFIGCO, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADEEMPTY.DLL) returns (ID) 393216
 8:11:59.078: DVDRSYS.DLL: LoadConfiguration((ID) 393216, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC58699.INI)
 8:11:59.093: DVDRSYS.DLL: CheckDevice((ID) 393216)
 8:11:59.093: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3001) returned: 1
 8:11:59.109: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3002) returned: 1E+009
 8:11:59.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:11:59.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:11:59.125: DVDRSYS.DLL: Going to resize device driver data array to 8 items
 8:11:59.140: DVDRSYS.DLL: Going to use device driver data on index: 7
 8:11:59.140: DVDRSYS.DLL: Going to call LoadLibrary for the 8th time

8:11:59.140: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTMP.DLL
8:11:59.171: DVDRSYS.DLL: Going to create device driver: ARPM20021
8:11:59.187: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:11:59.187: DVDRSYS.DLL: RegisterDeviceDriver((Device) ARPM20021, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTMP.DLL) returns (ID) 458752
8:11:59.187: DVDRSYS.DLL: LoadConfiguration((ID) 458752, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC17636.INI)
8:11:59.203: DVDRSYS.DLL: CheckDevice((ID) 458752)
8:11:59.828: NIGPIBDD: SendGPIO: *IDN?
8:11:59.843: NIGPIBDD: ReceiveGPIO: Amplifier Research,PM2002 RF Powermeter,321947,Ver 4.10
8:11:59.859: NIGPIBDD: SendGPIO: CH1;DB;FA;MN
8:11:59.953: NIGPIBDD: SendGPIO: TM3
8:12:00.062: NIGPIBDD: SendGPIO: TR
8:12:00.078: NIGPIBDD: ReceiveGPIO: 1,0,1,0
8:12:00.093: NIGPIBDD: SendGPIO: TM2
8:12:00.093: NIGPIBDD: ReceiveGPIO: 0,3,1
8:12:00.109: NIGPIBDD: SendGPIO: TM3
8:12:00.125: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3001) returned: 1000
8:12:00.125: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3002) returned: 4.01E+010
8:12:00.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:00.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:12:00.156: DVDRSYS.DLL: Going to resize device driver data array to 9 items
8:12:00.171: DVDRSYS.DLL: Going to use device driver data on index: 8
8:12:00.171: DVDRSYS.DLL: Going to call LoadLibrary for the 9th time
8:12:00.171: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTMP.DLL
8:12:00.187: DVDRSYS.DLL: Going to create device driver: ARPM20022
8:12:00.187: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:12:00.187: DVDRSYS.DLL: RegisterDeviceDriver((Device) ARPM20022, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTMP.DLL) returns (ID) 524289
8:12:00.203: DVDRSYS.DLL: LoadConfiguration((ID) 524289, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC91617.INI)
8:12:00.218: DVDRSYS.DLL: CheckDevice((ID) 524289)
8:12:00.937: NIGPIBDD: SendGPIO: *IDN?
8:12:00.937: NIGPIBDD: ReceiveGPIO: Amplifier Research,PM2002 RF Powermeter,321947,Ver 4.10
8:12:00.953: NIGPIBDD: SendGPIO: CH2;DB;FA;MN
8:12:01.046: NIGPIBDD: SendGPIO: TM3
8:12:01.171: NIGPIBDD: SendGPIO: TR
8:12:01.625: NIGPIBDD: ReceiveGPIO: 1,0,1,0
8:12:01.640: NIGPIBDD: SendGPIO: TM2
8:12:01.640: NIGPIBDD: ReceiveGPIO: 0,3,2
8:12:01.656: NIGPIBDD: SendGPIO: TM3
8:12:01.671: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3001) returned: 1000

8:12:01.687: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3002) returned: 4.01E+010
8:12:01.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:01.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:12:01.703: DVDRSYS.DLL: Going to resize device driver data array to 10 items
8:12:01.718: DVDRSYS.DLL: Going to use device driver data on index: 9
8:12:01.718: DVDRSYS.DLL: Going to call LoadLibrary for the 10th time
8:12:01.734: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTMP.DLL
8:12:01.734: DVDRSYS.DLL: Going to create device driver: BT9200B1
8:12:01.750: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:12:01.750: DVDRSYS.DLL: RegisterDeviceDriver((Device) BT9200B1, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTMP.DLL) returns (ID) 589826
8:12:01.750: DVDRSYS.DLL: LoadConfiguration((ID) 589826, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC13072.INI)
8:12:01.765: DVDRSYS.DLL: CheckDevice((ID) 589826)
8:12:02.296: NIGPIBDD: SendGPIB: 1N
8:12:02.406: NIGPIBDD: ReceiveGPIB: DBA-6716E-2,0,0

8:12:02.421: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3001) returned: 1000
8:12:02.421: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3002) returned: 1.81E+010
8:12:02.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:02.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:12:02.453: DVDRSYS.DLL: Going to resize device driver data array to 11 items
8:12:02.453: DVDRSYS.DLL: Going to use device driver data on index: 10
8:12:02.468: DVDRSYS.DLL: Going to call LoadLibrary for the 11th time
8:12:02.468: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL
8:12:02.531: DVDRSYS.DLL: Going to create device driver: FCCF65
8:12:02.546: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:12:02.562: DVDRSYS.DLL: RegisterDeviceDriver((Device) FCCF65, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL) returns (ID) 655360
8:12:02.562: DVDRSYS.DLL: LoadConfiguration((ID) 655360, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC82044.INI)
8:12:02.562: DVDRSYS.DLL: CheckDevice((ID) 655360)
8:12:02.578: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3001) returned: 100000
8:12:02.578: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3002) returned: 1E+009
8:12:02.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:02.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:12:02.609: DVDRSYS.DLL: Going to resize device driver data array to 12 items
8:12:02.625: DVDRSYS.DLL: Going to use device driver data on index: 11
8:12:02.625: DVDRSYS.DLL: Going to call LoadLibrary for the 12th time

8:12:02.625: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADAD.DLL
8:12:02.734: DVDRSYS.DLL: Going to create device driver: TEKTRONIXTDS500A
8:12:02.750: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:12:02.750: DVDRSYS.DLL: RegisterDeviceDriver((Device) TEKTRONIXTDS500A, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADAD.DLL) returns (ID) 720896
8:12:02.765: DVDRSYS.DLL: LoadConfiguration((ID) 720896, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC39053.INI)
8:12:02.765: DVDRSYS.DLL: CheckDevice((ID) 720896)
8:12:02.781: NIGPIBDD: SendGPIB: *IDN?
8:12:02.796: NIGPIBDD: ReceiveGPIB: TEKTRONIX,TDS 544A,0,CF:91.1CT FV:v3.7e

8:12:02.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:02.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:12:02.828: DVDRSYS.DLL: Going to resize device driver data array to 13 items
8:12:02.828: DVDRSYS.DLL: Going to use device driver data on index: 12
8:12:02.843: DVDRSYS.DLL: Going to call LoadLibrary for the 13th time
8:12:02.843: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL
8:12:02.843: DVDRSYS.DLL: Going to create device driver: FCCF140A
8:12:02.843: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:12:02.859: DVDRSYS.DLL: RegisterDeviceDriver((Device) FCCF140A, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL) returns (ID) 786433
8:12:02.859: DVDRSYS.DLL: LoadConfiguration((ID) 786433, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC61487.INI)
8:12:02.875: DVDRSYS.DLL: CheckDevice((ID) 786433)
8:12:02.875: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3001) returned: 100000
8:12:02.875: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3002) returned: 1.3E+009
8:12:02.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:02.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:12:02.890: DVDRSYS.DLL: Going to resize device driver data array to 14 items
8:12:02.906: DVDRSYS.DLL: Going to use device driver data on index: 13
8:12:02.906: DVDRSYS.DLL: Going to call LoadLibrary for the 14th time
8:12:02.921: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL
8:12:02.921: DVDRSYS.DLL: Going to create device driver: AR150A100BC
8:12:02.921: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:12:02.921: DVDRSYS.DLL: RegisterDeviceDriver((Device) AR150A100BC, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL) returns (ID) 851972
8:12:02.937: DVDRSYS.DLL: LoadConfiguration((ID) 851972, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC79755.INI)
8:12:02.937: DVDRSYS.DLL: CheckDevice((ID) 851972)
8:12:02.984: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3001) returned: 10000
8:12:02.984: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3002) returned: 1000000000

8:12:03.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:12:03.000: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:12:03.015: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:12:03.015: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:12:03.015: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:12:03.015: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:12:03.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
8:12:03.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.2039E-045, (Data2) 0)
8:12:03.046: NIGPIBDD: SendGPIB: S2:INT_RELAY_A_NO

8:12:03.125: NIGPIBDD: ReceiveGPIB: NO

8:12:03.140: NIGPIBDD: SendGPIB: S2:INT_RELAY_B_NO

8:12:03.234: NIGPIBDD: ReceiveGPIB: NO

8:12:03.250: NIGPIBDD: SendGPIB: S3:INT_RELAY_A_NO

8:12:03.343: NIGPIBDD: ReceiveGPIB: NO

8:12:03.359: NIGPIBDD: SendGPIB: S3:INT_RELAY_B_NO

8:12:03.437: NIGPIBDD: ReceiveGPIB: NO

8:12:03.453: NIGPIBDD: SendGPIB: S4:INT_RELAY_A_NC

8:12:03.531: NIGPIBDD: ReceiveGPIB: NC

8:12:03.562: NIGPIBDD: SendGPIB: S4:INT_RELAY_B_NC

8:12:03.640: NIGPIBDD: ReceiveGPIB: NC

8:12:03.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
8:12:03.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
8:12:03.687: DVDRSYS.DLL: InitDevice((ID) 327680)
8:12:03.703: NIGPIBDD: SendGPIB: *CLS
8:12:03.703: NIGPIBDD: SendGPIB: *SRE 48
8:12:03.718: NIGPIBDD: SendGPIB: *ESE 1
8:12:03.718: NIGPIBDD: SaveSendGPIB function entered
8:12:03.718: NIGPIBDD: Assigning zero string to sCommand
8:12:03.734: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:03.734: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:03.750: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:12:03.750: NIGPIBDD: SendGPIB: *RST

8:12:03.765: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:03.765: NIGPIBDD: After mcGPIBCommunication.Leave()

8:12:03.765: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:03.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:03.781: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:03.781: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:03.796: NIGPIBDD: Just before returning the error code
8:12:03.906: NIGPIBDD: SaveSendGPIB function entered
8:12:03.906: NIGPIBDD: Assigning zero string to sCommand
8:12:03.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:03.921: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:03.921: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:12:03.937: NIGPIBDD: SendGPIB: *OPT?

8:12:03.937: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:03.953: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:03.953: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:03.953: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:12:03.953: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:12:03.968: NIGPIBDD: ReceiveGPIB: SMA-B20, SMA-B81, SMA-B106

8:12:03.968: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:12:03.984: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:12:03.984: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:03.984: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:12:04.000: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.015: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.015: NIGPIBDD: Just before returning the error code
8:12:04.015: NIGPIBDD: SaveSendGPIB function entered
8:12:04.015: NIGPIBDD: Assigning zero string to sCommand
8:12:04.031: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.046: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 99
8:12:04.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.062: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.062: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.078: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.078: NIGPIBDD: Just before returning the error code
8:12:04.093: NIGPIBDD: SaveSendGPIB function entered
8:12:04.093: NIGPIBDD: Assigning zero string to sCommand
8:12:04.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.093: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.109: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:12:04.109: NIGPIBDD: SendGPIB: :ROSC:SOUR INT;*OPC?

8:12:04.109: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.109: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.125: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:12:04.125: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:12:04.125: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.140: NIGPIBDD: ReceiveGPIB: 1

8:12:04.140: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:12:04.140: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:12:04.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.156: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:12:04.171: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.171: NIGPIBDD: Just before returning the error code
8:12:04.171: NIGPIBDD: SaveSendGPIB function entered
8:12:04.187: NIGPIBDD: Assigning zero string to sCommand
8:12:04.187: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.187: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:12:04.203: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.218: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.218: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.218: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.218: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.234: NIGPIBDD: Just before returning the error code
8:12:04.234: NIGPIBDD: SaveSendGPIB function entered
8:12:04.234: NIGPIBDD: Assigning zero string to sCommand
8:12:04.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.250: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.250: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:12:04.265: NIGPIBDD: SendGPIB: SOURCE:FREQ:MODE CW;*OPC?

8:12:04.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.281: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.281: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.281: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:12:04.281: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:12:04.281: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.296: NIGPIBDD: Just before returning the error code
8:12:04.296: NIGPIBDD: ReceiveGPIB: 1

8:12:04.312: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:12:04.312: NIGPIBDD: SaveSendGPIB function entered
8:12:04.312: NIGPIBDD: Assigning zero string to sCommand
8:12:04.312: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:12:04.328: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:12:04.328: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.328: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.343: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:12:04.343: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.343: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.359: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.359: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.359: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.375: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.375: NIGPIBDD: Just before returning the error code

8:12:04.375: NIGPIBDD: SaveSendGPIB function entered
8:12:04.375: NIGPIBDD: Assigning zero string to sCommand
8:12:04.390: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.390: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.406: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:12:04.406: NIGPIBDD: SendGPIB: OUTPUT OFF;*OPC?

8:12:04.406: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.406: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.421: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:12:04.421: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:12:04.421: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.421: NIGPIBDD: ReceiveGPIB: 1

8:12:04.437: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:12:04.437: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:12:04.453: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.453: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.453: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:12:04.453: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.468: NIGPIBDD: Just before returning the error code
8:12:04.468: NIGPIBDD: SaveSendGPIB function entered
8:12:04.468: NIGPIBDD: Assigning zero string to sCommand
8:12:04.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.484: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.484: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:12:04.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.500: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.500: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.515: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.515: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.515: NIGPIBDD: Just before returning the error code
8:12:04.531: NIGPIBDD: SaveSendGPIB function entered
8:12:04.531: NIGPIBDD: Assigning zero string to sCommand
8:12:04.531: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.546: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:12:04.546: NIGPIBDD: SendGPIB: SOURCE:AM:STATE OFF;*OPC?

8:12:04.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.562: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.578: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.578: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.578: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:12:04.578: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:12:04.578: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.593: NIGPIBDD: Just before returning the error code
8:12:04.593: NIGPIBDD: ReceiveGPIB: 1

8:12:04.593: NIGPIBDD: After CheckDeviceSpecificStatusRegister

8:12:04.593: NIGPIBDD: SaveSendGPIB function entered
8:12:04.609: NIGPIBDD: Assigning zero string to sCommand
8:12:04.609: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:12:04.625: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:12:04.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.640: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:12:04.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.640: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.640: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.671: NIGPIBDD: Just before returning the error code
8:12:04.671: NIGPIBDD: SaveSendGPIB function entered
8:12:04.671: NIGPIBDD: Assigning zero string to sCommand
8:12:04.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.687: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:12:04.687: NIGPIBDD: SendGPIB: :SYST:SEC ON

8:12:04.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.718: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:12:04.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:12:04.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:12:04.718: NIGPIBDD: After mcGPIBCommunication.Leave()
8:12:04.734: NIGPIBDD: Just before returning the error code
8:12:04.734: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3001) returned: 9000
8:12:04.734: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3002) returned: 6E+009
8:12:04.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:12:04.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:12:04.765: DVDRSYS.DLL: InitDevice((ID) 393216)
8:12:04.859: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3001) returned: 1
8:12:04.859: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3002) returned: 1E+009
8:12:04.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:12:04.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:12:04.906: DVDRSYS.DLL: InitDevice((ID) 458752)
8:12:05.218: NIGPIBDD: SendGPIB: CL;
8:12:05.437: NIGPIBDD: SendGPIB: CH1;DB;FA;MN;TM3;
8:12:05.671: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3001) returned: 1000
8:12:05.687: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3002) returned:
4.01E+010
8:12:05.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:12:05.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
4.06377E-044, (Data2) 0)
8:12:05.718: DVDRSYS.DLL: SetValue((ID) 458752, (Function) CMN_StartZero)

8:12:05.734: NIGPIBDD: SendGPIB: CH1
8:12:05.734: NIGPIBDD: SendGPIB: ZR
8:12:35.750: NIGPIBDD: SendGPIB: TR
8:12:42.468: NIGPIBDD: ReceiveGPIB: 1,0,1,0
8:12:42.468: NIGPIBDD: SendGPIB: TR
8:12:42.671: NIGPIBDD: ReceiveGPIB: 0,-65.60,1,0
8:12:42.671: DVDRSYS.DLL: GetValue((ID) 458752, (Function) CMN_ZeroReady, (Progress) 1.4013E-045)
8:12:42.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.2039E-044, (Data2) 0)
8:12:42.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
8:12:42.703: DVDRSYS.DLL: InitDevice((ID) 524289)
8:12:43.015: NIGPIBDD: SendGPIB: CL;
8:12:43.234: NIGPIBDD: SendGPIB: CH2;DB;FA;MN;TM3;
8:12:43.484: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3001) returned: 1000
8:12:43.500: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3002) returned: 4.01E+010
8:12:43.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
8:12:43.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.34403E-044, (Data2) 0)
8:12:43.531: DVDRSYS.DLL: SetValue((ID) 524289, (Function) CMN_StartZero)
8:12:43.546: NIGPIBDD: SendGPIB: CH2
8:12:43.546: NIGPIBDD: SendGPIB: ZR
8:13:13.562: NIGPIBDD: SendGPIB: TR
8:13:20.250: NIGPIBDD: ReceiveGPIB: 1,0,1,0
8:13:20.265: NIGPIBDD: SendGPIB: TR
8:13:20.453: NIGPIBDD: ReceiveGPIB: 1,0,0,-70.49
8:13:20.453: DVDRSYS.DLL: GetValue((ID) 524289, (Function) CMN_ZeroReady, (Progress) 1.4013E-045)
8:13:20.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.48416E-044, (Data2) 0)
8:13:20.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
8:13:20.500: DVDRSYS.DLL: InitDevice((ID) 589826)
8:13:21.000: NIGPIBDD: SendGPIB: 0U0J0S0Q
8:13:21.218: NIGPIBDD: SendGPIB: 0K1X50ID0R
8:13:21.812: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3001) returned: 1000
8:13:21.828: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3002) returned: 1.81E+010
8:13:21.828: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
8:13:21.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.62428E-044, (Data2) 0)
8:13:21.859: DVDRSYS.DLL: SetValue((ID) 589826, (Function) CMN_StartZero)
8:13:21.875: NIGPIBDD: SendGPIB: 1N
8:13:21.937: NIGPIBDD: SendGPIB: ZD
8:13:39.953: DVDRSYS.DLL: GetValue((ID) 589826, (Function) CMN_ZeroReady, (Progress) 1.4013E-045)
8:13:39.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.76441E-044, (Data2) 0)

8:13:39.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:13:39.968: DVDRSYS.DLL: InitDevice((ID) 655360)
8:13:40.093: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3001) returned: 100000
8:13:40.093: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3002) returned: 1E+009
8:13:40.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:13:40.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:13:40.156: DVDRSYS.DLL: InitDevice((ID) 720896)
8:13:40.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:13:40.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:13:40.187: DVDRSYS.DLL: InitDevice((ID) 786433)
8:13:40.203: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3001) returned: 100000
8:13:40.203: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3002) returned: 1.3E+009
8:13:40.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:13:40.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:13:40.234: DVDRSYS.DLL: InitDevice((ID) 851972)
8:13:40.250: NIGPIBDD: SendGPIO: R

8:13:40.265: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3001) returned: 10000
8:13:40.265: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3002) returned:
100000000
8:13:40.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:13:40.265: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:13:40.281: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:13:40.281: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:13:40.296: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:13:40.296: DVDRSYS.DLL: SetValue((ID) 196611, (Function) Unknown)
8:13:40.312: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_PowerOn)
8:13:40.812: NIGPIBDD: SendGPIO: R

8:13:45.015: NIGPIBDD: SendGPIO: P1

8:13:45.218: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:13:45.234: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:13:45.234: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:13:45.250: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:13:45.250: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_Operate)
8:13:45.250: NIGPIBDD: SendGPIO: R

8:13:49.421: NIGPIBDD: SendGPIO: MM

8:13:53.625: NIGPIBDD: SendGPIO: G4095

8:13:54.031: NIGPIBDD: SendGPIO: O

8:13:55.046: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:13:55.046: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:13:55.046: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:13:55.046: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:13:55.078: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:13:55.078: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:13:55.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.82169E-044, (Data2) 0)
8:13:55.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.96182E-044, (Data2) 0)
8:13:55.140: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:13:55.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 5.60519E-045, (Data2) 0)
8:13:55.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-045, (Data2) 0)
8:13:55.187: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:13:55.218: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.1 MHz)
8:13:55.218: NIGPIBDD: SaveSendGPIB function entered
8:13:55.218: NIGPIBDD: Assigning zero string to sCommand
8:13:55.218: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:55.234: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:55.234: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:13:55.234: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.1 MHZ;*OPC?

8:13:55.234: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:55.250: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:55.250: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:55.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:55.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:55.265: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:55.265: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:55.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:55.281: NIGPIBDD: Just before returning the error code
8:13:55.281: NIGPIBDD: ReceiveGPIB: 1

8:13:55.281: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:13:55.281: NIGPIBDD: SaveSendGPIB function entered
8:13:55.296: NIGPIBDD: Assigning zero string to sCommand
8:13:55.296: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:13:55.312: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:13:55.312: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:55.312: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:55.328: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:13:55.328: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:55.328: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:55.328: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:55.343: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:55.343: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:55.359: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:55.359: NIGPIBDD: Just before returning the error code

8:13:55.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -1.58819E-023)
8:13:55.359: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:13:55.390: NIGPIBDD: ReceiveGPIB: NO

8:13:55.421: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:13:55.453: NIGPIBDD: ReceiveGPIB: NO

8:13:55.468: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:13:55.515: NIGPIBDD: ReceiveGPIB: NO

8:13:55.531: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:13:55.578: NIGPIBDD: ReceiveGPIB: NO

8:13:55.609: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:13:55.656: NIGPIBDD: ReceiveGPIB: NO

8:13:55.671: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:13:55.703: NIGPIBDD: ReceiveGPIB: NO

8:13:55.734: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:13:55.765: NIGPIBDD: ReceiveGPIB: NO

8:13:55.781: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:13:55.828: NIGPIBDD: ReceiveGPIB: NO

8:13:55.843: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:13:55.890: NIGPIBDD: ReceiveGPIB: NC

8:13:55.906: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:13:55.937: NIGPIBDD: ReceiveGPIB: NC

8:13:55.968: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:13:56.000: NIGPIBDD: ReceiveGPIB: NC

8:13:56.015: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:13:56.062: NIGPIBDD: ReceiveGPIB: NC

8:13:56.078: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -50 dBm)

8:13:56.078: NIGPIBDD: SaveSendGPIB function entered
8:13:56.078: NIGPIBDD: Assigning zero string to sCommand
8:13:56.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:56.093: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:56.109: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:13:56.109: NIGPIBDD: SendGPIB: SOURCE:POWER -50 DBM;*OPC?

8:13:56.109: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:56.109: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:56.125: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:56.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:56.125: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:56.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:56.140: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:56.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:56.140: NIGPIBDD: ReceiveGPIB: 1

8:13:56.156: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:13:56.156: NIGPIBDD: Just before returning the error code
8:13:56.156: NIGPIBDD: SaveSendGPIB function entered
8:13:56.156: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:13:56.171: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:13:56.171: NIGPIBDD: Assigning zero string to sCommand
8:13:56.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:56.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:56.187: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:13:56.203: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:56.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:56.203: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:56.203: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:56.218: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:56.218: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:56.218: NIGPIBDD: Just before returning the error code
8:13:56.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
8:13:56.234: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierOff)
8:13:56.250: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierOn)
8:13:56.250: NIGPIBDD: SaveSendGPIB function entered
8:13:56.250: NIGPIBDD: Assigning zero string to sCommand
8:13:56.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:56.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:56.281: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:13:56.281: NIGPIBDD: SendGPIB: OUTPUT ON;*OPC?

8:13:56.281: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:56.281: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:56.296: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:56.296: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:56.296: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:56.296: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:56.312: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:56.312: NIGPIBDD: After mcGPIBCommunication.Leave()

8:13:56.312: NIGPIBDD: ReceiveGPIB: 1

 8:13:56.328: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:13:56.328: NIGPIBDD: Just before returning the error code
 8:13:56.328: NIGPIBDD: SaveSendGPIB function entered
 8:13:56.328: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:13:56.343: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:13:56.343: NIGPIBDD: Assigning zero string to sCommand
 8:13:56.343: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:56.359: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:56.359: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
 8:13:56.375: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:56.375: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:56.375: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:56.375: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:56.390: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:56.390: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:56.390: NIGPIBDD: Just before returning the error code
 8:13:56.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:13:56.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:56.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:56.421: NIGPIBDD: SendGPIB: TR
 8:13:56.437: NIGPIBDD: ReceiveGPIB: 0,-56.16,0,-62.21
 8:13:56.468: NIGPIBDD: SendGPIB: TR
 8:13:56.859: NIGPIBDD: ReceiveGPIB: 0,-34.72,0,-40.49
 8:13:56.890: NIGPIBDD: SendGPIB: TR
 8:13:56.890: NIGPIBDD: ReceiveGPIB: 0,-34.72,0,-40.50
 8:13:56.906: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -34.72 dBm)
 8:13:56.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
 8:13:56.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
 8:13:56.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:56.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:56.937: NIGPIBDD: SendGPIB: TR
 8:13:56.953: NIGPIBDD: ReceiveGPIB: 0,-34.72,0,-40.50
 8:13:56.968: NIGPIBDD: SendGPIB: TR
 8:13:57.000: NIGPIBDD: ReceiveGPIB: 0,-34.72,0,-40.49
 8:13:57.000: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -40.49 dBm)
 8:13:57.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
 8:13:57.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.14988E+032)
 8:13:57.140: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -45 dBm)

8:13:57.140: NIGPIBDD: SaveSendGPIB function entered
 8:13:57.156: NIGPIBDD: Assigning zero string to sCommand
 8:13:57.156: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:57.156: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:57.156: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
 8:13:57.171: NIGPIBDD: SendGPIB: SOURCE:POWER -45 DBM;*OPC?

 8:13:57.171: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:57.187: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:57.187: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:57.187: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:57.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:57.187: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
 8:13:57.203: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
 8:13:57.203: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:57.218: NIGPIBDD: Just before returning the error code
 8:13:57.218: NIGPIBDD: ReceiveGPIB: 1

 8:13:57.218: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:13:57.218: NIGPIBDD: SaveSendGPIB function entered
 8:13:57.234: NIGPIBDD: Assigning zero string to sCommand
 8:13:57.234: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:13:57.234: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:13:57.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:57.250: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:57.250: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
 8:13:57.250: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:57.265: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:57.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:57.281: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:57.281: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:57.281: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:57.281: NIGPIBDD: Just before returning the error code
 8:13:57.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
 8:13:57.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:13:57.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:57.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:57.312: NIGPIBDD: SendGPIB: TR
 8:13:57.328: NIGPIBDD: ReceiveGPIB: 0,-29.99,0,-35.72
 8:13:57.359: NIGPIBDD: SendGPIB: TR
 8:13:57.390: NIGPIBDD: ReceiveGPIB: 0,-29.99,0,-35.54
 8:13:57.406: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -29.99 dBm)
 8:13:57.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
 8:13:57.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:13:57.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:57.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:57.437: NIGPIBDD: SendGPIB: TR
8:13:57.453: NIGPIBDD: ReceiveGPIB: 0,-29.99,0,-35.54
8:13:57.468: NIGPIBDD: SendGPIB: TR
8:13:57.500: NIGPIBDD: ReceiveGPIB: 0,-29.99,0,-35.54
8:13:57.500: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.1 MHz, (Power) -35.54 dBm)
8:13:57.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) -2)
8:13:57.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) -7.8678E-017)
8:13:57.531: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -40 dBm)
8:13:57.531: NIGPIBDD: SaveSendGPIB function entered
8:13:57.531: NIGPIBDD: Assigning zero string to sCommand
8:13:57.531: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:57.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:57.546: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:13:57.546: NIGPIBDD: SendGPIB: SOURCE:POWER -40 DBM;*OPC?

8:13:57.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:57.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:57.562: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:57.578: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:57.578: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:57.578: NIGPIBDD: ReceiveGPIB: 1

8:13:57.578: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:13:57.593: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:13:57.593: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:57.593: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:13:57.609: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:57.609: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:57.609: NIGPIBDD: Just before returning the error code
8:13:57.625: NIGPIBDD: SaveSendGPIB function entered
8:13:57.625: NIGPIBDD: Assigning zero string to sCommand
8:13:57.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:57.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:57.640: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:13:57.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:57.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:57.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:57.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:57.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:57.671: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:57.671: NIGPIBDD: Just before returning the error code
8:13:57.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
1.12104E-044, (Data2) 0)

8:13:57.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:13:57.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:57.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:57.703: NIGPIBDD: SendGPIB: TR
8:13:57.703: NIGPIBDD: ReceiveGPIB: 0,-24.79,0,-31.19
8:13:57.750: NIGPIBDD: SendGPIB: TR
8:13:58.000: NIGPIBDD: ReceiveGPIB: 0,-24.76,0,-30.59
8:13:58.000: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -24.76 dBm)
8:13:58.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)
8:13:58.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:13:58.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:58.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:58.046: NIGPIBDD: SendGPIB: TR
8:13:58.062: NIGPIBDD: ReceiveGPIB: 0,-24.76,0,-30.54
8:13:58.093: NIGPIBDD: SendGPIB: TR
8:13:58.109: NIGPIBDD: ReceiveGPIB: 0,-24.76,0,-30.54
8:13:58.109: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -30.54 dBm)
8:13:58.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:13:58.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1451.35)
8:13:58.125: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -35 dBm)
8:13:58.140: NIGPIBDD: SaveSendGPIB function entered
8:13:58.140: NIGPIBDD: Assigning zero string to sCommand
8:13:58.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:58.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:58.156: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:13:58.156: NIGPIBDD: SendGPIB: SOURCE:POWER -35 DBM;*OPC?

8:13:58.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:58.171: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:58.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:58.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:58.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:58.187: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:58.187: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:58.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:58.203: NIGPIBDD: Just before returning the error code
8:13:58.203: NIGPIBDD: ReceiveGPIB: 1

8:13:58.203: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:13:58.203: NIGPIBDD: SaveSendGPIB function entered

8:13:58.218: NIGPIBDD: Assigning zero string to sCommand
8:13:58.218: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:13:58.234: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:13:58.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:58.234: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:58.250: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:13:58.250: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:58.250: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:58.250: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:58.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:58.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:58.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:58.281: NIGPIBDD: Just before returning the error code
8:13:58.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
8:13:58.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:13:58.296: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:58.296: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:58.312: NIGPIBDD: SendGPIB: TR
8:13:58.312: NIGPIBDD: ReceiveGPIB: 0,-20.75,0,-26.48
8:13:58.343: NIGPIBDD: SendGPIB: TR
8:13:58.359: NIGPIBDD: ReceiveGPIB: 0,-20.75,0,-25.55
8:13:58.359: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -20.75 dBm)
8:13:58.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:13:58.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:13:58.375: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:58.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:58.390: NIGPIBDD: SendGPIB: TR
8:13:58.406: NIGPIBDD: ReceiveGPIB: 0,-20.75,0,-25.56
8:13:58.437: NIGPIBDD: SendGPIB: TR
8:13:58.453: NIGPIBDD: ReceiveGPIB: 0,-20.75,0,-25.56
8:13:58.453: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -25.56 dBm)
8:13:58.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:13:58.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 2.83901E+035)
8:13:58.484: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -30 dBm)
8:13:58.484: NIGPIBDD: SaveSendGPIB function entered
8:13:58.484: NIGPIBDD: Assigning zero string to sCommand
8:13:58.500: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:58.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:58.500: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:13:58.515: NIGPIBDD: SendGPIB: SOURCE:POWER -30 DBM;*OPC?
 8:13:58.515: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:58.515: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:58.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:58.531: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:58.531: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:58.531: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
 8:13:58.546: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
 8:13:58.546: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:58.546: NIGPIBDD: Just before returning the error code
 8:13:58.546: NIGPIBDD: ReceiveGPIB: 1

 8:13:58.562: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:13:58.562: NIGPIBDD: SaveSendGPIB function entered
 8:13:58.562: NIGPIBDD: Assigning zero string to sCommand
 8:13:58.562: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:13:58.578: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:13:58.578: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:58.593: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:58.593: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
 8:13:58.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:58.609: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:58.609: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:58.609: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:13:58.609: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:13:58.625: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:13:58.625: NIGPIBDD: Just before returning the error code
 8:13:58.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
 8:13:58.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:13:58.656: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:58.656: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:58.671: NIGPIBDD: SendGPIB: TR
 8:13:58.671: NIGPIBDD: ReceiveGPIB: 0,-15.80,0,-21.54
 8:13:58.703: NIGPIBDD: SendGPIB: TR
 8:13:58.718: NIGPIBDD: ReceiveGPIB: 0,-14.77,0,-20.58
 8:13:58.750: NIGPIBDD: SendGPIB: TR
 8:13:59.000: NIGPIBDD: ReceiveGPIB: 0,-14.78,0,-20.62
 8:13:59.000: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -14.78 dBm)
 8:13:59.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
 8:13:59.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
 8:13:59.015: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:13:59.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)

8:13:59.031: NIGPIBDD: SendGPIB: TR
8:13:59.046: NIGPIBDD: ReceiveGPIB: 0,-14.78,0,-20.57
8:13:59.078: NIGPIBDD: SendGPIB: TR
8:13:59.093: NIGPIBDD: ReceiveGPIB: 0,-14.78,0,-20.57
8:13:59.093: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -20.57 dBm)
8:13:59.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:13:59.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.10899E+033)
8:13:59.125: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -25 dBm)
8:13:59.125: NIGPIBDD: SaveSendGPIB function entered
8:13:59.140: NIGPIBDD: Assigning zero string to sCommand
8:13:59.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.140: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.140: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:13:59.156: NIGPIBDD: SendGPIB: SOURCE:POWER -25 DBM;*OPC?

8:13:59.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.156: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.156: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.171: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:59.171: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:59.187: NIGPIBDD: ReceiveGPIB: 1

8:13:59.187: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:13:59.187: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:13:59.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.187: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:13:59.203: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.218: NIGPIBDD: Just before returning the error code
8:13:59.218: NIGPIBDD: SaveSendGPIB function entered
8:13:59.218: NIGPIBDD: Assigning zero string to sCommand
8:13:59.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.234: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.250: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:13:59.250: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.281: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.281: NIGPIBDD: Just before returning the error code
8:13:59.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
8:13:59.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:13:59.328: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)

8:13:59.328: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.343: NIGPIBDD: SendGPIB: TR
8:13:59.343: NIGPIBDD: ReceiveGPIB: 0,-10.11,0,-15.57
8:13:59.390: NIGPIBDD: SendGPIB: TR
8:13:59.390: NIGPIBDD: ReceiveGPIB: 0,-10.11,0,-15.57
8:13:59.406: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -10.11 dBm)
8:13:59.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:13:59.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:13:59.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.437: NIGPIBDD: SendGPIB: TR
8:13:59.453: NIGPIBDD: ReceiveGPIB: 0,-10.11,0,-15.57
8:13:59.484: NIGPIBDD: SendGPIB: TR
8:13:59.500: NIGPIBDD: ReceiveGPIB: 0,-10.11,0,-15.57
8:13:59.500: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -15.57 dBm)
8:13:59.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:13:59.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 0.213584)
8:13:59.546: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -20 dBm)
8:13:59.546: NIGPIBDD: SaveSendGPIB function entered
8:13:59.562: NIGPIBDD: Assigning zero string to sCommand
8:13:59.562: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.562: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.562: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:13:59.578: NIGPIBDD: SendGPIB: SOURCE:POWER -20 DBM;*OPC?

8:13:59.578: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.593: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.593: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.593: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:13:59.609: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:13:59.625: NIGPIBDD: ReceiveGPIB: 1

8:13:59.625: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:13:59.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:13:59.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.640: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:13:59.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.656: NIGPIBDD: Just before returning the error code
8:13:59.656: NIGPIBDD: SaveSendGPIB function entered
8:13:59.656: NIGPIBDD: Assigning zero string to sCommand
8:13:59.671: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:13:59.671: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.671: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:13:59.671: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.687: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.703: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:13:59.703: NIGPIBDD: Just before returning the error code
8:13:59.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
8:13:59.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:13:59.734: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.734: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.734: NIGPIBDD: SendGPIB: TR
8:13:59.750: NIGPIBDD: ReceiveGPIB: 0,-4.96,0,-10.87
8:13:59.781: NIGPIBDD: SendGPIB: TR
8:13:59.796: NIGPIBDD: ReceiveGPIB: 0,-4.72,0,-10.62
8:13:59.812: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -4.72 dBm)
8:13:59.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:13:59.828: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:13:59.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:13:59.843: NIGPIBDD: SendGPIB: TR
8:13:59.859: NIGPIBDD: ReceiveGPIB: 0,-4.72,0,-10.62
8:13:59.890: NIGPIBDD: SendGPIB: TR
8:13:59.906: NIGPIBDD: ReceiveGPIB: 0,-4.72,0,-10.62
8:13:59.906: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -10.62 dBm)
8:13:59.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)
8:13:59.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 8.33036E-039)
8:13:59.937: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15 dBm)
8:13:59.937: NIGPIBDD: SaveSendGPIB function entered
8:13:59.937: NIGPIBDD: Assigning zero string to sCommand
8:13:59.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:13:59.953: NIGPIBDD: After mcGPIBCommunication.Enter()
8:13:59.953: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:13:59.953: NIGPIBDD: SendGPIB: SOURCE:POWER -15 DBM;*OPC?

8:13:59.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:13:59.968: NIGPIBDD: After mcGPIBCommunication.Leave()

8:13:59.968: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:13:59.968: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
 8:13:59.984: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
 8:13:59.984: NIGPIBDD: ReceiveGPIB: 1

 8:13:59.984: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:14:00.000: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:14:00.000: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:00.000: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:14:00.015: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:00.015: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:00.015: NIGPIBDD: Just before returning the error code
 8:14:00.031: NIGPIBDD: SaveSendGPIB function entered
 8:14:00.031: NIGPIBDD: Assigning zero string to sCommand
 8:14:00.031: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:00.031: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:00.046: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
 8:14:00.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:00.046: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:00.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:00.062: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:00.062: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:00.078: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:00.078: NIGPIBDD: Just before returning the error code
 8:14:00.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
 8:14:00.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:14:00.109: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:14:00.109: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:14:00.109: NIGPIBDD: SendGPIB: TR
 8:14:00.125: NIGPIBDD: ReceiveGPIB: 0,-0.75,0,-9.87
 8:14:00.156: NIGPIBDD: SendGPIB: TR
 8:14:00.390: NIGPIBDD: ReceiveGPIB: 0,+0.31,0,-5.66
 8:14:00.421: NIGPIBDD: SendGPIB: TR
 8:14:00.437: NIGPIBDD: ReceiveGPIB: 0,+0.32,0,-5.65
 8:14:00.453: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 0.32 dBm)
 8:14:00.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)
 8:14:00.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
 8:14:00.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:14:00.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
 8:14:00.484: NIGPIBDD: SendGPIB: TR
 8:14:00.500: NIGPIBDD: ReceiveGPIB: 0,+0.32,0,-5.65
 8:14:00.515: NIGPIBDD: SendGPIB: TR
 8:14:00.546: NIGPIBDD: ReceiveGPIB: 0,+0.32,0,-5.65

8:14:00.546: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -5.65 dBm)
8:14:00.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)
8:14:00.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 8.70937E+016)
8:14:00.578: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -10 dBm)
8:14:00.578: NIGPIBDD: SaveSendGPIB function entered
8:14:00.578: NIGPIBDD: Assigning zero string to sCommand
8:14:00.578: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:00.593: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:00.593: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:00.593: NIGPIBDD: SendGPIB: SOURCE:POWER -10 DBM;*OPC?

8:14:00.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:00.609: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:00.609: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:00.609: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:00.625: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:00.625: NIGPIBDD: ReceiveGPIB: 1

8:14:00.625: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:00.640: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:00.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:00.640: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:00.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:00.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:00.656: NIGPIBDD: Just before returning the error code
8:14:00.671: NIGPIBDD: SaveSendGPIB function entered
8:14:00.671: NIGPIBDD: Assigning zero string to sCommand
8:14:00.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:00.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:00.703: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:00.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:00.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:00.703: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:00.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:00.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:00.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:00.734: NIGPIBDD: Just before returning the error code
8:14:00.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
8:14:00.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:00.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:00.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:00.796: NIGPIBDD: SendGPIB: TR
8:14:00.796: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,-0.77
8:14:00.843: NIGPIBDD: SendGPIB: TR

8:14:00.843: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,-0.77
8:14:00.859: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 5.29 dBm)
8:14:00.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
8:14:00.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:00.875: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:00.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:00.890: NIGPIBDD: SendGPIB: TR
8:14:00.906: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,-0.77
8:14:00.937: NIGPIBDD: SendGPIB: TR
8:14:00.953: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,-0.77
8:14:00.953: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) -0.77 dBm)
8:14:00.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:00.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -6.01184E+013)
8:14:01.000: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -5.476 dBm)
8:14:01.000: NIGPIBDD: SaveSendGPIB function entered
8:14:01.015: NIGPIBDD: Assigning zero string to sCommand
8:14:01.015: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.015: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.015: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:01.031: NIGPIBDD: SendGPIB: SOURCE:POWER -5.476 DBM;*OPC?

8:14:01.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.046: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.062: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.062: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.062: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:01.078: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:01.078: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.078: NIGPIBDD: Just before returning the error code
8:14:01.093: NIGPIBDD: ReceiveGPIB: 1

8:14:01.093: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:01.093: NIGPIBDD: SaveSendGPIB function entered
8:14:01.109: NIGPIBDD: Assigning zero string to sCommand
8:14:01.109: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:01.109: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:01.109: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.125: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:01.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.140: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:01.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.156: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.156: NIGPIBDD: Just before returning the error code
8:14:01.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -1.08468E-033)
8:14:01.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:01.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.187: NIGPIBDD: SendGPIB: TR
8:14:01.203: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,+3.14
8:14:01.234: NIGPIBDD: SendGPIB: TR
8:14:01.250: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,+3.48
8:14:01.250: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 5.29 dBm)
8:14:01.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
8:14:01.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:01.265: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.281: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.281: NIGPIBDD: SendGPIB: TR
8:14:01.296: NIGPIBDD: ReceiveGPIB: 0,+5.29,0,+3.48
8:14:01.328: NIGPIBDD: SendGPIB: TR
8:14:01.343: NIGPIBDD: ReceiveGPIB: 0,+9.61,0,+3.48
8:14:01.343: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 3.48 dBm)
8:14:01.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:01.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -6.01184E+013)
8:14:01.375: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -0.952 dBm)
8:14:01.375: NIGPIBDD: SaveSendGPIB function entered
8:14:01.375: NIGPIBDD: Assigning zero string to sCommand
8:14:01.375: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.390: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.390: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:01.406: NIGPIBDD: SendGPIB: SOURCE:POWER -0.952 DBM;*OPC?

8:14:01.406: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.406: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.406: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.421: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:01.421: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:01.437: NIGPIBDD: ReceiveGPIB: 1

8:14:01.437: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:01.437: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:01.437: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.437: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:01.453: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.453: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.453: NIGPIBDD: Just before returning the error code
8:14:01.468: NIGPIBDD: SaveSendGPIB function entered
8:14:01.468: NIGPIBDD: Assigning zero string to sCommand
8:14:01.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.484: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.484: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:01.484: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.500: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.500: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:01.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:01.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:01.515: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:01.515: NIGPIBDD: Just before returning the error code
8:14:01.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -3.76685E-032)
8:14:01.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:01.546: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.546: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.562: NIGPIBDD: SendGPIB: TR
8:14:01.562: NIGPIBDD: ReceiveGPIB: 0,+11.92,0,+5.66
8:14:01.593: NIGPIBDD: SendGPIB: TR
8:14:01.609: NIGPIBDD: ReceiveGPIB: 0,+12.43,0,+6.15
8:14:01.640: NIGPIBDD: SendGPIB: TR
8:14:01.890: NIGPIBDD: ReceiveGPIB: 0,+12.46,0,+6.03
8:14:01.906: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 12.46 dBm)
8:14:01.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:01.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:01.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:01.921: NIGPIBDD: SendGPIB: TR
8:14:01.937: NIGPIBDD: ReceiveGPIB: 0,+12.46,0,+6.04
8:14:01.968: NIGPIBDD: SendGPIB: TR
8:14:01.984: NIGPIBDD: ReceiveGPIB: 0,+12.46,0,+6.04
8:14:01.984: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 6.04 dBm)
8:14:02.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)

8:14:02.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.15784E-020)
8:14:02.015: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -3.598 dBm)
8:14:02.015: NIGPIBDD: SaveSendGPIB function entered
8:14:02.031: NIGPIBDD: Assigning zero string to sCommand
8:14:02.031: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.031: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:02.046: NIGPIBDD: SendGPIB: SOURCE:POWER -3.598 DBM;*OPC?

8:14:02.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.062: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:02.062: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:02.078: NIGPIBDD: ReceiveGPIB: 1

8:14:02.078: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:02.093: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:02.093: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.093: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:02.093: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.109: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.109: NIGPIBDD: Just before returning the error code
8:14:02.109: NIGPIBDD: SaveSendGPIB function entered
8:14:02.109: NIGPIBDD: Assigning zero string to sCommand
8:14:02.125: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.140: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:02.140: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.187: NIGPIBDD: Just before returning the error code
8:14:02.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.72616E-007)
8:14:02.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:02.218: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.218: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.234: NIGPIBDD: SendGPIB: TR
8:14:02.234: NIGPIBDD: ReceiveGPIB: 0,+11.22,0,+4.88
8:14:02.281: NIGPIBDD: SendGPIB: TR
8:14:02.281: NIGPIBDD: ReceiveGPIB: 0,+11.22,0,+4.87
8:14:02.296: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 11.22 dBm)

8:14:02.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:02.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:02.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.328: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.328: NIGPIBDD: SendGPIB: TR
8:14:02.343: NIGPIBDD: ReceiveGPIB: 0,+11.21,0,+4.87
8:14:02.375: NIGPIBDD: SendGPIB: TR
8:14:02.390: NIGPIBDD: ReceiveGPIB: 0,+11.21,0,+4.86
8:14:02.390: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 4.86 dBm)
8:14:02.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:14:02.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.10899E+033)
8:14:02.421: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -5.004 dBm)
8:14:02.421: NIGPIBDD: SaveSendGPIB function entered
8:14:02.421: NIGPIBDD: Assigning zero string to sCommand
8:14:02.421: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.437: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.437: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:02.453: NIGPIBDD: SendGPIB: SOURCE:POWER -5.004 DBM;*OPC?

8:14:02.453: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.453: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.453: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.468: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.468: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.468: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:02.468: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:02.484: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.484: NIGPIBDD: Just before returning the error code
8:14:02.484: NIGPIBDD: ReceiveGPIB: 1

8:14:02.500: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:02.500: NIGPIBDD: SaveSendGPIB function entered
8:14:02.500: NIGPIBDD: Assigning zero string to sCommand
8:14:02.500: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:02.515: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:02.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.515: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.531: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:02.531: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.546: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.546: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.562: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:02.562: NIGPIBDD: Just before returning the error code
8:14:02.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -5.66215E-018)
8:14:02.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:02.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.593: NIGPIBDD: SendGPIB: TR
8:14:02.593: NIGPIBDD: ReceiveGPIB: 0,+10.33,0,+4.85
8:14:02.640: NIGPIBDD: SendGPIB: TR
8:14:02.796: NIGPIBDD: ReceiveGPIB: 0,+10.08,0,+4.04
8:14:02.796: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 10.08 dBm)
8:14:02.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
8:14:02.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:02.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:02.828: NIGPIBDD: SendGPIB: TR
8:14:02.843: NIGPIBDD: ReceiveGPIB: 0,+10.08,0,+3.89
8:14:02.875: NIGPIBDD: SendGPIB: TR
8:14:02.890: NIGPIBDD: ReceiveGPIB: 0,+10.08,0,+3.89
8:14:02.890: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 3.89 dBm)
8:14:02.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:14:02.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.27306E-008)
8:14:02.921: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -5.27 dBm)
8:14:02.921: NIGPIBDD: SaveSendGPIB function entered
8:14:02.937: NIGPIBDD: Assigning zero string to sCommand
8:14:02.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.937: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:02.937: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:02.953: NIGPIBDD: SendGPIB: SOURCE:POWER -5.27 DBM;*OPC?

8:14:02.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:02.953: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:02.953: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:02.968: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:02.968: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:02.984: NIGPIBDD: ReceiveGPIB: 1

8:14:02.984: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:02.984: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:02.984: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:02.984: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:03.000: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:03.015: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:03.015: NIGPIBDD: Just before returning the error code
8:14:03.015: NIGPIBDD: SaveSendGPIB function entered
8:14:03.015: NIGPIBDD: Assigning zero string to sCommand
8:14:03.031: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:03.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:03.031: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:03.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:03.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:03.046: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:03.062: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:03.062: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:03.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:03.062: NIGPIBDD: Just before returning the error code
8:14:03.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -3.21866E+026)
8:14:03.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:03.093: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:03.093: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:03.093: NIGPIBDD: SendGPIB: TR
8:14:03.109: NIGPIBDD: ReceiveGPIB: 0,+9.83,0,+3.64
8:14:03.140: NIGPIBDD: SendGPIB: TR
8:14:03.156: NIGPIBDD: ReceiveGPIB: 0,+9.82,0,+3.64
8:14:03.156: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 9.82 dBm)
8:14:03.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:03.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:03.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:03.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:03.203: NIGPIBDD: SendGPIB: TR
8:14:03.218: NIGPIBDD: ReceiveGPIB: 0,+9.82,0,+3.64
8:14:03.234: NIGPIBDD: SendGPIB: TR
8:14:03.312: NIGPIBDD: ReceiveGPIB: 0,+9.82,0,+3.64
8:14:03.312: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 3.64 dBm)
8:14:03.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:14:03.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.53903E+016)
8:14:03.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:03.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:14:03.406: NIGPIBDD: SendGPIB: 1N
8:14:03.515: NIGPIBDD: ReceiveGPIB: DBA-5446E-2,0,0

8:14:03.531: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.1 MHz, (Power) -54.46 dBm)
8:14:03.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 2)
8:14:03.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 1.30294E-019)
8:14:03.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:05.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:05.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:05.593: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:05.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:05.609: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:05.640: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:05.656: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:05.656: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:05.656: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:05.656: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:05.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:05.671: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:05.703: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:05.703: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:05.703: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:05.703: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:05.718: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:05.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:05.734: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:05.750: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:05.765: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:05.765: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:05.781: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:05.781: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:05.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:05.796: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:05.812: NIGPIBDD: ReceiveGPIB: 53.790E+0

8:14:05.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.79)
8:14:05.828: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:05.828: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:05.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:05.843: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:05.875: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:05.875: NIGPIBDD: SendGPIB: TR
8:14:05.890: NIGPIBDD: ReceiveGPIB: 0,+9.79,0,+3.61
8:14:05.921: NIGPIBDD: SendGPIB: TR
8:14:05.937: NIGPIBDD: ReceiveGPIB: 0,+9.79,0,+3.61
8:14:05.937: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 9.79 dBm)
8:14:05.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:05.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:05.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:05.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:05.968: NIGPIBDD: SendGPIB: TR
8:14:06.000: NIGPIBDD: ReceiveGPIB: 0,+9.79,0,+3.61
8:14:06.031: NIGPIBDD: SendGPIB: TR
8:14:06.031: NIGPIBDD: ReceiveGPIB: 0,+9.79,0,+3.60
8:14:06.046: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 3.6 dBm)
8:14:06.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:06.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.53903E+016)
8:14:06.062: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -5.95234 dBm)
8:14:06.078: NIGPIBDD: SaveSendGPIB function entered
8:14:06.078: NIGPIBDD: Assigning zero string to sCommand
8:14:06.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.093: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.093: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:06.093: NIGPIBDD: SendGPIB: SOURCE:POWER -5.95234 DBM;*OPC?

8:14:06.109: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.109: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:06.109: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.125: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:06.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.140: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:06.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.140: NIGPIBDD: ReceiveGPIB: 1

8:14:06.140: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:06.140: NIGPIBDD: Just before returning the error code
8:14:06.156: NIGPIBDD: SaveSendGPIB function entered
8:14:06.156: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:06.156: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:06.171: NIGPIBDD: Assigning zero string to sCommand
8:14:06.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.187: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:06.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.203: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.203: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.203: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.218: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.218: NIGPIBDD: Just before returning the error code
8:14:06.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.32419E+009)
8:14:06.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:06.234: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:06.250: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:06.250: NIGPIBDD: SendGPIB: TR
8:14:06.265: NIGPIBDD: ReceiveGPIB: 0,+9.16,0,+3.13
8:14:06.281: NIGPIBDD: SendGPIB: TR
8:14:06.296: NIGPIBDD: ReceiveGPIB: 0,+9.16,0,+2.97
8:14:06.296: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 9.16 dBm)
8:14:06.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:06.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:06.359: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:06.359: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.1 MHz, (Attenuation) 40 dB)
8:14:06.406: NIGPIBDD: SendGPIB: TR
8:14:06.406: NIGPIBDD: ReceiveGPIB: 0,+9.15,0,+2.97
8:14:06.437: NIGPIBDD: SendGPIB: TR
8:14:06.453: NIGPIBDD: ReceiveGPIB: 0,+9.15,0,+2.97
8:14:06.453: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.1 MHz, (Power) 2.97 dBm)

8:14:06.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:14:06.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.53903E+016)
8:14:06.500: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.13 MHz)
8:14:06.500: NIGPIBDD: SaveSendGPIB function entered
8:14:06.500: NIGPIBDD: Assigning zero string to sCommand
8:14:06.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.515: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.531: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:06.531: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.13 MHZ;*OPC?

8:14:06.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.546: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.546: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.562: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.562: NIGPIBDD: Just before returning the error code
8:14:06.562: NIGPIBDD: SaveSendGPIB function entered
8:14:06.578: NIGPIBDD: Assigning zero string to sCommand
8:14:06.578: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.578: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:06.593: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:06.593: NIGPIBDD: ReceiveGPIB: 1

8:14:06.593: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:06.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:06.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.625: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:06.640: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:06.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.640: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:06.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:06.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:06.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:06.671: NIGPIBDD: Just before returning the error code
8:14:06.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 9.1212E-033)
8:14:06.687: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:06.718: NIGPIBDD: ReceiveGPIB: NO

8:14:06.734: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:06.781: NIGPIBDD: ReceiveGPIB: NO

8:14:06.796: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:06.843: NIGPIBDD: ReceiveGPIB: NO

8:14:06.875: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?
8:14:06.921: NIGPIBDD: ReceiveGPIB: NO
8:14:06.937: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:06.984: NIGPIBDD: ReceiveGPIB: NO
8:14:07.000: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:07.031: NIGPIBDD: ReceiveGPIB: NO
8:14:07.062: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:07.093: NIGPIBDD: ReceiveGPIB: NO
8:14:07.109: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:07.156: NIGPIBDD: ReceiveGPIB: NO
8:14:07.171: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:07.218: NIGPIBDD: ReceiveGPIB: NC
8:14:07.234: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:07.265: NIGPIBDD: ReceiveGPIB: NC
8:14:07.281: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:07.328: NIGPIBDD: ReceiveGPIB: NC
8:14:07.343: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:07.390: NIGPIBDD: ReceiveGPIB: NC
8:14:07.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:07.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.421: NIGPIBDD: SendGPIB: TR
8:14:07.437: NIGPIBDD: ReceiveGPIB: 0,+8.77,0,+2.55
8:14:07.468: NIGPIBDD: SendGPIB: TR
8:14:07.484: NIGPIBDD: ReceiveGPIB: 0,+8.77,0,+2.55
8:14:07.484: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.13 MHz, (Power) 8.77 dBm)
8:14:07.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)

8:14:07.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:07.500: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.500: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.515: NIGPIBDD: SendGPIO: TR
8:14:07.531: NIGPIBDD: ReceiveGPIO: 0,+8.77,0,+2.56
8:14:07.562: NIGPIBDD: SendGPIO: TR
8:14:07.578: NIGPIBDD: ReceiveGPIO: 0,+8.77,0,+2.56
8:14:07.593: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.13 MHz, (Power) 2.56 dBm)
8:14:07.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:07.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 4.27792E+019)
8:14:07.609: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -5.61468 dBm)
8:14:07.625: NIGPIBDD: SaveSendGPIO function entered
8:14:07.625: NIGPIBDD: Assigning zero string to sCommand
8:14:07.625: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:07.625: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:07.640: NIGPIBDD::SaveSendGPIO: mISuggestedReadSize: 0
8:14:07.640: NIGPIBDD: SendGPIO: SOURCE:POWER -5.61468 DBM;*OPC?

8:14:07.656: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:07.656: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:07.656: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Enter()
8:14:07.656: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Enter()
8:14:07.656: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:07.671: NIGPIBDD: ReceiveGPIO: 1

8:14:07.687: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:07.687: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Leave()
8:14:07.687: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:07.687: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:07.687: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Leave()
8:14:07.703: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:07.703: NIGPIBDD: Just before returning the error code
8:14:07.703: NIGPIBDD: SaveSendGPIO function entered
8:14:07.718: NIGPIBDD: Assigning zero string to sCommand
8:14:07.718: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:07.734: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:07.734: NIGPIBDD::SaveSendGPIO: mISuggestedReadSize: 10
8:14:07.734: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:07.734: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:07.750: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:07.750: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:07.750: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:07.750: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:07.765: NIGPIBDD: Just before returning the error code

8:14:07.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -1.8083E+030)
8:14:07.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:07.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.796: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.796: NIGPIBDD: SendGPIO: TR
8:14:07.812: NIGPIBDD: ReceiveGPIO: 0,+9.08,0,+2.87
8:14:07.843: NIGPIBDD: SendGPIO: TR
8:14:07.859: NIGPIBDD: ReceiveGPIO: 0,+9.08,0,+2.87
8:14:07.859: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.13 MHz, (Power) 9.08 dBm)
8:14:07.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
8:14:07.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:07.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:07.890: NIGPIBDD: SendGPIO: TR
8:14:07.906: NIGPIBDD: ReceiveGPIO: 0,+9.08,0,+2.87
8:14:07.937: NIGPIBDD: SendGPIO: TR
8:14:07.953: NIGPIBDD: ReceiveGPIO: 0,+9.08,0,+2.87
8:14:07.953: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.13 MHz, (Power) 2.87 dBm)
8:14:07.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:07.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 2.80358E+024)
8:14:07.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:07.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:08.000: NIGPIBDD: SendGPIO: 1N
8:14:08.140: NIGPIBDD: ReceiveGPIO: DBA-5464E-2,0,0

8:14:08.140: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.13 MHz, (Power) -54.64 dBm)
8:14:08.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:08.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.89433E-008)
8:14:08.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:10.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:10.156: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:10.156: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:10.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:10.171: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:10.203: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:10.203: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 0, (Data2) 3.7)
8:14:10.203: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 0, (Data2) 100)
8:14:10.203: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:10.218: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:10.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:10.234: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:10.250: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:10.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 1.4013E-045, (Data2) 0.58)
8:14:10.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 1.4013E-045, (Data2) 100)
8:14:10.281: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:10.281: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:10.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:10.281: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:10.312: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:10.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 2.8026E-045, (Data2) 0.2)
8:14:10.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 2.8026E-045, (Data2) 100)
8:14:10.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:10.328: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:10.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:10.343: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:10.359: NIGPIBDD: ReceiveGPIB: 53.673E+0

8:14:10.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 4.2039E-045, (Data2) 53.673)
8:14:10.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 4.2039E-045, (Data2) 100)
8:14:10.390: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:10.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.22299E-044, (Data2) 0)
8:14:10.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)

8:14:10.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.437: NIGPIBDD: SendGPIB: TR
8:14:10.453: NIGPIBDD: ReceiveGPIB: 0,+9.07,0,+2.86
8:14:10.484: NIGPIBDD: SendGPIB: TR
8:14:10.484: NIGPIBDD: ReceiveGPIB: 0,+9.07,0,+2.86
8:14:10.500: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.13 MHz, (Power) 9.07 dBm)
8:14:10.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) 0)
8:14:10.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)
8:14:10.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.531: NIGPIBDD: SendGPIB: TR
8:14:10.546: NIGPIBDD: ReceiveGPIB: 0,+9.07,0,+2.86
8:14:10.562: NIGPIBDD: SendGPIB: TR
8:14:10.578: NIGPIBDD: ReceiveGPIB: 0,+9.07,0,+2.86
8:14:10.578: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.13 MHz, (Power) 2.86 dBm)
8:14:10.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) -1.0842E-019)
8:14:10.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) 2.80358E+024)
8:14:10.609: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -7.2537 dBm)
8:14:10.609: NIGPIBDD: SaveSendGPIB function entered
8:14:10.625: NIGPIBDD: Assigning zero string to sCommand
8:14:10.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:10.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:10.640: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:10.640: NIGPIBDD: SendGPIB: SOURCE:POWER -7.2537 DBM;*OPC?

8:14:10.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:10.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:10.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:10.656: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:10.656: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:10.671: NIGPIBDD: ReceiveGPIB: 1

8:14:10.671: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:10.687: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:10.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:10.687: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:10.687: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:10.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:10.703: NIGPIBDD: Just before returning the error code
8:14:10.703: NIGPIBDD: SaveSendGPIB function entered
8:14:10.703: NIGPIBDD: Assigning zero string to sCommand
8:14:10.718: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:10.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:10.734: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:10.734: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:10.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:10.734: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:10.750: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:10.750: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:10.750: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:10.765: NIGPIBDD: Just before returning the error code
8:14:10.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -211.379)
8:14:10.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:10.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.796: NIGPIBDD: SendGPIB: TR
8:14:10.796: NIGPIBDD: ReceiveGPIB: 0,+7.51,0,+1.75
8:14:10.843: NIGPIBDD: SendGPIB: TR
8:14:10.843: NIGPIBDD: ReceiveGPIB: 0,+7.48,0,+1.28
8:14:10.859: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.13 MHz, (Power) 7.48 dBm)
8:14:10.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:10.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:10.875: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.875: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.13 MHz, (Attenuation) 40 dB)
8:14:10.875: NIGPIBDD: SendGPIB: TR
8:14:10.890: NIGPIBDD: ReceiveGPIB: 0,+7.47,0,+1.28
8:14:10.921: NIGPIBDD: SendGPIB: TR
8:14:10.937: NIGPIBDD: ReceiveGPIB: 0,+7.47,0,+1.28
8:14:10.937: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.13 MHz, (Power) 1.28 dBm)
8:14:10.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:10.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 2.80358E+024)
8:14:10.968: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.16 MHz)
8:14:10.968: NIGPIBDD: SaveSendGPIB function entered
8:14:10.984: NIGPIBDD: Assigning zero string to sCommand
8:14:10.984: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:10.984: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:10.984: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:11.000: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.16 MHz;*OPC?

8:14:11.000: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:11.000: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:11.000: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:11.015: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:11.015: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:11.031: NIGPIBDD: ReceiveGPIB: 1

8:14:11.031: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:11.031: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:11.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:11.031: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:11.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:11.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:11.062: NIGPIBDD: Just before returning the error code
8:14:11.062: NIGPIBDD: SaveSendGPIB function entered
8:14:11.062: NIGPIBDD: Assigning zero string to sCommand
8:14:11.078: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:11.078: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:11.078: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:11.078: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:11.093: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:11.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:11.109: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:11.109: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:11.109: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:11.109: NIGPIBDD: Just before returning the error code
8:14:11.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 89129)
8:14:11.125: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:11.156: NIGPIBDD: ReceiveGPIB: NO

8:14:11.187: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:11.234: NIGPIBDD: ReceiveGPIB: NO

8:14:11.250: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:11.296: NIGPIBDD: ReceiveGPIB: NO

8:14:11.312: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:11.359: NIGPIBDD: ReceiveGPIB: NO

8:14:11.375: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:11.406: NIGPIBDD: ReceiveGPIB: NO

8:14:11.437: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:11.468: NIGPIBDD: ReceiveGPIB: NO

8:14:11.484: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:11.531: NIGPIBDD: ReceiveGPIB: NO

8:14:11.562: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:11.593: NIGPIBDD: ReceiveGPIB: NO

8:14:11.609: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:11.640: NIGPIBDD: ReceiveGPIB: NC

8:14:11.671: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:11.703: NIGPIBDD: ReceiveGPIB: NC

8:14:11.718: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:11.781: NIGPIBDD: ReceiveGPIB: NC

8:14:11.796: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:11.843: NIGPIBDD: ReceiveGPIB: NC

8:14:11.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:11.859: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)

8:14:11.859: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)

8:14:11.875: NIGPIBDD: SendGPIB: TR

8:14:11.875: NIGPIBDD: ReceiveGPIB: 0,+7.65,0,+1.44

8:14:11.921: NIGPIBDD: SendGPIB: TR

8:14:11.921: NIGPIBDD: ReceiveGPIB: 0,+7.65,0,+1.44

8:14:11.937: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 7.65 dBm)

8:14:11.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)

8:14:11.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:11.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)

8:14:11.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)

8:14:11.968: NIGPIBDD: SendGPIB: TR

8:14:11.984: NIGPIBDD: ReceiveGPIB: 0,+7.65,0,+1.44

8:14:12.000: NIGPIBDD: SendGPIB: TR

8:14:12.015: NIGPIBDD: ReceiveGPIB: 0,+7.65,0,+1.44

8:14:12.015: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 1.44 dBm)

8:14:12.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)

8:14:12.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.44371E+027)

8:14:12.046: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -7.47271 dBm)
8:14:12.046: NIGPIBDD: SaveSendGPIB function entered
8:14:12.062: NIGPIBDD: Assigning zero string to sCommand
8:14:12.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:12.078: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:12.078: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:12.078: NIGPIBDD: SendGPIB: SOURCE:POWER -7.47271 DBM;*OPC?

8:14:12.078: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:12.093: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:12.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:12.093: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:12.109: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:12.109: NIGPIBDD: ReceiveGPIB: 1

8:14:12.109: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:12.125: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:12.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:12.125: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:12.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:12.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:12.140: NIGPIBDD: Just before returning the error code
8:14:12.156: NIGPIBDD: SaveSendGPIB function entered
8:14:12.156: NIGPIBDD: Assigning zero string to sCommand
8:14:12.156: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:12.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:12.171: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:12.171: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:12.171: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:12.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:12.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:12.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:12.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:12.203: NIGPIBDD: Just before returning the error code
8:14:12.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 4.47346E-007)
8:14:12.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:12.218: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:12.234: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:12.234: NIGPIBDD: SendGPIB: TR
8:14:12.250: NIGPIBDD: ReceiveGPIB: 0,+7.44,0,+1.24
8:14:12.281: NIGPIBDD: SendGPIB: TR
8:14:12.281: NIGPIBDD: ReceiveGPIB: 0,+7.44,0,+1.24
8:14:12.296: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 7.44 dBm)
8:14:12.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:14:12.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:12.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:12.328: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:12.328: NIGPIBDD: SendGPIB: TR
8:14:12.343: NIGPIBDD: ReceiveGPIB: 0,+7.44,0,+1.24
8:14:12.359: NIGPIBDD: SendGPIB: TR
8:14:12.375: NIGPIBDD: ReceiveGPIB: 0,+7.44,0,+1.24
8:14:12.375: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 1.24 dBm)
8:14:12.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:12.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 517476)
8:14:12.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:12.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:12.437: NIGPIBDD: SendGPIB: 1N
8:14:12.546: NIGPIBDD: ReceiveGPIB: DBA-5800E-2,0,0

8:14:12.562: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.16 MHz, (Power) -58 dBm)
8:14:12.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:12.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -7.39456E-012)
8:14:12.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:14.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:14.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:14.578: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:14.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:14.593: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:14.625: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:14.625: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:14.625: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:14.640: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:14.640: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:14.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:14.656: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:14.671: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:14.671: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:14.687: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:14.687: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:14.687: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:14.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:14.703: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:14.734: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:14.734: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:14.734: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:14.750: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:14.750: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:14.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:14.765: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:14.781: NIGPIBDD: ReceiveGPIB: 53.648E+0

8:14:14.781: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.648)
8:14:14.796: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:14.796: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:14.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:14.843: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:14.843: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:14.843: NIGPIBDD: SendGPIB: TR
8:14:14.875: NIGPIBDD: ReceiveGPIB: 0,+7.43,0,+1.25
8:14:14.890: NIGPIBDD: SendGPIB: TR
8:14:14.921: NIGPIBDD: ReceiveGPIB: 0,+7.43,0,+1.25
8:14:14.921: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 7.43 dBm)
8:14:14.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:14.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:14.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:14.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:14.953: NIGPIBDD: SendGPIB: TR
8:14:14.968: NIGPIBDD: ReceiveGPIB: 0,+7.43,0,+1.25

8:14:15.000: NIGPIBDD: SendGPIB: TR
8:14:15.015: NIGPIBDD: ReceiveGPIB: 0,+7.43,0,+1.25
8:14:15.031: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 1.25 dBm)
8:14:15.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:15.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 517476)
8:14:15.046: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -9.14387 dBm)
8:14:15.062: NIGPIBDD: SaveSendGPIB function entered
8:14:15.062: NIGPIBDD: Assigning zero string to sCommand
8:14:15.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.062: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.078: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:15.078: NIGPIBDD: SendGPIB: SOURCE:POWER -9.14387 DBM;*OPC?

8:14:15.093: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.093: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.093: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:15.093: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:15.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.109: NIGPIBDD: ReceiveGPIB: 1

8:14:15.109: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:15.109: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:15.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.125: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:15.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.140: NIGPIBDD: Just before returning the error code
8:14:15.140: NIGPIBDD: SaveSendGPIB function entered
8:14:15.156: NIGPIBDD: Assigning zero string to sCommand
8:14:15.156: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.156: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:15.171: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.171: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.187: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.203: NIGPIBDD: Just before returning the error code
8:14:15.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 6.61766E-033)
8:14:15.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:15.218: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:15.218: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:15.218: NIGPIBDD: SendGPIB: TR

8:14:15.234: NIGPIBDD: ReceiveGPIB: 0,+6.21,0,+0.04
8:14:15.265: NIGPIBDD: SendGPIB: TR
8:14:15.281: NIGPIBDD: ReceiveGPIB: 0,+5.84,0,-0.31
8:14:15.312: NIGPIBDD: SendGPIB: TR
8:14:15.328: NIGPIBDD: ReceiveGPIB: 0,+5.84,0,-0.31
8:14:15.328: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) 5.84 dBm)
8:14:15.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:15.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:15.359: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:15.359: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.16 MHz, (Attenuation) 40 dB)
8:14:15.375: NIGPIBDD: SendGPIB: TR
8:14:15.375: NIGPIBDD: ReceiveGPIB: 0,+5.84,0,-0.31
8:14:15.406: NIGPIBDD: SendGPIB: TR
8:14:15.421: NIGPIBDD: ReceiveGPIB: 0,+5.84,0,-0.30
8:14:15.421: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.16 MHz, (Power) -0.3 dBm)
8:14:15.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:15.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 517476)
8:14:15.453: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.19 MHz)
8:14:15.453: NIGPIBDD: SaveSendGPIB function entered
8:14:15.453: NIGPIBDD: Assigning zero string to sCommand
8:14:15.468: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.468: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.468: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:15.468: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.19 MHZ;*OPC?

8:14:15.484: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.484: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.500: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:15.500: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:15.500: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.500: NIGPIBDD: ReceiveGPIB: 1

8:14:15.515: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:15.515: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:15.531: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.531: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.531: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:15.531: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.546: NIGPIBDD: Just before returning the error code
8:14:15.546: NIGPIBDD: SaveSendGPIB function entered
8:14:15.546: NIGPIBDD: Assigning zero string to sCommand
8:14:15.546: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.562: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:15.562: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:15.578: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.578: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.578: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:15.578: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:15.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:15.593: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:15.593: NIGPIBDD: Just before returning the error code
8:14:15.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
9.80909E-045, (Data2) -7.46298E-036)
8:14:15.609: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:15.640: NIGPIBDD: ReceiveGPIB: NO

8:14:15.671: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:15.703: NIGPIBDD: ReceiveGPIB: NO

8:14:15.734: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:15.750: NIGPIBDD: ReceiveGPIB: NO

8:14:15.781: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:15.812: NIGPIBDD: ReceiveGPIB: NO

8:14:15.843: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:15.875: NIGPIBDD: ReceiveGPIB: NO

8:14:15.906: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:15.937: NIGPIBDD: ReceiveGPIB: NO

8:14:15.968: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:15.984: NIGPIBDD: ReceiveGPIB: NO

8:14:16.015: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:16.046: NIGPIBDD: ReceiveGPIB: NO

8:14:16.078: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:16.109: NIGPIBDD: ReceiveGPIB: NC

8:14:16.140: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:16.203: NIGPIBDD: ReceiveGPIB: NC

8:14:16.218: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:16.265: NIGPIBDD: ReceiveGPIO: NC

8:14:16.296: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?

8:14:16.343: NIGPIBDD: ReceiveGPIO: NC

8:14:16.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:16.359: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)

8:14:16.359: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)

8:14:16.359: NIGPIBDD: SendGPIO: TR

8:14:16.375: NIGPIBDD: ReceiveGPIO: 0,+5.94,0,-0.23

8:14:16.406: NIGPIBDD: SendGPIO: TR

8:14:16.421: NIGPIBDD: ReceiveGPIO: 0,+5.94,0,-0.23

8:14:16.421: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) 5.94 dBm)

8:14:16.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:14:16.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:16.453: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)

8:14:16.453: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)

8:14:16.453: NIGPIBDD: SendGPIO: TR

8:14:16.468: NIGPIBDD: ReceiveGPIO: 0,+5.94,0,-0.23

8:14:16.500: NIGPIBDD: SendGPIO: TR

8:14:16.515: NIGPIBDD: ReceiveGPIO: 0,+5.94,0,-0.23

8:14:16.531: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) -0.23 dBm)

8:14:16.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)

8:14:16.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.51377E-012)

8:14:16.546: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -9.32503 dBm)

8:14:16.562: NIGPIBDD: SaveSendGPIO function entered

8:14:16.562: NIGPIBDD: Assigning zero string to sCommand

8:14:16.562: NIGPIBDD: Before mcGPIOCommunication.Enter()

8:14:16.562: NIGPIBDD: After mcGPIOCommunication.Enter()

8:14:16.578: NIGPIBDD::SaveSendGPIO: mISuggestedReadSize: 0

8:14:16.578: NIGPIBDD: SendGPIO: SOURCE:POWER -9.32503 DBM;*OPC?

8:14:16.593: NIGPIBDD: Before mcGPIOCommunication.Leave()

8:14:16.593: NIGPIBDD: After mcGPIOCommunication.Leave()

8:14:16.593: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Enter()

8:14:16.609: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Enter()

8:14:16.609: NIGPIBDD: Before mcGPIOCommunication.Enter()

8:14:16.625: NIGPIBDD: ReceiveGPIO: 1

8:14:16.625: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:16.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:16.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:16.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:16.640: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:16.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:16.671: NIGPIBDD: Just before returning the error code
8:14:16.671: NIGPIBDD: SaveSendGPIB function entered
8:14:16.671: NIGPIBDD: Assigning zero string to sCommand
8:14:16.671: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:16.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:16.687: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:16.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:16.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:16.703: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:16.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:16.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:16.718: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:16.734: NIGPIBDD: Just before returning the error code
8:14:16.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -0.000295264)
8:14:16.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:16.750: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:16.765: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:16.765: NIGPIBDD: SendGPIB: TR
8:14:16.781: NIGPIBDD: ReceiveGPIB: 0,+5.76,0,-0.42
8:14:16.812: NIGPIBDD: SendGPIB: TR
8:14:16.828: NIGPIBDD: ReceiveGPIB: 0,+5.75,0,-0.42
8:14:16.828: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) 5.75 dBm)
8:14:16.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:16.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:16.859: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:16.859: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:16.859: NIGPIBDD: SendGPIB: TR
8:14:16.875: NIGPIBDD: ReceiveGPIB: 0,+5.75,0,-0.42
8:14:16.906: NIGPIBDD: SendGPIB: TR
8:14:16.921: NIGPIBDD: ReceiveGPIB: 0,+5.75,0,-0.42
8:14:16.921: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) -0.42 dBm)
8:14:16.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)
8:14:16.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.5873E-006)

8:14:16.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:16.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:16.968: NIGPIBDD: SendGPIO: 1N
8:14:17.078: NIGPIBDD: ReceiveGPIO: DBA-6176E-2,0,0

8:14:17.078: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.19 MHz, (Power) -61.76 dBm)
8:14:17.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) -1.0842E-019)
8:14:17.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.32302E+023)
8:14:17.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:19.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:19.109: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:19.109: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:19.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:19.125: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:14:19.156: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:14:19.156: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:19.156: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:19.156: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:19.171: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:19.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:19.187: NIGPIBDD: SendGPIO: :MEASU:MEAS2:VAL?

8:14:19.203: NIGPIBDD: ReceiveGPIO: 580.0E-3

8:14:19.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:19.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:19.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:19.218: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:19.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:19.234: NIGPIBDD: SendGPIO: :MEASU:MEAS3:VAL?

8:14:19.296: NIGPIBDD: ReceiveGPIO: 200.0E-3

8:14:19.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:14:19.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:19.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:19.312: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:19.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:19.328: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:19.375: NIGPIBDD: ReceiveGPIB: 53.670E+0

8:14:19.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.67)
8:14:19.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:19.390: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:19.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:19.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.437: NIGPIBDD: SendGPIB: TR
8:14:19.453: NIGPIBDD: ReceiveGPIB: 0,+5.74,0,-0.41
8:14:19.484: NIGPIBDD: SendGPIB: TR
8:14:19.500: NIGPIBDD: ReceiveGPIB: 0,+5.75,0,-0.41
8:14:19.500: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) 5.75 dBm)
8:14:19.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:19.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:19.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.531: NIGPIBDD: SendGPIB: TR
8:14:19.546: NIGPIBDD: ReceiveGPIB: 0,+5.75,0,-0.41
8:14:19.578: NIGPIBDD: SendGPIB: TR
8:14:19.593: NIGPIBDD: ReceiveGPIB: 0,+5.75,0,-0.41
8:14:19.593: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) -0.41 dBm)
8:14:19.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)
8:14:19.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.5873E-006)
8:14:19.609: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -10.4176 dBm)
8:14:19.609: NIGPIBDD: SaveSendGPIB function entered
8:14:19.625: NIGPIBDD: Assigning zero string to sCommand
8:14:19.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:19.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:19.640: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0

8:14:19.640: NIGPIBDD: SendGPIB: SOURCE:POWER -10.4176 DBM;*OPC?

8:14:19.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:19.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:19.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:19.656: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:19.671: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:19.671: NIGPIBDD: ReceiveGPIB: 1

8:14:19.671: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:19.687: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:19.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:19.687: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:19.687: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:19.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:19.703: NIGPIBDD: Just before returning the error code
8:14:19.718: NIGPIBDD: SaveSendGPIB function entered
8:14:19.718: NIGPIBDD: Assigning zero string to sCommand
8:14:19.718: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:19.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:19.734: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:19.734: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:19.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:19.750: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:19.750: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:19.750: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:19.765: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:19.765: NIGPIBDD: Just before returning the error code
8:14:19.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 3.26844E-037)
8:14:19.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:19.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.796: NIGPIBDD: SendGPIB: TR
8:14:19.812: NIGPIBDD: ReceiveGPIB: 0,+4.76,0,-1.38
8:14:19.859: NIGPIBDD: SendGPIB: TR
8:14:19.859: NIGPIBDD: ReceiveGPIB: 0,+4.69,0,-1.45
8:14:19.875: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) 4.69 dBm)
8:14:19.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)
8:14:19.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:19.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.19 MHz, (Attenuation) 40 dB)
8:14:19.906: NIGPIBDD: SendGPIB: TR
8:14:19.937: NIGPIBDD: ReceiveGPIB: 0,+4.69,0,-1.45

8:14:19.953: NIGPIBDD: SendGPIB: TR
8:14:19.984: NIGPIBDD: ReceiveGPIB: 0,+4.69,0,-1.45
8:14:19.984: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.19 MHz, (Power) -1.45 dBm)
8:14:20.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:20.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.5873E-006)
8:14:20.015: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.22 MHz)
8:14:20.015: NIGPIBDD: SaveSendGPIB function entered
8:14:20.031: NIGPIBDD: Assigning zero string to sCommand
8:14:20.031: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:20.046: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:20.046: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:20.046: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.22 MHZ,*OPC?

8:14:20.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:20.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:20.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:20.062: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:20.078: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:20.093: NIGPIBDD: ReceiveGPIB: 1

8:14:20.093: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:20.109: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:20.109: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:20.109: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:20.109: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:20.125: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:20.125: NIGPIBDD: Just before returning the error code
8:14:20.140: NIGPIBDD: SaveSendGPIB function entered
8:14:20.140: NIGPIBDD: Assigning zero string to sCommand
8:14:20.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:20.140: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:20.156: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:20.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:20.171: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:20.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:20.171: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:20.171: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:20.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:20.187: NIGPIBDD: Just before returning the error code
8:14:20.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -71.68)
8:14:20.203: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:20.234: NIGPIBDD: ReceiveGPIB: NO

8:14:20.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:20.328: NIGPIBDD: ReceiveGPIB: NO

8:14:20.343: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?
8:14:20.390: NIGPIBDD: ReceiveGPIB: NO
8:14:20.421: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?
8:14:20.468: NIGPIBDD: ReceiveGPIB: NO
8:14:20.484: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:20.531: NIGPIBDD: ReceiveGPIB: NO
8:14:20.546: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:20.593: NIGPIBDD: ReceiveGPIB: NO
8:14:20.609: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:20.640: NIGPIBDD: ReceiveGPIB: NO
8:14:20.656: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:20.703: NIGPIBDD: ReceiveGPIB: NO
8:14:20.718: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:20.765: NIGPIBDD: ReceiveGPIB: NC
8:14:20.781: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:20.843: NIGPIBDD: ReceiveGPIB: NC
8:14:20.859: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:20.890: NIGPIBDD: ReceiveGPIB: NC
8:14:20.921: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:20.937: NIGPIBDD: ReceiveGPIB: NC
8:14:20.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:20.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:20.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:20.968: NIGPIBDD: SendGPIB: TR
8:14:20.984: NIGPIBDD: ReceiveGPIB: 0,+4.62,0,-1.54
8:14:21.015: NIGPIBDD: SendGPIB: TR
8:14:21.015: NIGPIBDD: ReceiveGPIB: 0,+4.62,0,-1.54

8:14:21.031: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.22 MHz, (Power) 4.62 dBm)
8:14:21.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)
8:14:21.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:21.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:21.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:21.062: NIGPIBDD: SendGPIO: TR
8:14:21.078: NIGPIBDD: ReceiveGPIO: 0,+4.62,0,-1.54
8:14:21.093: NIGPIBDD: SendGPIO: TR
8:14:21.109: NIGPIBDD: ReceiveGPIO: 0,+4.62,0,-1.54
8:14:21.109: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.22 MHz, (Power) -1.54 dBm)
8:14:21.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:21.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 3.244E-008)
8:14:21.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:21.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:21.156: NIGPIBDD: SendGPIO: 1N
8:14:21.312: NIGPIBDD: ReceiveGPIO: DBA-6488E-2,0,0

8:14:21.328: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.22 MHz, (Power) -64.88 dBm)
8:14:21.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) -3.68935E+019)
8:14:21.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -3.71618E-034)
8:14:21.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:23.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:23.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:23.343: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:23.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:23.359: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:14:23.390: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:14:23.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:23.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:23.406: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:23.406: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:23.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:23.421: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:23.437: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:23.437: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 1.4013E-045, (Data2) 0.58)
8:14:23.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 1.4013E-045, (Data2) 100)
8:14:23.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:23.468: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:23.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:23.468: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:23.500: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:23.500: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 2.8026E-045, (Data2) 0.2)
8:14:23.500: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 2.8026E-045, (Data2) 100)
8:14:23.531: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:23.531: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:23.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:14:23.546: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:23.578: NIGPIBDD: ReceiveGPIB: 53.730E+0

8:14:23.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 4.2039E-045, (Data2) 53.73)
8:14:23.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 4.2039E-045, (Data2) 100)
8:14:23.578: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:23.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.22299E-044, (Data2) 0)
8:14:23.609: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:23.609: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:23.609: NIGPIBDD: SendGPIB: TR
8:14:23.625: NIGPIBDD: ReceiveGPIB: 0,+4.61,0,-1.54
8:14:23.656: NIGPIBDD: SendGPIB: TR
8:14:23.671: NIGPIBDD: ReceiveGPIB: 0,+4.61,0,-1.54
8:14:23.671: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.22 MHz, (Power) 4.61 dBm)
8:14:23.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) -3.68935E+019)
8:14:23.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)

8:14:23.703: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:23.703: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:23.703: NIGPIBDD: SendGPIB: TR
8:14:23.718: NIGPIBDD: ReceiveGPIB: 0,+4.61,0,-1.54
8:14:23.750: NIGPIBDD: SendGPIB: TR
8:14:23.765: NIGPIBDD: ReceiveGPIB: 0,+4.61,0,-1.54
8:14:23.765: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.22 MHz, (Power) -1.54 dBm)
8:14:23.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) 0)
8:14:23.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) 3.244E-008)
8:14:23.796: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -11.1864 dBm)
8:14:23.796: NIGPIBDD: SaveSendGPIB function entered
8:14:23.796: NIGPIBDD: Assigning zero string to sCommand
8:14:23.812: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:23.812: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:23.828: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:23.828: NIGPIBDD: SendGPIB: SOURCE:POWER -11.1864 DBM;*OPC?

8:14:23.828: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:23.828: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:23.843: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:23.843: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:23.843: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:23.843: NIGPIBDD: ReceiveGPIB: 1

8:14:23.859: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:23.859: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:23.875: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:23.875: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:23.875: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:23.875: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:23.890: NIGPIBDD: Just before returning the error code
8:14:23.890: NIGPIBDD: SaveSendGPIB function entered
8:14:23.890: NIGPIBDD: Assigning zero string to sCommand
8:14:23.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:23.906: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:23.906: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:23.921: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:23.921: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:23.921: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:23.921: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:23.937: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:23.937: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:23.953: NIGPIBDD: Just before returning the error code
8:14:23.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
1.12104E-044, (Data2) 7.69292E-007)

8:14:23.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:23.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:23.968: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:23.968: NIGPIBDD: SendGPIO: TR
8:14:23.984: NIGPIBDD: ReceiveGPIO: 0,+4.61,0,-2.24
8:14:24.015: NIGPIBDD: SendGPIO: TR
8:14:24.031: NIGPIBDD: ReceiveGPIO: 0,+4.61,0,-2.25
8:14:24.031: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.22 MHz, (Power) 4.61 dBm)
8:14:24.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:24.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:24.062: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:24.062: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:24.062: NIGPIBDD: SendGPIO: TR
8:14:24.078: NIGPIBDD: ReceiveGPIO: 0,+4.61,0,-2.26
8:14:24.109: NIGPIBDD: SendGPIO: TR
8:14:24.109: NIGPIBDD: ReceiveGPIO: 0,+4.61,0,-2.26
8:14:24.125: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.22 MHz, (Power) -2.26 dBm)
8:14:24.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:14:24.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 3.244E-008)
8:14:24.140: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -11.9551 dBm)
8:14:24.156: NIGPIBDD: SaveSendGPIO function entered
8:14:24.156: NIGPIBDD: Assigning zero string to sCommand
8:14:24.171: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:24.171: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:24.171: NIGPIBDD::SaveSendGPIO: mlSuggestedReadSize: 0
8:14:24.171: NIGPIBDD: SendGPIO: SOURCE:POWER -11.9551 DBM;*OPC?

8:14:24.187: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:24.187: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:24.187: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:24.203: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:24.203: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Enter()
8:14:24.203: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:24.218: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Enter()
8:14:24.218: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:24.218: NIGPIBDD: ReceiveGPIO: 1

8:14:24.218: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:24.218: NIGPIBDD: Just before returning the error code
8:14:24.234: NIGPIBDD: SaveSendGPIO function entered

8:14:24.234: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:24.234: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:24.250: NIGPIBDD: Assigning zero string to sCommand
8:14:24.250: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:24.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:24.265: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:24.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:24.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:24.281: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:24.281: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:24.281: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:24.281: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:24.296: NIGPIBDD: Just before returning the error code
8:14:24.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.7999E+024)
8:14:24.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:24.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:24.328: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:24.328: NIGPIBDD: SendGPIB: TR
8:14:24.343: NIGPIBDD: ReceiveGPIB: 0,+3.17,0,-2.96
8:14:24.359: NIGPIBDD: SendGPIB: TR
8:14:24.375: NIGPIBDD: ReceiveGPIB: 0,+3.15,0,-2.98
8:14:24.375: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.22 MHz, (Power) 3.15 dBm)
8:14:24.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)
8:14:24.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:24.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:24.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.22 MHz, (Attenuation) 40 dB)
8:14:24.421: NIGPIBDD: SendGPIB: TR
8:14:24.421: NIGPIBDD: ReceiveGPIB: 0,+3.13,0,-2.99
8:14:24.453: NIGPIBDD: SendGPIB: TR
8:14:24.468: NIGPIBDD: ReceiveGPIB: 0,+3.13,0,-2.99
8:14:24.484: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.22 MHz, (Power) -2.99 dBm)
8:14:24.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:14:24.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 3.244E-008)
8:14:24.500: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.25 MHz)
8:14:24.500: NIGPIBDD: SaveSendGPIB function entered
8:14:24.500: NIGPIBDD: Assigning zero string to sCommand
8:14:24.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:24.515: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:24.531: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:14:24.531: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.25 MHZ;*OPC?

8:14:24.531: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:24.531: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:24.546: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:24.546: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:24.546: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:24.562: NIGPIBDD: ReceiveGPIB: 1

8:14:24.562: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:24.562: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:24.578: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:24.578: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:24.578: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:24.578: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:24.593: NIGPIBDD: Just before returning the error code
8:14:24.593: NIGPIBDD: SaveSendGPIB function entered
8:14:24.609: NIGPIBDD: Assigning zero string to sCommand
8:14:24.609: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:24.609: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:24.609: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:24.625: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:24.625: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:24.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:24.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:24.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:24.640: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:24.656: NIGPIBDD: Just before returning the error code
8:14:24.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 0)
8:14:24.656: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:24.718: NIGPIBDD: ReceiveGPIB: NO

8:14:24.750: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:24.781: NIGPIBDD: ReceiveGPIB: NO

8:14:24.796: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:24.828: NIGPIBDD: ReceiveGPIB: NO

8:14:24.859: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:24.906: NIGPIBDD: ReceiveGPIB: NO

8:14:24.921: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:24.984: NIGPIBDD: ReceiveGPIB: NO

8:14:25.000: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:25.031: NIGPIBDD: ReceiveGPIB: NO

8:14:25.046: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:25.078: NIGPIBDD: ReceiveGPIB: NO

8:14:25.109: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:25.140: NIGPIBDD: ReceiveGPIB: NO

8:14:25.156: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:25.218: NIGPIBDD: ReceiveGPIB: NC

8:14:25.234: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:25.265: NIGPIBDD: ReceiveGPIB: NC

8:14:25.296: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:25.328: NIGPIBDD: ReceiveGPIB: NC

8:14:25.343: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:25.375: NIGPIBDD: ReceiveGPIB: NC

8:14:25.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:25.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)

8:14:25.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)

8:14:25.421: NIGPIBDD: SendGPIB: TR

8:14:25.437: NIGPIBDD: ReceiveGPIB: 0,+3.15,0,-3.01

8:14:25.468: NIGPIBDD: SendGPIB: TR

8:14:25.484: NIGPIBDD: ReceiveGPIB: 0,+3.15,0,-3.01

8:14:25.484: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) 3.15 dBm)

8:14:25.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)

8:14:25.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:25.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)

8:14:25.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)

8:14:25.531: NIGPIBDD: SendGPIB: TR

8:14:25.531: NIGPIBDD: ReceiveGPIB: 0,+3.15,0,-3.01

8:14:25.578: NIGPIBDD: SendGPIB: TR

8:14:25.578: NIGPIBDD: ReceiveGPIB: 0,+3.15,0,-3.01

8:14:25.593: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) -3.01 dBm)

8:14:25.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:14:25.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -4.21721E-005)
8:14:25.625: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -11.2638 dBm)
8:14:25.625: NIGPIBDD: SaveSendGPIB function entered
8:14:25.640: NIGPIBDD: Assigning zero string to sCommand
8:14:25.640: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:25.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:25.656: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:25.656: NIGPIBDD: SendGPIB: SOURCE:POWER -11.2638 DBM;*OPC?

8:14:25.671: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:25.671: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:25.671: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:25.687: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:25.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:25.703: NIGPIBDD: ReceiveGPIB: 1

8:14:25.703: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:25.703: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:25.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:25.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:25.718: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:25.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:25.734: NIGPIBDD: Just before returning the error code
8:14:25.734: NIGPIBDD: SaveSendGPIB function entered
8:14:25.750: NIGPIBDD: Assigning zero string to sCommand
8:14:25.750: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:25.765: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:25.765: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:25.765: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:25.765: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:25.781: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:25.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:25.781: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:25.781: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:25.796: NIGPIBDD: Just before returning the error code
8:14:25.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 2.26694E+035)
8:14:25.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:25.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:25.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:25.828: NIGPIBDD: SendGPIB: TR
8:14:25.843: NIGPIBDD: ReceiveGPIB: 0,+3.69,0,-2.47
8:14:25.875: NIGPIBDD: SendGPIB: TR
8:14:25.890: NIGPIBDD: ReceiveGPIB: 0,+3.82,0,-2.34

8:14:25.890: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) 3.82 dBm)
8:14:25.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:25.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:25.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:25.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:25.921: NIGPIBDD: SendGPIO: TR
8:14:25.921: NIGPIBDD: ReceiveGPIO: 0,+3.82,0,-2.35
8:14:25.968: NIGPIBDD: SendGPIO: TR
8:14:25.968: NIGPIBDD: ReceiveGPIO: 0,+3.82,0,-2.35
8:14:25.984: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) -2.35 dBm)
8:14:25.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:26.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.35117E+038)
8:14:26.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:26.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:26.015: NIGPIBDD: SendGPIO: 1N
8:14:26.140: NIGPIBDD: ReceiveGPIO: DBA-6757E-2,0,0

8:14:26.140: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.25 MHz, (Power) -67.57 dBm)
8:14:26.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) -3.68935E+019)
8:14:26.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 2.14354E-032)
8:14:26.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:28.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:28.156: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:28.156: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:28.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:28.171: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:14:28.203: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:14:28.203: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:28.203: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:28.203: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:28.218: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:28.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:28.234: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:28.250: NIGPIBDD: ReceiveGPIB: 560.0E-3

8:14:28.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.56)
8:14:28.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:28.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:28.265: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:28.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:28.281: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:28.312: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:28.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:28.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:28.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:28.328: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:28.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:28.343: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:28.390: NIGPIBDD: ReceiveGPIB: 53.863E+0

8:14:28.406: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.863)
8:14:28.406: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:28.421: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:28.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:28.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.453: NIGPIBDD: SendGPIB: TR
8:14:28.453: NIGPIBDD: ReceiveGPIB: 0,+3.82,0,-2.35
8:14:28.484: NIGPIBDD: SendGPIB: TR
8:14:28.500: NIGPIBDD: ReceiveGPIB: 0,+3.82,0,-2.35
8:14:28.500: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) 3.82 dBm)
8:14:28.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:28.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:28.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.531: NIGPIBDD: SendGPIB: TR
8:14:28.546: NIGPIBDD: ReceiveGPIB: 0,+3.82,0,-2.35
8:14:28.578: NIGPIBDD: SendGPIB: TR
8:14:28.593: NIGPIBDD: ReceiveGPIB: 0,+3.82,0,-2.35
8:14:28.593: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) -2.35 dBm)
8:14:28.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:28.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.35117E+038)
8:14:28.625: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -12.0408 dBm)
8:14:28.625: NIGPIBDD: SaveSendGPIB function entered
8:14:28.640: NIGPIBDD: Assigning zero string to sCommand
8:14:28.640: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:28.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:28.640: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:28.656: NIGPIBDD: SendGPIB: SOURCE:POWER -12.0408 DBM;*OPC?

8:14:28.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:28.671: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:28.671: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:28.671: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:28.671: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:28.687: NIGPIBDD: ReceiveGPIB: 1

8:14:28.687: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:28.687: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:28.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:28.703: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:28.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:28.718: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:28.718: NIGPIBDD: Just before returning the error code
8:14:28.718: NIGPIBDD: SaveSendGPIB function entered
8:14:28.718: NIGPIBDD: Assigning zero string to sCommand
8:14:28.734: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:28.734: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:28.734: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:28.750: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:28.750: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:28.750: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:28.765: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:28.765: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:28.765: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:28.765: NIGPIBDD: Just before returning the error code
8:14:28.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.80387E+025)

8:14:28.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:28.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.828: NIGPIBDD: SendGPIB: TR
8:14:28.843: NIGPIBDD: ReceiveGPIB: 0,+3.22,0,-2.94
8:14:28.875: NIGPIBDD: SendGPIB: TR
8:14:28.875: NIGPIBDD: ReceiveGPIB: 0,+3.06,0,-3.10
8:14:28.890: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) 3.06 dBm)
8:14:28.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)
8:14:28.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:28.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.25 MHz, (Attenuation) 40 dB)
8:14:28.921: NIGPIBDD: SendGPIB: TR
8:14:28.937: NIGPIBDD: ReceiveGPIB: 0,+3.06,0,-3.10
8:14:28.953: NIGPIBDD: SendGPIB: TR
8:14:28.968: NIGPIBDD: ReceiveGPIB: 0,+3.06,0,-3.10
8:14:28.968: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.25 MHz, (Power) -3.1 dBm)
8:14:28.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:28.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.35117E+038)
8:14:29.000: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.28 MHz)
8:14:29.000: NIGPIBDD: SaveSendGPIB function entered
8:14:29.015: NIGPIBDD: Assigning zero string to sCommand
8:14:29.015: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:29.015: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:29.031: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:29.031: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.28 MHZ;*OPC?

8:14:29.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:29.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:29.046: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:29.046: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:29.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:29.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:29.062: NIGPIBDD: Just before returning the error code
8:14:29.062: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:29.078: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:29.078: NIGPIBDD: SaveSendGPIB function entered
8:14:29.078: NIGPIBDD: Assigning zero string to sCommand
8:14:29.078: NIGPIBDD: ReceiveGPIB: 1

8:14:29.093: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:29.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:29.093: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:29.109: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:29.109: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:29.109: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:29.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:29.125: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:29.125: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:29.140: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:29.140: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:29.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:29.140: NIGPIBDD: Just before returning the error code
8:14:29.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 1.95156E-020)
8:14:29.156: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:29.187: NIGPIBDD: ReceiveGPIB: NO

8:14:29.218: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:29.250: NIGPIBDD: ReceiveGPIB: NO

8:14:29.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:29.312: NIGPIBDD: ReceiveGPIB: NO

8:14:29.343: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:29.375: NIGPIBDD: ReceiveGPIB: NO

8:14:29.390: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:29.421: NIGPIBDD: ReceiveGPIB: NO

8:14:29.453: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:29.484: NIGPIBDD: ReceiveGPIB: NO

8:14:29.515: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:29.562: NIGPIBDD: ReceiveGPIB: NO

8:14:29.578: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:29.625: NIGPIBDD: ReceiveGPIB: NO

8:14:29.640: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:29.671: NIGPIBDD: ReceiveGPIB: NC

8:14:29.703: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:29.734: NIGPIBDD: ReceiveGPIB: NC

8:14:29.750: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:29.796: NIGPIBDD: ReceiveGPIB: NC

8:14:29.812: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:29.875: NIGPIBDD: ReceiveGPIB: NC

8:14:29.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:29.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)

8:14:29.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)

8:14:29.890: NIGPIBDD: SendGPIB: TR

8:14:29.906: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10

8:14:29.937: NIGPIBDD: SendGPIB: TR

8:14:29.953: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10

8:14:29.953: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.28 MHz, (Power) 3.09 dBm)

8:14:29.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)

8:14:29.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:29.968: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)

8:14:29.984: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)

8:14:29.984: NIGPIBDD: SendGPIB: TR

8:14:30.000: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10

8:14:30.031: NIGPIBDD: SendGPIB: TR

8:14:30.109: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10

8:14:30.109: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.28 MHz, (Power) -3.1 dBm)

8:14:30.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)

8:14:30.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -25.3609)

8:14:30.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)

8:14:30.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:14:30.156: NIGPIBDD: SendGPIB: 1N

8:14:30.312: NIGPIBDD: ReceiveGPIB: DBA-6990E-2,0,0

8:14:30.312: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.28 MHz, (Power) -69.9 dBm)

8:14:30.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) -1.0842E-019)

8:14:30.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -238.53)

8:14:30.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)

8:14:32.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)

8:14:32.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:32.343: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:32.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:32.359: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:32.375: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:32.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)

8:14:32.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)

8:14:32.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:32.390: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:32.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:32.406: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:32.437: NIGPIBDD: ReceiveGPIB: 560.0E-3

8:14:32.437: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.56)

8:14:32.437: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)

8:14:32.437: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:32.453: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:32.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:32.468: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:32.484: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:32.500: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:14:32.500: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)

8:14:32.515: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:32.515: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:32.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:32.531: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:32.546: NIGPIBDD: ReceiveGPIB: 53.890E+0

8:14:32.546: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.89)

8:14:32.562: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:32.562: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:32.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:32.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:32.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:32.593: NIGPIBDD: SendGPIB: TR
8:14:32.609: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10
8:14:32.625: NIGPIBDD: SendGPIB: TR
8:14:32.640: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10
8:14:32.640: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.28 MHz, (Power) 3.09 dBm)
8:14:32.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:32.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:32.671: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:32.671: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:32.687: NIGPIBDD: SendGPIB: TR
8:14:32.687: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10
8:14:32.718: NIGPIBDD: SendGPIB: TR
8:14:32.734: NIGPIBDD: ReceiveGPIB: 0,+3.09,0,-3.10
8:14:32.750: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.28 MHz, (Power) -3.1 dBm)
8:14:32.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:32.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -25.3609)
8:14:32.765: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -12.7706 dBm)
8:14:32.781: NIGPIBDD: SaveSendGPIB function entered
8:14:32.781: NIGPIBDD: Assigning zero string to sCommand
8:14:32.781: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:32.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:32.796: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:32.796: NIGPIBDD: SendGPIB: SOURCE:POWER -12.7706 DBM;*OPC?

8:14:32.812: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:32.812: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:32.812: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:32.812: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:32.828: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:32.828: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:32.828: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:32.843: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:32.843: NIGPIBDD: Just before returning the error code
8:14:32.843: NIGPIBDD: SaveSendGPIB function entered

8:14:32.843: NIGPIBDD: ReceiveGPIB: 1

8:14:32.859: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:32.859: NIGPIBDD: Assigning zero string to sCommand
8:14:32.859: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:32.859: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:32.875: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:32.875: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:32.875: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:32.890: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:32.890: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:32.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:32.906: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:32.906: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:32.906: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:32.921: NIGPIBDD: Just before returning the error code
8:14:32.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 7602.3)
8:14:32.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:32.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:32.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:32.937: NIGPIBDD: SendGPIB: TR
8:14:32.953: NIGPIBDD: ReceiveGPIB: 0,+2.53,0,-3.66
8:14:33.000: NIGPIBDD: SendGPIB: TR
8:14:33.015: NIGPIBDD: ReceiveGPIB: 0,+2.38,0,-3.80
8:14:33.015: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.28 MHz, (Power) 2.38 dBm)
8:14:33.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:33.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:33.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:33.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.28 MHz, (Attenuation) 40 dB)
8:14:33.046: NIGPIBDD: SendGPIB: TR
8:14:33.046: NIGPIBDD: ReceiveGPIB: 0,+2.38,0,-3.80
8:14:33.093: NIGPIBDD: SendGPIB: TR
8:14:33.093: NIGPIBDD: ReceiveGPIB: 0,+2.38,0,-3.80
8:14:33.109: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.28 MHz, (Power) -3.8 dBm)
8:14:33.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:14:33.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -25.3609)
8:14:33.125: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.31 MHz)
8:14:33.140: NIGPIBDD: SaveSendGPIB function entered
8:14:33.140: NIGPIBDD: Assigning zero string to sCommand

8:14:33.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:33.140: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:33.156: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:33.156: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.31 MHZ;*OPC?

8:14:33.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:33.156: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:33.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:33.171: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:33.171: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:33.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:33.187: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:33.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:33.187: NIGPIBDD: ReceiveGPIB: 1

8:14:33.203: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:33.203: NIGPIBDD: Just before returning the error code
8:14:33.203: NIGPIBDD: SaveSendGPIB function entered
8:14:33.203: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:33.218: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:33.218: NIGPIBDD: Assigning zero string to sCommand
8:14:33.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:33.234: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:33.234: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:33.250: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:33.250: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:33.250: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:33.250: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:33.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:33.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:33.281: NIGPIBDD: Just before returning the error code
8:14:33.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 0.05875)
8:14:33.281: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:33.312: NIGPIBDD: ReceiveGPIB: NO

8:14:33.343: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:33.390: NIGPIBDD: ReceiveGPIB: NO

8:14:33.406: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:33.453: NIGPIBDD: ReceiveGPIB: NO

8:14:33.468: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:33.500: NIGPIBDD: ReceiveGPIB: NO

8:14:33.531: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:33.562: NIGPIBDD: ReceiveGPIB: NO

8:14:33.578: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:33.625: NIGPIBDD: ReceiveGPIB: NO
8:14:33.640: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:33.718: NIGPIBDD: ReceiveGPIB: NO
8:14:33.734: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:33.781: NIGPIBDD: ReceiveGPIB: NO
8:14:33.796: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:33.843: NIGPIBDD: ReceiveGPIB: NC
8:14:33.875: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:33.906: NIGPIBDD: ReceiveGPIB: NC
8:14:33.937: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:33.968: NIGPIBDD: ReceiveGPIB: NC
8:14:34.000: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:34.015: NIGPIBDD: ReceiveGPIB: NC

8:14:34.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:34.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)
8:14:34.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)
8:14:34.046: NIGPIBDD: SendGPIB: TR
8:14:34.062: NIGPIBDD: ReceiveGPIB: 0,+2.29,0,-3.93
8:14:34.093: NIGPIBDD: SendGPIB: TR
8:14:34.109: NIGPIBDD: ReceiveGPIB: 0,+2.29,0,-3.93
8:14:34.109: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.31 MHz, (Power) 2.29 dBm)
8:14:34.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:14:34.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:34.140: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)
8:14:34.140: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)
8:14:34.140: NIGPIBDD: SendGPIB: TR
8:14:34.156: NIGPIBDD: ReceiveGPIB: 0,+2.29,0,-3.93
8:14:34.187: NIGPIBDD: SendGPIB: TR

8:14:34.203: NIGPIBDD: ReceiveGPIO: 0,+2.28,0,-3.93
8:14:34.218: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.31 MHz, (Power) -3.93 dBm)
8:14:34.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:14:34.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 8.06603E+037)
8:14:34.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:34.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:34.265: NIGPIBDD: SendGPIO: 1N
8:14:34.421: NIGPIBDD: ReceiveGPIO: DBA-7267E-2,0,0

8:14:34.421: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.31 MHz, (Power) -72.67 dBm)
8:14:34.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 2)
8:14:34.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -7.63109E-022)
8:14:34.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:36.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:36.468: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:36.468: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:36.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:36.484: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:14:36.515: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:14:36.515: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:36.515: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:36.515: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:36.531: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:36.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:36.546: NIGPIBDD: SendGPIO: :MEASU:MEAS2:VAL?

8:14:36.562: NIGPIBDD: ReceiveGPIO: 580.0E-3

8:14:36.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:36.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:36.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:36.578: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:36.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:36.593: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:36.625: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:36.625: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:14:36.640: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)

8:14:36.656: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:36.671: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:36.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:36.687: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:36.703: NIGPIBDD: ReceiveGPIB: 53.898E+0

8:14:36.718: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.898)

8:14:36.718: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)

8:14:36.718: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)

8:14:36.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:36.750: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)

8:14:36.750: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)

8:14:36.750: NIGPIBDD: SendGPIB: TR

8:14:36.765: NIGPIBDD: ReceiveGPIB: 0,+2.27,0,-3.93

8:14:36.796: NIGPIBDD: SendGPIB: TR

8:14:36.812: NIGPIBDD: ReceiveGPIB: 0,+2.27,0,-3.93

8:14:36.812: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.31 MHz, (Power) 2.27 dBm)

8:14:36.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)

8:14:36.828: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:36.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)

8:14:36.843: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)

8:14:36.843: NIGPIBDD: SendGPIB: TR

8:14:36.859: NIGPIBDD: ReceiveGPIB: 0,+2.27,0,-3.93

8:14:36.890: NIGPIBDD: SendGPIB: TR

8:14:36.906: NIGPIBDD: ReceiveGPIB: 0,+2.27,0,-3.93

8:14:36.906: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.31 MHz, (Power) -3.93 dBm)

8:14:36.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)

8:14:36.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 8.06603E+037)

8:14:36.937: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -13.037 dBm)

8:14:36.937: NIGPIBDD: SaveSendGPIB function entered

8:14:36.937: NIGPIBDD: Assigning zero string to sCommand

8:14:36.937: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:36.953: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:36.953: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:14:36.953: NIGPIBDD: SendGPIB: SOURCE:POWER -13.037 DBM;*OPC?

8:14:36.968: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:36.968: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:36.968: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:36.984: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:14:36.984: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:14:36.984: NIGPIBDD: ReceiveGPIB: 1

8:14:36.984: NIGPIBDD: After CheckDeviceSpecificStatusRegister

8:14:37.000: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()

8:14:37.000: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:37.000: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()

8:14:37.015: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:37.015: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:37.015: NIGPIBDD: Just before returning the error code

8:14:37.031: NIGPIBDD: SaveSendGPIB function entered

8:14:37.031: NIGPIBDD: Assigning zero string to sCommand

8:14:37.031: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:37.031: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:37.046: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10

8:14:37.046: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:37.062: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:37.062: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:37.062: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:37.062: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:37.078: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:37.078: NIGPIBDD: Just before returning the error code

8:14:37.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -1.3609E-037)

8:14:37.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:37.093: DVDRSYS.DLL: GetValue((ID) 393216, (Function)

CP_GetForwardAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)

8:14:37.093: DVDRSYS.DLL: GetValue((ID) 393216, (Function)

CP_GetReflectedAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)

8:14:37.109: NIGPIBDD: SendGPIB: TR

8:14:37.109: NIGPIBDD: ReceiveGPIB: 0,+2.02,0,-4.18

8:14:37.156: NIGPIBDD: SendGPIB: TR

8:14:37.156: NIGPIBDD: ReceiveGPIB: 0,+2.02,0,-4.19

8:14:37.171: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.31 MHz, (Power) 2.02 dBm)

8:14:37.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)

8:14:37.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:37.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)
8:14:37.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.31 MHz, (Attenuation) 40 dB)
8:14:37.203: NIGPIBDD: SendGPIB: TR
8:14:37.218: NIGPIBDD: ReceiveGPIB: 0,+2.01,0,-4.19
8:14:37.234: NIGPIBDD: SendGPIB: TR
8:14:37.250: NIGPIBDD: ReceiveGPIB: 0,+2.01,0,-4.20
8:14:37.250: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.31 MHz, (Power) -4.2 dBm)
8:14:37.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:37.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 8.06603E+037)
8:14:37.281: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.34 MHz)
8:14:37.281: NIGPIBDD: SaveSendGPIB function entered
8:14:37.296: NIGPIBDD: Assigning zero string to sCommand
8:14:37.296: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:37.296: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:37.296: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:37.312: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.34 MHZ;*OPC?

8:14:37.312: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:37.328: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:37.328: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:37.328: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:37.328: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:37.343: NIGPIBDD: ReceiveGPIB: 1

8:14:37.343: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:37.343: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:37.359: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:37.359: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:37.359: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:37.375: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:37.375: NIGPIBDD: Just before returning the error code
8:14:37.375: NIGPIBDD: SaveSendGPIB function entered
8:14:37.375: NIGPIBDD: Assigning zero string to sCommand
8:14:37.390: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:37.390: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:37.390: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:37.406: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:37.406: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:37.406: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:37.421: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:37.421: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:37.421: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:37.421: NIGPIBDD: Just before returning the error code

8:14:37.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 1.90232E+017)
8:14:37.437: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:37.468: NIGPIBDD: ReceiveGPIB: NO

8:14:37.484: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:37.515: NIGPIBDD: ReceiveGPIB: NO

8:14:37.546: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:37.593: NIGPIBDD: ReceiveGPIB: NO

8:14:37.609: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:37.640: NIGPIBDD: ReceiveGPIB: NO

8:14:37.656: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:37.687: NIGPIBDD: ReceiveGPIB: NO

8:14:37.718: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:37.750: NIGPIBDD: ReceiveGPIB: NO

8:14:37.781: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:37.843: NIGPIBDD: ReceiveGPIB: NO

8:14:37.859: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:37.906: NIGPIBDD: ReceiveGPIB: NO

8:14:37.937: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:37.984: NIGPIBDD: ReceiveGPIB: NC

8:14:38.000: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:38.046: NIGPIBDD: ReceiveGPIB: NC

8:14:38.062: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:38.109: NIGPIBDD: ReceiveGPIB: NC

8:14:38.125: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:38.156: NIGPIBDD: ReceiveGPIB: NC

8:14:38.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:38.171: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.171: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.187: NIGPIBDD: SendGPIB: TR
8:14:38.187: NIGPIBDD: ReceiveGPIB: 0,+2.11,0,-4.12
8:14:38.218: NIGPIBDD: SendGPIB: TR
8:14:38.234: NIGPIBDD: ReceiveGPIB: 0,+2.12,0,-4.12
8:14:38.234: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.34 MHz, (Power) 2.12 dBm)
8:14:38.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) 0)
8:14:38.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)
8:14:38.265: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.265: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.265: NIGPIBDD: SendGPIB: TR
8:14:38.281: NIGPIBDD: ReceiveGPIB: 0,+2.12,0,-4.12
8:14:38.312: NIGPIBDD: SendGPIB: TR
8:14:38.328: NIGPIBDD: ReceiveGPIB: 0,+2.12,0,-4.12
8:14:38.328: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.34 MHz, (Power) -4.12 dBm)
8:14:38.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) 2)
8:14:38.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) 7065.07)
8:14:38.359: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -13.1534 dBm)
8:14:38.359: NIGPIBDD: SaveSendGPIB function entered
8:14:38.375: NIGPIBDD: Assigning zero string to sCommand
8:14:38.375: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:38.375: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:38.375: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:38.390: NIGPIBDD: SendGPIB: SOURCE:POWER -13.1534 DBM;*OPC?

8:14:38.390: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:38.406: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:38.406: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:38.406: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:38.406: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:38.421: NIGPIBDD: ReceiveGPIB: 1

8:14:38.421: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:38.421: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:38.437: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:38.437: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:38.437: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:38.453: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:38.453: NIGPIBDD: Just before returning the error code
8:14:38.453: NIGPIBDD: SaveSendGPIB function entered

8:14:38.453: NIGPIBDD: Assigning zero string to sCommand
8:14:38.468: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:38.468: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:38.468: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:38.484: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:38.484: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:38.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:38.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:38.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:38.500: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:38.500: NIGPIBDD: Just before returning the error code
8:14:38.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -2.05654E+028)
8:14:38.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:38.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.546: NIGPIBDD: SendGPIB: TR
8:14:38.546: NIGPIBDD: ReceiveGPIB: 0,+2.01,0,-4.23
8:14:38.593: NIGPIBDD: SendGPIB: TR
8:14:38.593: NIGPIBDD: ReceiveGPIB: 0,+2.01,0,-4.23
8:14:38.609: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.34 MHz, (Power) 2.01 dBm)
8:14:38.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:38.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:38.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:38.625: NIGPIBDD: SendGPIB: TR
8:14:38.640: NIGPIBDD: ReceiveGPIB: 0,+2.01,0,-4.23
8:14:38.671: NIGPIBDD: SendGPIB: TR
8:14:38.687: NIGPIBDD: ReceiveGPIB: 0,+2.01,0,-4.23
8:14:38.687: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.34 MHz, (Power) -4.23 dBm)
8:14:38.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:14:38.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.32879E-033)
8:14:38.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:38.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:38.734: NIGPIBDD: SendGPIB: 1N
8:14:38.859: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:14:38.859: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.34 MHz, (Power) -150 dBm)

8:14:38.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:38.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 9.72066E+031)
8:14:38.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:40.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:40.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:40.875: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:40.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:40.890: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:40.937: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:40.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:40.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:40.953: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:40.953: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:40.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:40.968: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:40.984: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:40.984: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:41.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:41.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:41.015: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:41.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:41.031: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:41.046: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:41.046: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:41.062: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:41.062: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:41.062: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:41.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:41.078: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:41.093: NIGPIBDD: ReceiveGPIB: 53.908E+0

8:14:41.109: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.908)
8:14:41.109: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:41.109: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:41.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:41.156: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.171: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.171: NIGPIBDD: SendGPIO: TR
8:14:41.187: NIGPIBDD: ReceiveGPIO: 0,+2.01,0,-4.22
8:14:41.203: NIGPIBDD: SendGPIO: TR
8:14:41.218: NIGPIBDD: ReceiveGPIO: 0,+2.01,0,-4.22
8:14:41.234: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.34 MHz, (Power) 2.01 dBm)
8:14:41.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:41.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:41.250: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.250: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.265: NIGPIBDD: SendGPIO: TR
8:14:41.281: NIGPIBDD: ReceiveGPIO: 0,+2.01,0,-4.22
8:14:41.312: NIGPIBDD: SendGPIO: TR
8:14:41.328: NIGPIBDD: ReceiveGPIO: 0,+2.01,0,-4.22
8:14:41.328: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.34 MHz, (Power) -4.22 dBm)
8:14:41.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)
8:14:41.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.32879E-033)
8:14:41.359: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -13.5559 dBm)
8:14:41.359: NIGPIBDD: SaveSendGPIO function entered
8:14:41.359: NIGPIBDD: Assigning zero string to sCommand
8:14:41.375: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:41.375: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:41.390: NIGPIBDD::SaveSendGPIO: mlSuggestedReadSize: 0
8:14:41.390: NIGPIBDD: SendGPIO: SOURCE:POWER -13.5559 DBM;*OPC?

8:14:41.390: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:41.390: NIGPIBDD: After mcGPIOCommunication.Leave()
8:14:41.406: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:14:41.406: NIGPIBDD: After mcGPIOCommunication.Enter()
8:14:41.406: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Enter()
8:14:41.406: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:14:41.421: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Enter()
8:14:41.421: NIGPIBDD: After mcGPIOCommunication.Leave()

8:14:41.421: NIGPIBDD: ReceiveGPIB: 1

8:14:41.437: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:41.437: NIGPIBDD: Just before returning the error code
8:14:41.437: NIGPIBDD: SaveSendGPIB function entered
8:14:41.437: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:41.453: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:41.453: NIGPIBDD: Assigning zero string to sCommand
8:14:41.453: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:41.468: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:41.468: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:41.484: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:41.484: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:41.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:41.484: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:41.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:41.500: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:41.500: NIGPIBDD: Just before returning the error code
8:14:41.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 2928.45)
8:14:41.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:41.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.531: NIGPIBDD: SendGPIB: TR
8:14:41.546: NIGPIBDD: ReceiveGPIB: 0,+1.68,0,-4.61
8:14:41.578: NIGPIBDD: SendGPIB: TR
8:14:41.593: NIGPIBDD: ReceiveGPIB: 0,+1.60,0,-4.61
8:14:41.593: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.34 MHz, (Power) 1.6 dBm)
8:14:41.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:14:41.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:41.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.34 MHz, (Attenuation) 40 dB)
8:14:41.625: NIGPIBDD: SendGPIB: TR
8:14:41.640: NIGPIBDD: ReceiveGPIB: 0,+1.60,0,-4.61
8:14:41.671: NIGPIBDD: SendGPIB: TR
8:14:41.687: NIGPIBDD: ReceiveGPIB: 0,+1.60,0,-4.61
8:14:41.687: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.34 MHz, (Power) -4.61 dBm)
8:14:41.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:14:41.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.32879E-033)
8:14:41.703: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.37 MHz)

8:14:41.718: NIGPIBDD: SaveSendGPIB function entered
8:14:41.718: NIGPIBDD: Assigning zero string to sCommand
8:14:41.734: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:41.734: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:41.734: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:41.734: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.37 MHZ;*OPC?

8:14:41.750: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:41.750: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:41.765: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:41.765: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:41.765: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:41.765: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:41.781: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:41.781: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:41.781: NIGPIBDD: ReceiveGPIB: 1

8:14:41.781: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:41.781: NIGPIBDD: Just before returning the error code
8:14:41.796: NIGPIBDD: SaveSendGPIB function entered
8:14:41.796: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:41.812: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:41.812: NIGPIBDD: Assigning zero string to sCommand
8:14:41.812: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:41.828: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:41.828: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:41.843: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:41.843: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:41.843: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:41.843: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:41.859: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:41.859: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:41.859: NIGPIBDD: Just before returning the error code
8:14:41.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 5.8486E+035)
8:14:41.875: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:41.906: NIGPIBDD: ReceiveGPIB: NO

8:14:41.937: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:41.984: NIGPIBDD: ReceiveGPIB: NO

8:14:42.000: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:42.046: NIGPIBDD: ReceiveGPIB: NO

8:14:42.062: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:42.109: NIGPIBDD: ReceiveGPIB: NO

8:14:42.140: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:42.187: NIGPIBDD: ReceiveGPIO: NO

8:14:42.203: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:14:42.250: NIGPIBDD: ReceiveGPIO: NO

8:14:42.265: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:14:42.296: NIGPIBDD: ReceiveGPIO: NO

8:14:42.312: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:14:42.359: NIGPIBDD: ReceiveGPIO: NO

8:14:42.375: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?

8:14:42.421: NIGPIBDD: ReceiveGPIO: NC

8:14:42.437: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?

8:14:42.500: NIGPIBDD: ReceiveGPIO: NC

8:14:42.515: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?

8:14:42.546: NIGPIBDD: ReceiveGPIO: NC

8:14:42.578: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?

8:14:42.593: NIGPIBDD: ReceiveGPIO: NC

8:14:42.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:42.609: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)

8:14:42.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)

8:14:42.625: NIGPIBDD: SendGPIO: TR

8:14:42.640: NIGPIBDD: ReceiveGPIO: 0,+1.65,0,-4.60

8:14:42.671: NIGPIBDD: SendGPIO: TR

8:14:42.687: NIGPIBDD: ReceiveGPIO: 0,+1.65,0,-4.60

8:14:42.687: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.37 MHz, (Power) 1.65 dBm)

8:14:42.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:14:42.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:42.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)

8:14:42.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)

8:14:42.734: NIGPIBDD: SendGPIO: TR

8:14:42.750: NIGPIBDD: ReceiveGPIO: 0,+1.65,0,-4.60
8:14:42.781: NIGPIBDD: SendGPIO: TR
8:14:42.781: NIGPIBDD: ReceiveGPIO: 0,+1.65,0,-4.60
8:14:42.796: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.37 MHz, (Power) -4.6 dBm)
8:14:42.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:14:42.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -6.04472E+033)
8:14:42.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:42.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:42.843: NIGPIBDD: SendGPIO: 1N
8:14:43.015: NIGPIBDD: ReceiveGPIO: DBA+0000E+0,3,0

8:14:43.015: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.37 MHz, (Power) -150 dBm)
8:14:43.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:43.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.59283E-012)
8:14:43.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:45.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:45.062: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:45.062: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:45.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:45.078: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:14:45.109: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:14:45.109: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:45.109: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:45.109: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:45.125: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:45.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:45.140: NIGPIBDD: SendGPIO: :MEASU:MEAS2:VAL?

8:14:45.156: NIGPIBDD: ReceiveGPIO: 560.0E-3

8:14:45.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.56)
8:14:45.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:45.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:45.187: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:45.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:45.187: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:45.218: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:45.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:45.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:45.250: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:45.265: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:45.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:45.281: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:45.312: NIGPIBDD: ReceiveGPIB: 53.940E+0

8:14:45.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.94)
8:14:45.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:45.328: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:45.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:45.343: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.343: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.359: NIGPIBDD: SendGPIB: TR
8:14:45.375: NIGPIBDD: ReceiveGPIB: 0,+1.64,0,-4.60
8:14:45.406: NIGPIBDD: SendGPIB: TR
8:14:45.421: NIGPIBDD: ReceiveGPIB: 0,+1.64,0,-4.60
8:14:45.421: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.37 MHz, (Power) 1.64 dBm)
8:14:45.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:14:45.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:45.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.453: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.453: NIGPIBDD: SendGPIB: TR
8:14:45.468: NIGPIBDD: ReceiveGPIB: 0,+1.64,0,-4.60
8:14:45.500: NIGPIBDD: SendGPIB: TR
8:14:45.515: NIGPIBDD: ReceiveGPIB: 0,+1.64,0,-4.60
8:14:45.515: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.37 MHz, (Power) -4.6 dBm)
8:14:45.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)

8:14:45.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -6.04472E+033)
8:14:45.546: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -14.0535 dBm)
8:14:45.546: NIGPIBDD: SaveSendGPIB function entered
8:14:45.562: NIGPIBDD: Assigning zero string to sCommand
8:14:45.562: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:45.562: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:45.562: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:45.578: NIGPIBDD: SendGPIB: SOURCE:POWER -14.0535 DBM;*OPC?

8:14:45.578: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:45.593: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:45.593: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:45.593: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:45.593: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:45.609: NIGPIBDD: ReceiveGPIB: 1

8:14:45.609: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:45.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:45.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:45.625: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:45.625: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:45.640: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:45.640: NIGPIBDD: Just before returning the error code
8:14:45.640: NIGPIBDD: SaveSendGPIB function entered
8:14:45.640: NIGPIBDD: Assigning zero string to sCommand
8:14:45.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:45.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:45.671: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:45.671: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:45.671: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:45.671: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:45.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:45.687: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:45.687: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:45.687: NIGPIBDD: Just before returning the error code
8:14:45.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 5400.82)
8:14:45.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:45.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.734: NIGPIBDD: SendGPIB: TR
8:14:45.734: NIGPIBDD: ReceiveGPIB: 0,+1.26,0,-5.07
8:14:45.765: NIGPIBDD: SendGPIB: TR
8:14:45.781: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.07
8:14:45.781: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.37 MHz, (Power) 1.16 dBm)

8:14:45.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:45.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:45.796: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.37 MHz, (Attenuation) 40 dB)
8:14:45.812: NIGPIBDD: SendGPIB: TR
8:14:45.828: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.07
8:14:45.859: NIGPIBDD: SendGPIB: TR
8:14:45.875: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.07
8:14:45.875: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.37 MHz, (Power) -5.07 dBm)
8:14:45.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:14:45.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -6.04472E+033)
8:14:45.906: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.4 MHz)
8:14:45.906: NIGPIBDD: SaveSendGPIB function entered
8:14:45.906: NIGPIBDD: Assigning zero string to sCommand
8:14:45.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:45.921: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:45.921: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:45.937: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.4 MHZ;*OPC?

8:14:45.937: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:45.937: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:45.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:45.953: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:45.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:45.953: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:45.953: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:45.953: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:45.968: NIGPIBDD: Just before returning the error code
8:14:45.968: NIGPIBDD: ReceiveGPIB: 1

8:14:45.984: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:45.984: NIGPIBDD: SaveSendGPIB function entered
8:14:45.984: NIGPIBDD: Assigning zero string to sCommand
8:14:45.984: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:46.000: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:46.000: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:46.000: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:46.015: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:46.015: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:46.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:46.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:46.078: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:46.078: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:46.078: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:46.078: NIGPIBDD: Just before returning the error code
8:14:46.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
9.80909E-045, (Data2) -1.58819E-023)
8:14:46.093: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:46.125: NIGPIBDD: ReceiveGPIB: NO

8:14:46.140: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:46.187: NIGPIBDD: ReceiveGPIB: NO

8:14:46.203: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:46.250: NIGPIBDD: ReceiveGPIB: NO

8:14:46.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:46.312: NIGPIBDD: ReceiveGPIB: NO

8:14:46.343: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:46.375: NIGPIBDD: ReceiveGPIB: NO

8:14:46.406: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:46.421: NIGPIBDD: ReceiveGPIB: NO

8:14:46.453: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:46.484: NIGPIBDD: ReceiveGPIB: NO

8:14:46.500: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:46.546: NIGPIBDD: ReceiveGPIB: NO

8:14:46.578: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:46.609: NIGPIBDD: ReceiveGPIB: NC

8:14:46.625: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:46.656: NIGPIBDD: ReceiveGPIB: NC

8:14:46.687: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:46.718: NIGPIBDD: ReceiveGPIB: NC

8:14:46.750: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:46.781: NIGPIBDD: ReceiveGPIB: NC

8:14:46.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:46.796: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:46.796: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:46.812: NIGPIBDD: SendGPIB: TR
8:14:46.828: NIGPIBDD: ReceiveGPIB: 0,+1.17,0,-5.09
8:14:46.859: NIGPIBDD: SendGPIB: TR
8:14:46.875: NIGPIBDD: ReceiveGPIB: 0,+1.17,0,-5.09
8:14:46.875: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.4 MHz, (Power) 1.17 dBm)
8:14:46.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:14:46.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:46.890: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:46.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:46.906: NIGPIBDD: SendGPIB: TR
8:14:46.921: NIGPIBDD: ReceiveGPIB: 0,+1.17,0,-5.09
8:14:46.953: NIGPIBDD: SendGPIB: TR
8:14:46.968: NIGPIBDD: ReceiveGPIB: 0,+1.17,0,-5.09
8:14:46.968: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.4 MHz, (Power) -5.09 dBm)
8:14:46.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:46.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.18325E+016)
8:14:47.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:47.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:47.015: NIGPIBDD: SendGPIB: 1N
8:14:47.156: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:14:47.171: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.4 MHz, (Power) -150 dBm)
8:14:47.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:47.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 2.67953E+009)
8:14:47.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:49.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:49.187: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:49.187: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:49.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:49.203: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:49.234: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:49.234: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)

8:14:49.234: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)

8:14:49.250: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:49.250: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:49.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:49.265: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:49.281: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:49.281: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)

8:14:49.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)

8:14:49.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:49.296: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:49.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:49.312: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:49.343: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:49.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:14:49.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)

8:14:49.359: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:14:49.359: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:49.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:14:49.390: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:49.421: NIGPIBDD: ReceiveGPIB: 54.033E+0

8:14:49.421: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 54.033)

8:14:49.437: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)

8:14:49.437: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)

8:14:49.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:49.453: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)

8:14:49.453: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)

8:14:49.468: NIGPIBDD: SendGPIB: TR

8:14:49.484: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.09

8:14:49.500: NIGPIBDD: SendGPIB: TR
8:14:49.515: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.09
8:14:49.515: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.4 MHz, (Power) 1.16 dBm)
8:14:49.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:49.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:49.546: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:49.546: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:49.562: NIGPIBDD: SendGPIB: TR
8:14:49.562: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.09
8:14:49.593: NIGPIBDD: SendGPIB: TR
8:14:49.609: NIGPIBDD: ReceiveGPIB: 0,+1.16,0,-5.09
8:14:49.625: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.4 MHz, (Power) -5.09 dBm)
8:14:49.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:49.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.18325E+016)
8:14:49.640: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -14.3414 dBm)
8:14:49.656: NIGPIBDD: SaveSendGPIB function entered
8:14:49.656: NIGPIBDD: Assigning zero string to sCommand
8:14:49.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:49.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:49.671: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:49.671: NIGPIBDD: SendGPIB: SOURCE:POWER -14.3414 DBM;*OPC?

8:14:49.687: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:49.687: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:49.687: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:49.687: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:49.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:49.703: NIGPIBDD: ReceiveGPIB: 1

8:14:49.703: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:49.718: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:49.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:49.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:49.718: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:49.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:49.734: NIGPIBDD: Just before returning the error code
8:14:49.734: NIGPIBDD: SaveSendGPIB function entered
8:14:49.750: NIGPIBDD: Assigning zero string to sCommand
8:14:49.750: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:49.750: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:49.765: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:49.765: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:49.765: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:49.781: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:49.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:49.781: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:49.781: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:49.796: NIGPIBDD: Just before returning the error code
8:14:49.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -1.96292E-019)
8:14:49.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:49.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:49.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:49.828: NIGPIBDD: SendGPIB: TR
8:14:49.843: NIGPIBDD: ReceiveGPIB: 0,+0.87,0,-5.38
8:14:49.875: NIGPIBDD: SendGPIB: TR
8:14:49.890: NIGPIBDD: ReceiveGPIB: 0,+0.87,0,-5.38
8:14:49.890: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.4 MHz, (Power) 0.87 dBm)
8:14:49.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)
8:14:49.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:49.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:49.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.4 MHz, (Attenuation) 40 dB)
8:14:49.921: NIGPIBDD: SendGPIB: TR
8:14:49.921: NIGPIBDD: ReceiveGPIB: 0,+0.87,0,-5.38
8:14:49.968: NIGPIBDD: SendGPIB: TR
8:14:49.968: NIGPIBDD: ReceiveGPIB: 0,+0.87,0,-5.38
8:14:49.984: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.4 MHz, (Power) -5.38 dBm)
8:14:49.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:49.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.18325E+016)
8:14:50.000: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.43 MHz)
8:14:50.000: NIGPIBDD: SaveSendGPIB function entered
8:14:50.000: NIGPIBDD: Assigning zero string to sCommand
8:14:50.015: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:50.015: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:50.031: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:50.031: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.43 MHZ,*OPC?

8:14:50.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:50.031: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:50.046: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:50.046: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:50.046: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:50.062: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:50.062: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:50.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:50.062: NIGPIBDD: ReceiveGPIB: 1

8:14:50.078: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:50.078: NIGPIBDD: Just before returning the error code
8:14:50.078: NIGPIBDD: SaveSendGPIB function entered
8:14:50.078: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:50.093: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:50.093: NIGPIBDD: Assigning zero string to sCommand
8:14:50.093: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:50.109: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:50.109: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:14:50.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:50.125: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:50.125: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:50.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:50.140: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:50.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:50.140: NIGPIBDD: Just before returning the error code
8:14:50.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -5.00488E-005)
8:14:50.156: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:50.203: NIGPIBDD: ReceiveGPIB: NO

8:14:50.218: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:50.250: NIGPIBDD: ReceiveGPIB: NO

8:14:50.281: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:50.296: NIGPIBDD: ReceiveGPIB: NO

8:14:50.328: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:50.375: NIGPIBDD: ReceiveGPIB: NO

8:14:50.390: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:50.437: NIGPIBDD: ReceiveGPIB: NO

8:14:50.453: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:50.484: NIGPIBDD: ReceiveGPIB: NO

8:14:50.515: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:50.546: NIGPIBDD: ReceiveGPIB: NO

8:14:50.562: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:50.609: NIGPIBDD: ReceiveGPIO: NO
 8:14:50.625: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?
 8:14:50.687: NIGPIBDD: ReceiveGPIO: NC
 8:14:50.718: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?
 8:14:50.765: NIGPIBDD: ReceiveGPIO: NC
 8:14:50.781: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?
 8:14:50.828: NIGPIBDD: ReceiveGPIO: NC
 8:14:50.843: NIGPIBDD: SendGPIO: S4:INT_RELAY_A?
 8:14:50.890: NIGPIBDD: ReceiveGPIO: NC
 8:14:50.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:14:50.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:50.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:50.921: NIGPIBDD: SendGPIO: TR
 8:14:50.937: NIGPIBDD: ReceiveGPIO: 0,+0.90,0,-5.38
 8:14:50.968: NIGPIBDD: SendGPIO: TR
 8:14:50.984: NIGPIBDD: ReceiveGPIO: 0,+0.90,0,-5.38
 8:14:50.984: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.43 MHz, (Power) 0.9 dBm)
 8:14:50.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
 8:14:51.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
 8:14:51.000: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:51.000: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:51.015: NIGPIBDD: SendGPIO: TR
 8:14:51.015: NIGPIBDD: ReceiveGPIO: 0,+0.90,0,-5.38
 8:14:51.062: NIGPIBDD: SendGPIO: TR
 8:14:51.062: NIGPIBDD: ReceiveGPIO: 0,+0.90,0,-5.38
 8:14:51.078: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.43 MHz, (Power) -5.38 dBm)
 8:14:51.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
 8:14:51.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -0.0126966)
 8:14:51.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
 8:14:51.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:14:51.109: NIGPIBDD: SendGPIB: 1N
8:14:51.265: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:14:51.265: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.43 MHz, (Power) -150 dBm)
8:14:51.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:51.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -8.97461E+007)
8:14:51.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:53.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:53.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:53.296: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:53.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:53.312: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:53.343: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:53.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:53.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:53.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:53.359: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:53.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:53.375: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:53.390: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:53.406: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:53.406: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:53.406: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:53.406: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:53.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:53.421: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:53.453: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:53.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:53.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:53.484: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:53.500: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:14:53.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:53.500: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:53.531: NIGPIBDD: ReceiveGPIB: 54.123E+0

8:14:53.546: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 54.123)
8:14:53.546: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:53.546: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:53.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:53.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
8:14:53.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
8:14:53.578: NIGPIBDD: SendGPIB: TR
8:14:53.593: NIGPIBDD: ReceiveGPIB: 0,+0.90,0,-5.38
8:14:53.625: NIGPIBDD: SendGPIB: TR
8:14:53.640: NIGPIBDD: ReceiveGPIB: 0,+0.90,0,-5.38
8:14:53.640: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.43 MHz, (Power) 0.9 dBm)
8:14:53.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
8:14:53.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:53.656: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
8:14:53.671: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
8:14:53.671: NIGPIBDD: SendGPIB: TR
8:14:53.687: NIGPIBDD: ReceiveGPIB: 0,+0.90,0,-5.38
8:14:53.718: NIGPIBDD: SendGPIB: TR
8:14:53.734: NIGPIBDD: ReceiveGPIB: 0,+0.90,0,-5.38
8:14:53.734: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.43 MHz, (Power) -5.38 dBm)
8:14:53.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:53.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -0.0126966)
8:14:53.765: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -14.6718 dBm)
8:14:53.765: NIGPIBDD: SaveSendGPIB function entered
8:14:53.765: NIGPIBDD: Assigning zero string to sCommand
8:14:53.765: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:53.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:53.781: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:14:53.781: NIGPIBDD: SendGPIB: SOURCE:POWER -14.6718 DBM;*OPC?

8:14:53.781: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:53.796: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:53.796: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:53.796: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
 8:14:53.812: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
 8:14:53.828: NIGPIBDD: ReceiveGPIB: 1

 8:14:53.828: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:14:53.828: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:14:53.828: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:53.828: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:14:53.843: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:53.843: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:53.843: NIGPIBDD: Just before returning the error code
 8:14:53.859: NIGPIBDD: SaveSendGPIB function entered
 8:14:53.859: NIGPIBDD: Assigning zero string to sCommand
 8:14:53.875: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:53.875: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:53.875: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
 8:14:53.875: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:53.890: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:53.890: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:53.890: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:53.890: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:53.906: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:53.906: NIGPIBDD: Just before returning the error code
 8:14:53.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 8.74579E-006)
 8:14:53.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:14:53.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:53.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:53.937: NIGPIBDD: SendGPIB: TR
 8:14:53.953: NIGPIBDD: ReceiveGPIB: 0,+0.60,0,-5.68
 8:14:53.984: NIGPIBDD: SendGPIB: TR
 8:14:53.984: NIGPIBDD: ReceiveGPIB: 0,+0.58,0,-5.69
 8:14:54.000: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.43 MHz, (Power) 0.58 dBm)
 8:14:54.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
 8:14:54.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
 8:14:54.015: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:54.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.43 MHz, (Attenuation) 40 dB)
 8:14:54.031: NIGPIBDD: SendGPIB: TR
 8:14:54.046: NIGPIBDD: ReceiveGPIB: 0,+0.58,0,-5.70
 8:14:54.062: NIGPIBDD: SendGPIB: TR
 8:14:54.078: NIGPIBDD: ReceiveGPIB: 0,+0.57,0,-5.70
 8:14:54.078: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.43 MHz, (Power) -5.7 dBm)

8:14:54.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:14:54.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -0.0126966)
8:14:54.109: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.46 MHz)
8:14:54.109: NIGPIBDD: SaveSendGPIB function entered
8:14:54.125: NIGPIBDD: Assigning zero string to sCommand
8:14:54.125: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:54.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:54.125: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:54.140: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.46 MHZ,*OPC?

8:14:54.140: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:54.156: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:54.156: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:54.156: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:54.156: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:54.171: NIGPIBDD: ReceiveGPIB: 1

8:14:54.171: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:54.187: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:54.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:54.187: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:54.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:54.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:54.203: NIGPIBDD: Just before returning the error code
8:14:54.203: NIGPIBDD: SaveSendGPIB function entered
8:14:54.203: NIGPIBDD: Assigning zero string to sCommand
8:14:54.218: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:54.218: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:54.234: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:54.234: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:54.234: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:54.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:54.250: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:54.250: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:54.250: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:54.250: NIGPIBDD: Just before returning the error code
8:14:54.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -1.51997E+014)
8:14:54.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:54.328: NIGPIBDD: ReceiveGPIB: NO

8:14:54.343: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:54.390: NIGPIBDD: ReceiveGPIB: NO

8:14:54.406: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:54.437: NIGPIBDD: ReceiveGPIB: NO

8:14:54.453: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?
8:14:54.500: NIGPIBDD: ReceiveGPIB: NO
8:14:54.531: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:54.578: NIGPIBDD: ReceiveGPIB: NO
8:14:54.593: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:54.625: NIGPIBDD: ReceiveGPIB: NO
8:14:54.640: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:54.671: NIGPIBDD: ReceiveGPIB: NO
8:14:54.703: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:14:54.734: NIGPIBDD: ReceiveGPIB: NO
8:14:54.765: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:54.828: NIGPIBDD: ReceiveGPIB: NC
8:14:54.843: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:54.890: NIGPIBDD: ReceiveGPIB: NC
8:14:54.906: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:54.953: NIGPIBDD: ReceiveGPIB: NC
8:14:54.984: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:14:55.031: NIGPIBDD: ReceiveGPIB: NC

8:14:55.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:55.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:55.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:55.046: NIGPIBDD: SendGPIB: TR
8:14:55.062: NIGPIBDD: ReceiveGPIB: 0,+0.60,0,-5.71
8:14:55.093: NIGPIBDD: SendGPIB: TR
8:14:55.109: NIGPIBDD: ReceiveGPIB: 0,+0.60,0,-5.71
8:14:55.109: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.46 MHz, (Power) 0.6 dBm)
8:14:55.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)

8:14:55.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:55.125: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:55.140: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:55.140: NIGPIBDD: SendGPIB: TR
8:14:55.156: NIGPIBDD: ReceiveGPIB: 0,+0.60,0,-5.71
8:14:55.187: NIGPIBDD: SendGPIB: TR
8:14:55.203: NIGPIBDD: ReceiveGPIB: 0,+0.60,0,-5.71
8:14:55.203: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.46 MHz, (Power) -5.71 dBm)
8:14:55.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:55.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -0.000172653)
8:14:55.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:14:55.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:14:55.250: NIGPIBDD: SendGPIB: 1N
8:14:55.421: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:14:55.437: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.46 MHz, (Power) -150 dBm)
8:14:55.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:14:55.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.61228E-033)
8:14:55.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:14:57.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:14:57.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:57.453: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:57.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:57.468: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:14:57.500: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:14:57.500: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:14:57.500: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:14:57.515: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:57.515: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:57.531: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:57.531: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:14:57.546: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:14:57.546: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:14:57.562: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:14:57.562: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:57.562: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:57.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:57.578: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:14:57.609: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:14:57.609: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:14:57.609: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:14:57.656: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:14:57.656: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:14:57.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:14:57.671: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:14:57.687: NIGPIBDD: ReceiveGPIB: 53.973E+0

8:14:57.687: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.973)
8:14:57.703: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:14:57.703: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:14:57.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:57.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:57.734: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:57.734: NIGPIBDD: SendGPIB: TR
8:14:57.750: NIGPIBDD: ReceiveGPIB: 0,+0.59,0,-5.71
8:14:57.765: NIGPIBDD: SendGPIB: TR
8:14:57.781: NIGPIBDD: ReceiveGPIB: 0,+0.59,0,-5.71
8:14:57.781: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.46 MHz, (Power) 0.59 dBm)
8:14:57.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:14:57.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:57.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:57.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:57.828: NIGPIBDD: SendGPIB: TR
8:14:57.828: NIGPIBDD: ReceiveGPIB: 0,+0.59,0,-5.71

8:14:57.859: NIGPIBDD: SendGPIB: TR
8:14:57.875: NIGPIBDD: ReceiveGPIB: 0,+0.59,0,-5.71
8:14:57.875: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.46 MHz, (Power) -5.71 dBm)
8:14:57.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:14:57.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -0.000172653)
8:14:57.906: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15.0316 dBm)
8:14:57.906: NIGPIBDD: SaveSendGPIB function entered
8:14:57.906: NIGPIBDD: Assigning zero string to sCommand
8:14:57.921: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:57.921: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:57.937: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:57.937: NIGPIBDD: SendGPIB: SOURCE:POWER -15.0316 DBM;*OPC?

8:14:57.937: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:57.937: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:57.953: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:57.953: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:57.953: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:57.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:57.968: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:57.968: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:57.968: NIGPIBDD: ReceiveGPIB: 1

8:14:57.984: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:57.984: NIGPIBDD: Just before returning the error code
8:14:57.984: NIGPIBDD: SaveSendGPIB function entered
8:14:57.984: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:58.000: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:58.000: NIGPIBDD: Assigning zero string to sCommand
8:14:58.000: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:58.015: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:58.015: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:58.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:58.031: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:58.031: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:58.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:58.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:58.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:58.046: NIGPIBDD: Just before returning the error code
8:14:58.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -0.00704228)
8:14:58.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:14:58.062: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:58.078: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:58.078: NIGPIBDD: SendGPIB: TR

8:14:58.093: NIGPIBDD: ReceiveGPIB: 0,+0.16,0,-6.12
8:14:58.125: NIGPIBDD: SendGPIB: TR
8:14:58.140: NIGPIBDD: ReceiveGPIB: 0,+0.14,0,-6.15
8:14:58.140: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.46 MHz, (Power) 0.14 dBm)
8:14:58.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:14:58.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:14:58.156: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:58.156: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.46 MHz, (Attenuation) 40 dB)
8:14:58.171: NIGPIBDD: SendGPIB: TR
8:14:58.187: NIGPIBDD: ReceiveGPIB: 0,+0.11,0,-6.15
8:14:58.218: NIGPIBDD: SendGPIB: TR
8:14:58.218: NIGPIBDD: ReceiveGPIB: 0,+0.11,0,-6.16
8:14:58.234: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.46 MHz, (Power) -6.16 dBm)
8:14:58.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:14:58.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -0.000172653)
8:14:58.250: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.49 MHz)
8:14:58.265: NIGPIBDD: SaveSendGPIB function entered
8:14:58.265: NIGPIBDD: Assigning zero string to sCommand
8:14:58.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:58.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:58.281: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:14:58.281: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.49 MHZ;*OPC?

8:14:58.296: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:58.296: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:58.296: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:58.296: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:58.312: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:14:58.312: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:58.312: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:14:58.312: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:58.328: NIGPIBDD: ReceiveGPIB: 1

8:14:58.328: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:14:58.328: NIGPIBDD: Just before returning the error code
8:14:58.343: NIGPIBDD: SaveSendGPIB function entered
8:14:58.343: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:14:58.343: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:14:58.343: NIGPIBDD: Assigning zero string to sCommand
8:14:58.359: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:58.359: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:58.359: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:14:58.375: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:58.375: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:58.390: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:14:58.390: NIGPIBDD: After mcGPIBCommunication.Enter()
8:14:58.390: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:14:58.390: NIGPIBDD: After mcGPIBCommunication.Leave()
8:14:58.406: NIGPIBDD: Just before returning the error code
8:14:58.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -4.93268E+032)
8:14:58.421: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:58.453: NIGPIBDD: ReceiveGPIB: NO

8:14:58.484: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:58.515: NIGPIBDD: ReceiveGPIB: NO

8:14:58.546: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:58.562: NIGPIBDD: ReceiveGPIB: NO

8:14:58.593: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:14:58.640: NIGPIBDD: ReceiveGPIB: NO

8:14:58.656: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:58.703: NIGPIBDD: ReceiveGPIB: NO

8:14:58.718: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:58.750: NIGPIBDD: ReceiveGPIB: NO

8:14:58.781: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:58.812: NIGPIBDD: ReceiveGPIB: NO

8:14:58.828: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:14:58.875: NIGPIBDD: ReceiveGPIB: NO

8:14:58.890: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:58.953: NIGPIBDD: ReceiveGPIB: NC

8:14:58.984: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:59.031: NIGPIBDD: ReceiveGPIB: NC

8:14:59.046: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:59.093: NIGPIBDD: ReceiveGPIB: NC

8:14:59.109: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:14:59.156: NIGPIBDD: ReceiveGPIB: NC

8:14:59.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:14:59.171: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:14:59.187: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:14:59.187: NIGPIBDD: SendGPIB: TR

8:14:59.203: NIGPIBDD: ReceiveGPIB: 0,+0.13,0,-6.17

8:14:59.234: NIGPIBDD: SendGPIB: TR

8:14:59.250: NIGPIBDD: ReceiveGPIB: 0,+0.13,0,-6.17

8:14:59.250: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.49 MHz, (Power) 0.13 dBm)

8:14:59.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)

8:14:59.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:14:59.265: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:14:59.281: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:14:59.281: NIGPIBDD: SendGPIB: TR

8:14:59.296: NIGPIBDD: ReceiveGPIB: 0,+0.13,0,-6.17

8:14:59.328: NIGPIBDD: SendGPIB: TR

8:14:59.343: NIGPIBDD: ReceiveGPIB: 0,+0.13,0,-6.17

8:14:59.359: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.49 MHz, (Power) -6.17 dBm)

8:14:59.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)

8:14:59.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 5.12571E-038)

8:14:59.390: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -14.9314 dBm)

8:14:59.390: NIGPIBDD: SaveSendGPIB function entered

8:14:59.390: NIGPIBDD: Assigning zero string to sCommand

8:14:59.406: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:59.406: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:59.421: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0

8:14:59.421: NIGPIBDD: SendGPIB: SOURCE:POWER -14.9314 DBM;*OPC?

8:14:59.437: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:59.437: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:59.453: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:14:59.453: NIGPIBDD: After mcGPIBCommunication.Enter()

8:14:59.437: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:14:59.453: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:14:59.468: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:14:59.468: NIGPIBDD: After mcGPIBCommunication.Leave()

8:14:59.468: NIGPIBDD: ReceiveGPIB: 1

8:14:59.484: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:14:59.484: NIGPIBDD: Just before returning the error code
 8:14:59.500: NIGPIBDD: SaveSendGPIB function entered
 8:14:59.500: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:14:59.500: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:14:59.500: NIGPIBDD: Assigning zero string to sCommand
 8:14:59.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:59.531: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:59.531: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
 8:14:59.531: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:59.531: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:59.546: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:14:59.546: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:14:59.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:14:59.546: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:14:59.562: NIGPIBDD: Just before returning the error code
 8:14:59.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 5.06304E-018)
 8:14:59.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
 8:14:59.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
 8:14:59.593: NIGPIBDD: SendGPIB: 1N
 8:14:59.718: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

 8:14:59.718: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.49 MHz, (Power) -150 dBm)
 8:14:59.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
 8:14:59.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 129.159)
 8:14:59.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
 8:15:01.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
 8:15:01.734: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
 8:15:01.734: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
 8:15:01.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
 8:15:01.750: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

 8:15:01.781: NIGPIBDD: ReceiveGPIB: 3.70E+0

 8:15:01.781: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
 8:15:01.781: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
 8:15:01.828: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
 8:15:01.828: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
 8:15:01.828: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:15:01.843: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:01.859: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:01.859: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)

8:15:01.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)

8:15:01.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:15:01.875: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:15:01.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:15:01.890: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:01.921: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:01.921: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:15:01.921: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)

8:15:01.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:15:01.937: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:15:01.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:15:01.953: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:01.968: NIGPIBDD: ReceiveGPIB: 53.448E+0

8:15:01.968: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.448)

8:15:01.984: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)

8:15:01.984: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)

8:15:02.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:02.000: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:15:02.015: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:15:02.015: NIGPIBDD: SendGPIB: TR

8:15:02.031: NIGPIBDD: ReceiveGPIB: 0,+0.36,0,-5.97

8:15:02.046: NIGPIBDD: SendGPIB: TR

8:15:02.062: NIGPIBDD: ReceiveGPIB: 0,+0.36,0,-5.97

8:15:02.078: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.49 MHz, (Power) 0.36 dBm)

8:15:02.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)

8:15:02.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:02.093: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)

8:15:02.093: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)
8:15:02.109: NIGPIBDD: SendGPIB: TR
8:15:02.109: NIGPIBDD: ReceiveGPIB: 0,+0.36,0,-5.97
8:15:02.156: NIGPIBDD: SendGPIB: TR
8:15:02.156: NIGPIBDD: ReceiveGPIB: 0,+0.36,0,-5.97
8:15:02.171: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.49 MHz, (Power) -5.97 dBm)
8:15:02.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)
8:15:02.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 5.12571E-038)
8:15:02.187: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15.3174 dBm)
8:15:02.187: NIGPIBDD: SaveSendGPIB function entered
8:15:02.187: NIGPIBDD: Assigning zero string to sCommand
8:15:02.203: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:02.203: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:02.218: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:02.218: NIGPIBDD: SendGPIB: SOURCE:POWER -15.3174 DBM;*OPC?

8:15:02.218: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:02.218: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:02.234: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:02.234: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:02.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:02.250: NIGPIBDD: ReceiveGPIB: 1

8:15:02.250: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:02.250: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:02.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:02.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:02.265: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:02.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:02.281: NIGPIBDD: Just before returning the error code
8:15:02.281: NIGPIBDD: SaveSendGPIB function entered
8:15:02.296: NIGPIBDD: Assigning zero string to sCommand
8:15:02.296: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:02.296: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:02.296: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:02.312: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:02.312: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:02.312: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:02.312: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:02.328: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:02.328: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:02.343: NIGPIBDD: Just before returning the error code
8:15:02.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 5.08955E+019)
8:15:08.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:08.546: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)
8:15:08.562: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)
8:15:08.562: NIGPIBDD: SendGPIB: TR
8:15:08.578: NIGPIBDD: ReceiveGPIB: 0,-0.16,0,-6.45
8:15:08.609: NIGPIBDD: SendGPIB: TR
8:15:08.625: NIGPIBDD: ReceiveGPIB: 0,-0.16,0,-6.45
8:15:08.625: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.49 MHz, (Power) -0.16 dBm)
8:15:08.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) 2)
8:15:08.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)
8:15:08.640: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)
8:15:08.640: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.49 MHz, (Attenuation) 40 dB)
8:15:08.656: NIGPIBDD: SendGPIB: TR
8:15:08.671: NIGPIBDD: ReceiveGPIB: 0,-0.16,0,-6.45
8:15:08.703: NIGPIBDD: SendGPIB: TR
8:15:08.703: NIGPIBDD: ReceiveGPIB: 0,-0.16,0,-6.45
8:15:08.718: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.49 MHz, (Power) -6.45 dBm)
8:15:08.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) -2)
8:15:08.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) 5.12571E-038)
8:15:08.734: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency,
(Frequency) 0.52 MHz)
8:15:08.750: NIGPIBDD: SaveSendGPIB function entered
8:15:08.750: NIGPIBDD: Assigning zero string to sCommand
8:15:08.750: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:08.750: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:08.765: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:15:08.765: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.52 MHZ,*OPC?

8:15:08.781: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:08.781: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:08.781: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:08.781: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:08.781: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:08.796: NIGPIBDD: ReceiveGPIB: 1

8:15:08.812: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:08.812: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:08.812: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:08.812: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:08.812: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:08.828: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:08.828: NIGPIBDD: Just before returning the error code
8:15:08.828: NIGPIBDD: SaveSendGPIB function entered

8:15:08.843: NIGPIBDD: Assigning zero string to sCommand
8:15:08.843: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:08.859: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:08.859: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:08.859: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:08.859: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:08.875: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:08.875: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:08.875: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:08.875: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:08.890: NIGPIBDD: Just before returning the error code
8:15:08.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
9.80909E-045, (Data2) 9.12121E-033)
8:15:08.906: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:08.937: NIGPIBDD: ReceiveGPIB: NO

8:15:08.953: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:09.000: NIGPIBDD: ReceiveGPIB: NO

8:15:09.015: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:09.046: NIGPIBDD: ReceiveGPIB: NO

8:15:09.062: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:09.093: NIGPIBDD: ReceiveGPIB: NO

8:15:09.109: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:09.156: NIGPIBDD: ReceiveGPIB: NO

8:15:09.171: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:09.218: NIGPIBDD: ReceiveGPIB: NO

8:15:09.250: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:09.281: NIGPIBDD: ReceiveGPIB: NO

8:15:09.296: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:09.328: NIGPIBDD: ReceiveGPIB: NO

8:15:09.359: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:09.390: NIGPIBDD: ReceiveGPIB: NC

8:15:09.406: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:09.453: NIGPIBDD: ReceiveGPIB: NC

8:15:09.484: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:09.515: NIGPIBDD: ReceiveGPIB: NC

8:15:09.546: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:09.562: NIGPIBDD: ReceiveGPIB: NC

8:15:09.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:09.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)

8:15:09.593: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)

8:15:09.593: NIGPIBDD: SendGPIB: TR

8:15:09.609: NIGPIBDD: ReceiveGPIB: 0,-0.15,0,-6.46

8:15:09.640: NIGPIBDD: SendGPIB: TR

8:15:09.656: NIGPIBDD: ReceiveGPIB: 0,-0.14,0,-6.46

8:15:09.656: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.52 MHz, (Power) -0.14 dBm)

8:15:09.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)

8:15:09.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:09.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)

8:15:09.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)

8:15:09.687: NIGPIBDD: SendGPIB: TR

8:15:09.703: NIGPIBDD: ReceiveGPIB: 0,-0.14,0,-6.47

8:15:09.734: NIGPIBDD: SendGPIB: TR

8:15:09.734: NIGPIBDD: ReceiveGPIB: 0,-0.14,0,-6.47

8:15:09.750: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.52 MHz, (Power) -6.47 dBm)

8:15:09.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)

8:15:09.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.63073E-009)

8:15:09.765: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15.2034 dBm)

8:15:09.781: NIGPIBDD: SaveSendGPIB function entered

8:15:09.781: NIGPIBDD: Assigning zero string to sCommand

8:15:09.796: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:09.796: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:09.796: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:15:09.796: NIGPIBDD: SendGPIB: SOURCE:POWER -15.2034 DBM;*OPC?

8:15:09.812: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:09.812: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:09.812: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:15:09.812: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:15:09.828: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:15:09.828: NIGPIBDD: ReceiveGPIB: 1

 8:15:09.843: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:15:09.843: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:15:09.843: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:15:09.843: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:15:09.843: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:15:09.859: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:15:09.875: NIGPIBDD: Just before returning the error code
 8:15:09.875: NIGPIBDD: SaveSendGPIB function entered
 8:15:09.875: NIGPIBDD: Assigning zero string to sCommand
 8:15:09.875: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:15:09.890: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:15:09.890: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
 8:15:09.890: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:15:09.890: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:15:09.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:15:09.906: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:15:09.921: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:15:09.921: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:15:09.921: NIGPIBDD: Just before returning the error code
 8:15:09.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -2.20182E-021)
 8:15:09.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
 8:15:09.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
 8:15:09.968: NIGPIBDD: SendGPIB: 1N
 8:15:10.078: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

 8:15:10.078: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.52 MHz, (Power) -150 dBm)
 8:15:10.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
 8:15:10.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -4.26539E+030)
 8:15:10.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
 8:15:12.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
 8:15:12.093: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
 8:15:12.093: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
 8:15:12.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
 8:15:12.125: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

 8:15:12.171: NIGPIBDD: ReceiveGPIB: 3.70E+0

 8:15:12.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)

8:15:12.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:12.187: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:12.187: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:12.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:12.203: NIGPIBDD: SendGPIOB: :MEASU:MEAS2:VAL?

8:15:12.218: NIGPIBDD: ReceiveGPIOB: 580.0E-3

8:15:12.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:15:12.234: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:12.234: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:12.250: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:12.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:12.250: NIGPIBDD: SendGPIOB: :MEASU:MEAS3:VAL?

8:15:12.281: NIGPIBDD: ReceiveGPIOB: 200.0E-3

8:15:12.281: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:15:12.281: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:12.296: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:12.296: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:12.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:12.312: NIGPIBDD: SendGPIOB: :MEASU:MEAS4:VAL?

8:15:12.343: NIGPIBDD: ReceiveGPIOB: 53.153E+0

8:15:12.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.153)
8:15:12.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:15:12.343: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:12.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:12.375: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.375: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.375: NIGPIBDD: SendGPIOB: TR
8:15:12.390: NIGPIBDD: ReceiveGPIOB: 0,-0.03,0,-6.36
8:15:12.421: NIGPIBDD: SendGPIOB: TR
8:15:12.437: NIGPIBDD: ReceiveGPIOB: 0,-0.03,0,-6.36
8:15:12.437: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.52 MHz, (Power) -0.03 dBm)

8:15:12.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:15:12.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:12.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.468: NIGPIBDD: SendGPIB: TR
8:15:12.484: NIGPIBDD: ReceiveGPIB: 0,-0.03,0,-6.36
8:15:12.515: NIGPIBDD: SendGPIB: TR
8:15:12.531: NIGPIBDD: ReceiveGPIB: 0,-0.03,0,-6.36
8:15:12.531: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.52 MHz, (Power) -6.36 dBm)
8:15:12.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:15:12.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.63073E-009)
8:15:12.562: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15.4376 dBm)
8:15:12.562: NIGPIBDD: SaveSendGPIB function entered
8:15:12.562: NIGPIBDD: Assigning zero string to sCommand
8:15:12.578: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:12.578: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:12.578: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:12.593: NIGPIBDD: SendGPIB: SOURCE:POWER -15.4376 DBM;*OPC?

8:15:12.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:12.593: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:12.609: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:12.609: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:12.609: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:12.609: NIGPIBDD: ReceiveGPIB: 1

8:15:12.625: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:12.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:12.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:12.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:12.640: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:12.640: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:12.656: NIGPIBDD: Just before returning the error code
8:15:12.656: NIGPIBDD: SaveSendGPIB function entered
8:15:12.656: NIGPIBDD: Assigning zero string to sCommand
8:15:12.656: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:12.671: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:12.671: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:12.687: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:12.687: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:12.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:12.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:12.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:12.703: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:12.703: NIGPIBDD: Just before returning the error code
8:15:12.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -5.33419E+033)
8:15:12.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:12.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.734: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.734: NIGPIBDD: SendGPIB: TR
8:15:12.750: NIGPIBDD: ReceiveGPIB: 0,-0.26,0,-6.59
8:15:12.781: NIGPIBDD: SendGPIB: TR
8:15:12.796: NIGPIBDD: ReceiveGPIB: 0,-0.27,0,-6.59
8:15:12.796: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.52 MHz, (Power) -0.27 dBm)
8:15:12.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:15:12.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:12.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.52 MHz, (Attenuation) 40 dB)
8:15:12.828: NIGPIBDD: SendGPIB: TR
8:15:12.843: NIGPIBDD: ReceiveGPIB: 0,-0.27,0,-6.59
8:15:12.875: NIGPIBDD: SendGPIB: TR
8:15:12.875: NIGPIBDD: ReceiveGPIB: 0,-0.27,0,-6.59
8:15:12.890: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.52 MHz, (Power) -6.59 dBm)
8:15:12.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:12.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.63073E-009)
8:15:12.906: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.55 MHz)
8:15:12.921: NIGPIBDD: SaveSendGPIB function entered
8:15:12.921: NIGPIBDD: Assigning zero string to sCommand
8:15:12.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:12.937: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:12.937: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:12.937: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.55 MHZ;*OPC?

8:15:12.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:12.953: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:12.953: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:12.953: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:12.968: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:12.968: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:12.984: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:12.984: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:12.984: NIGPIBDD: ReceiveGPIB: 1

8:15:12.984: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:12.984: NIGPIBDD: Just before returning the error code
8:15:13.000: NIGPIBDD: SaveSendGPIB function entered
8:15:13.000: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:13.000: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:13.000: NIGPIBDD: Assigning zero string to sCommand
8:15:13.015: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:13.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:13.031: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:13.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:13.031: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:13.046: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:13.046: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:13.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:13.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:13.062: NIGPIBDD: Just before returning the error code
8:15:13.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
9.80909E-045, (Data2) -1.58819E-023)
8:15:13.078: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:13.140: NIGPIBDD: ReceiveGPIB: NO

8:15:13.156: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:13.187: NIGPIBDD: ReceiveGPIB: NO

8:15:13.203: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:13.250: NIGPIBDD: ReceiveGPIB: NO

8:15:13.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:13.312: NIGPIBDD: ReceiveGPIB: NO

8:15:13.343: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:13.390: NIGPIBDD: ReceiveGPIB: NO

8:15:13.421: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:13.437: NIGPIBDD: ReceiveGPIB: NO

8:15:13.468: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:13.500: NIGPIBDD: ReceiveGPIB: NO

8:15:13.515: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:13.562: NIGPIBDD: ReceiveGPIB: NO

8:15:13.578: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:13.625: NIGPIBDD: ReceiveGPIB: NC

8:15:13.640: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:13.687: NIGPIBDD: ReceiveGPIB: NC

8:15:13.703: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:13.734: NIGPIBDD: ReceiveGPIB: NC

8:15:13.765: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:13.796: NIGPIBDD: ReceiveGPIB: NC

8:15:13.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:13.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:13.828: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:13.828: NIGPIBDD: SendGPIB: TR

8:15:13.843: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:13.859: NIGPIBDD: SendGPIB: TR

8:15:13.875: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:13.875: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.55 MHz, (Power) -0.24 dBm)

8:15:13.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)

8:15:13.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:13.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:13.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:13.921: NIGPIBDD: SendGPIB: TR

8:15:13.921: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:13.953: NIGPIBDD: SendGPIB: TR

8:15:13.968: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:13.984: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.55 MHz, (Power) -6.59 dBm)

8:15:13.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)

8:15:14.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.60234E-024)

8:15:14.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)

8:15:14.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:15:14.015: NIGPIBDD: SendGPIB: 1N

8:15:14.171: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:14.171: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.55 MHz, (Power) -150 dBm)
8:15:14.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:14.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -0.0306244)
8:15:14.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:16.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:16.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:16.265: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:16.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:16.281: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:16.312: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:16.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:16.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:16.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:16.328: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:16.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:16.343: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:16.359: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:16.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:15:16.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:16.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:16.375: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:16.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:16.390: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:16.421: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:16.421: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:15:16.421: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:16.421: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:16.437: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:16.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:16.468: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:16.515: NIGPIBDD: ReceiveGPIB: 53.375E+0

8:15:16.531: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.375)

8:15:16.531: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)

8:15:16.546: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)

8:15:16.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:16.562: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:16.562: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:16.578: NIGPIBDD: SendGPIB: TR

8:15:16.578: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:16.609: NIGPIBDD: SendGPIB: TR

8:15:16.625: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:16.625: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.55 MHz, (Power) -0.24 dBm)

8:15:16.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)

8:15:16.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:16.640: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:16.656: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)

8:15:16.656: NIGPIBDD: SendGPIB: TR

8:15:16.671: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:16.703: NIGPIBDD: SendGPIB: TR

8:15:16.718: NIGPIBDD: ReceiveGPIB: 0,-0.24,0,-6.59

8:15:16.718: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.55 MHz, (Power) -6.59 dBm)

8:15:16.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)

8:15:16.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.60234E-024)

8:15:16.750: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15.7306 dBm)

8:15:16.750: NIGPIBDD: SaveSendGPIB function entered

8:15:16.765: NIGPIBDD: Assigning zero string to sCommand

8:15:16.765: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:16.765: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:16.765: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:15:16.781: NIGPIBDD: SendGPIB: SOURCE:POWER -15.7306 DBM;*OPC?

8:15:16.781: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:16.796: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:16.796: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:16.796: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:15:16.796: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:15:16.812: NIGPIBDD: ReceiveGPIB: 1

8:15:16.812: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:16.812: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:16.812: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:16.812: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:16.828: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:16.843: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:16.843: NIGPIBDD: Just before returning the error code
8:15:16.843: NIGPIBDD: SaveSendGPIB function entered
8:15:16.843: NIGPIBDD: Assigning zero string to sCommand
8:15:16.859: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:16.859: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:16.859: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:15:16.859: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:16.875: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:16.875: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:16.890: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:16.890: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:16.890: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:16.890: NIGPIBDD: Just before returning the error code
8:15:16.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -6.6501E+016)
8:15:16.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:16.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)
8:15:16.921: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)
8:15:16.921: NIGPIBDD: SendGPIB: TR
8:15:16.937: NIGPIBDD: ReceiveGPIB: 0,-0.51,0,-6.86
8:15:16.968: NIGPIBDD: SendGPIB: TR
8:15:16.984: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.86
8:15:16.984: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.55 MHz, (Power) -0.52 dBm)
8:15:17.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:15:17.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:17.000: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)
8:15:17.015: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.55 MHz, (Attenuation) 40 dB)
8:15:17.015: NIGPIBDD: SendGPIB: TR
8:15:17.031: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.86
8:15:17.062: NIGPIBDD: SendGPIB: TR
8:15:17.078: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.86
8:15:17.078: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.55 MHz, (Power) -6.86 dBm)
8:15:17.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:15:17.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -1.60234E-024)

8:15:17.109: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.58 MHz)
8:15:17.109: NIGPIBDD: SaveSendGPIB function entered
8:15:17.109: NIGPIBDD: Assigning zero string to sCommand
8:15:17.109: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:17.125: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:17.125: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:15:17.140: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.58 MHZ;*OPC?

8:15:17.140: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:17.140: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:17.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:17.156: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:17.156: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:17.171: NIGPIBDD: ReceiveGPIB: 1

8:15:17.171: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:17.171: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:17.171: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:17.171: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:17.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:17.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:17.187: NIGPIBDD: Just before returning the error code
8:15:17.203: NIGPIBDD: SaveSendGPIB function entered
8:15:17.203: NIGPIBDD: Assigning zero string to sCommand
8:15:17.218: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:17.218: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:17.218: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:15:17.218: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:17.234: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:17.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:17.234: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:17.234: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:17.250: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:17.250: NIGPIBDD: Just before returning the error code
8:15:17.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 2.72848E-014)
8:15:17.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:17.296: NIGPIBDD: ReceiveGPIB: NO

8:15:17.312: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:17.359: NIGPIBDD: ReceiveGPIB: NO

8:15:17.375: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:17.421: NIGPIBDD: ReceiveGPIB: NO

8:15:17.437: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:17.484: NIGPIBDD: ReceiveGPIB: NO

8:15:17.515: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:17.546: NIGPIBDD: ReceiveGPIB: NO
8:15:17.562: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:17.593: NIGPIBDD: ReceiveGPIB: NO
8:15:17.625: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:17.656: NIGPIBDD: ReceiveGPIB: NO
8:15:17.687: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:17.734: NIGPIBDD: ReceiveGPIB: NO
8:15:17.750: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:17.781: NIGPIBDD: ReceiveGPIB: NC
8:15:17.812: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:17.843: NIGPIBDD: ReceiveGPIB: NC
8:15:17.859: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:17.890: NIGPIBDD: ReceiveGPIB: NC
8:15:17.921: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:17.968: NIGPIBDD: ReceiveGPIB: NC

8:15:25.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:25.281: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:25.296: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:25.296: NIGPIBDD: SendGPIB: TR
8:15:25.312: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:25.343: NIGPIBDD: SendGPIB: TR
8:15:25.359: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:25.359: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.58 MHz, (Power) -0.52 dBm)
8:15:25.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:15:25.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:25.375: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)

8:15:25.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:25.390: NIGPIBDD: SendGPIB: TR
8:15:25.406: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:25.437: NIGPIBDD: SendGPIB: TR
8:15:25.453: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:25.468: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.58 MHz, (Power) -6.89 dBm)
8:15:25.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:15:25.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -3.78783E-010)
8:15:25.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:15:25.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:15:25.500: NIGPIBDD: SendGPIB: 1N
8:15:25.625: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:25.625: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.58 MHz, (Power) -150 dBm)
8:15:25.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:25.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.61387E-029)
8:15:25.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:27.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:27.640: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:27.640: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:27.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:27.656: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:27.703: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:27.703: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:27.703: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:27.718: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:27.718: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:27.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:27.734: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:27.750: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:27.765: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)

8:15:27.765: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:27.781: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:27.781: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:27.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:27.796: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:27.812: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:27.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:15:27.828: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:27.859: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:27.859: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:27.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:27.875: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:27.906: NIGPIBDD: ReceiveGPIB: 53.790E+0

8:15:27.906: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.79)
8:15:27.906: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:15:27.921: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:27.921: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:27.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:27.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:27.953: NIGPIBDD: SendGPIB: TR
8:15:27.953: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:28.000: NIGPIBDD: SendGPIB: TR
8:15:28.000: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:28.015: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.58 MHz, (Power) -0.52 dBm)
8:15:28.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:15:28.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:28.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:28.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:28.031: NIGPIBDD: SendGPIB: TR
8:15:28.062: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89
8:15:28.078: NIGPIBDD: SendGPIB: TR
8:15:28.109: NIGPIBDD: ReceiveGPIB: 0,-0.52,0,-6.89

8:15:28.109: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.58 MHz, (Power) -6.89 dBm)
8:15:28.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:15:28.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -3.78783E-010)
8:15:28.125: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -15.994 dBm)
8:15:28.125: NIGPIBDD: SaveSendGPIB function entered
8:15:28.140: NIGPIBDD: Assigning zero string to sCommand
8:15:28.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.156: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:28.156: NIGPIBDD: SendGPIB: SOURCE:POWER -15.994 DBM;*OPC?

8:15:28.156: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.171: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.187: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.187: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:28.187: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:28.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.203: NIGPIBDD: Just before returning the error code
8:15:28.203: NIGPIBDD: ReceiveGPIB: 1

8:15:28.203: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:28.203: NIGPIBDD: SaveSendGPIB function entered
8:15:28.218: NIGPIBDD: Assigning zero string to sCommand
8:15:28.218: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:28.234: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:28.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.234: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.250: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:28.250: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.250: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.250: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.281: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.281: NIGPIBDD: Just before returning the error code
8:15:28.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -1.30242E-008)
8:15:28.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:28.296: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:28.296: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:28.312: NIGPIBDD: SendGPIB: TR
8:15:28.312: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.14
8:15:28.343: NIGPIBDD: SendGPIB: TR

8:15:28.359: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.14
8:15:28.375: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.58 MHz, (Power) -0.77 dBm)
8:15:28.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:15:28.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:28.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:28.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.58 MHz, (Attenuation) 40 dB)
8:15:28.390: NIGPIBDD: SendGPIB: TR
8:15:28.406: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.14
8:15:28.437: NIGPIBDD: SendGPIB: TR
8:15:28.453: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.14
8:15:28.453: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.58 MHz, (Power) -7.14 dBm)
8:15:28.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 1.0842E-019)
8:15:28.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -3.78783E-010)
8:15:28.484: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.61 MHz)
8:15:28.484: NIGPIBDD: SaveSendGPIB function entered
8:15:28.484: NIGPIBDD: Assigning zero string to sCommand
8:15:28.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.500: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:28.515: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.61 MHZ;*OPC?

8:15:28.515: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.515: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.531: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:28.531: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:28.546: NIGPIBDD: ReceiveGPIB: 1

8:15:28.546: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:28.546: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:28.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.546: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:28.562: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.578: NIGPIBDD: Just before returning the error code
8:15:28.578: NIGPIBDD: SaveSendGPIB function entered
8:15:28.578: NIGPIBDD: Assigning zero string to sCommand
8:15:28.593: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:28.593: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.593: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:28.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.609: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.609: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:28.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:28.625: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:28.625: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:28.625: NIGPIBDD: Just before returning the error code
8:15:28.640: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
9.80909E-045, (Data2) -5.00488E-005)
8:15:28.640: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:28.687: NIGPIBDD: ReceiveGPIB: NO

8:15:28.718: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:28.765: NIGPIBDD: ReceiveGPIB: NO

8:15:28.781: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:28.828: NIGPIBDD: ReceiveGPIB: NO

8:15:28.843: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:28.890: NIGPIBDD: ReceiveGPIB: NO

8:15:28.906: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:28.937: NIGPIBDD: ReceiveGPIB: NO

8:15:28.953: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:29.000: NIGPIBDD: ReceiveGPIB: NO

8:15:29.015: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:29.062: NIGPIBDD: ReceiveGPIB: NO

8:15:29.093: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:29.140: NIGPIBDD: ReceiveGPIB: NO

8:15:29.156: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:29.187: NIGPIBDD: ReceiveGPIB: NC

8:15:29.218: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:29.250: NIGPIBDD: ReceiveGPIB: NC

8:15:29.265: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:29.296: NIGPIBDD: ReceiveGPIB: NC

8:15:29.328: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:29.375: NIGPIBDD: ReceiveGPIO: NC

8:15:29.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:29.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)

8:15:29.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)

8:15:29.406: NIGPIBDD: SendGPIO: TR

8:15:29.406: NIGPIBDD: ReceiveGPIO: 0,-0.76,0,-7.15

8:15:29.437: NIGPIBDD: SendGPIO: TR

8:15:29.453: NIGPIBDD: ReceiveGPIO: 0,-0.76,0,-7.15

8:15:29.453: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.61 MHz, (Power) -0.76 dBm)

8:15:29.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)

8:15:29.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:29.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)

8:15:29.484: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)

8:15:29.484: NIGPIBDD: SendGPIO: TR

8:15:29.500: NIGPIBDD: ReceiveGPIO: 0,-0.76,0,-7.15

8:15:29.531: NIGPIBDD: SendGPIO: TR

8:15:29.546: NIGPIBDD: ReceiveGPIO: 0,-0.76,0,-7.15

8:15:29.546: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.61 MHz, (Power) -7.15 dBm)

8:15:29.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -1.0842E-019)

8:15:29.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -4.67177E-012)

8:15:29.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)

8:15:29.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:15:29.593: NIGPIBDD: SendGPIO: 1N

8:15:29.734: NIGPIBDD: ReceiveGPIO: DBA+0000E+0,3,0

8:15:29.750: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.61 MHz, (Power) -150 dBm)

8:15:29.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)

8:15:29.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 0.10458)

8:15:29.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)

8:15:31.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)

8:15:31.765: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:15:31.765: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:15:31.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:31.781: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:31.812: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:31.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 0, (Data2) 3.7)
8:15:31.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 0, (Data2) 100)
8:15:31.828: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:31.828: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:31.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:31.843: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:31.859: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:31.859: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 1.4013E-045, (Data2) 0.58)
8:15:31.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 1.4013E-045, (Data2) 100)
8:15:31.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:31.875: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:31.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:31.890: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:31.921: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:31.921: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 2.8026E-045, (Data2) 0.2)
8:15:31.921: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 2.8026E-045, (Data2) 100)
8:15:31.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:31.937: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:31.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:31.984: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:32.000: NIGPIBDD: ReceiveGPIB: 53.900E+0

8:15:32.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 4.2039E-045, (Data2) 53.9)
8:15:32.015: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 4.2039E-045, (Data2) 100)
8:15:32.015: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:32.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.22299E-044, (Data2) 0)
8:15:32.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)

8:15:32.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.046: NIGPIBDD: SendGPIB: TR
8:15:32.062: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.16
8:15:32.093: NIGPIBDD: SendGPIB: TR
8:15:32.109: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.16
8:15:32.109: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.61 MHz, (Power) -0.77 dBm)
8:15:32.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) 0)
8:15:32.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)
8:15:32.125: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.125: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.140: NIGPIBDD: SendGPIB: TR
8:15:32.140: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.16
8:15:32.187: NIGPIBDD: SendGPIB: TR
8:15:32.203: NIGPIBDD: ReceiveGPIB: 0,-0.77,0,-7.16
8:15:32.203: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.61 MHz, (Power) -7.16 dBm)
8:15:32.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) 0)
8:15:32.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) -4.67177E-012)
8:15:32.218: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -16.2029 dBm)
8:15:32.234: NIGPIBDD: SaveSendGPIB function entered
8:15:32.234: NIGPIBDD: Assigning zero string to sCommand
8:15:32.250: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.250: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.250: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:15:32.250: NIGPIBDD: SendGPIB: SOURCE:POWER -16.2029 DBM;*OPC?

8:15:32.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.265: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:32.265: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:32.281: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.281: NIGPIBDD: ReceiveGPIB: 1

8:15:32.296: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:32.296: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:32.296: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.296: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.296: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:32.312: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.328: NIGPIBDD: Just before returning the error code
8:15:32.328: NIGPIBDD: SaveSendGPIB function entered
8:15:32.328: NIGPIBDD: Assigning zero string to sCommand
8:15:32.328: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:32.343: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.343: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:32.343: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.343: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.359: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.359: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.375: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.375: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.375: NIGPIBDD: Just before returning the error code
8:15:32.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.70825E-022)
8:15:32.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:32.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.406: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.406: NIGPIBDD: SendGPIB: TR
8:15:32.421: NIGPIBDD: ReceiveGPIB: 0,-0.97,0,-7.36
8:15:32.453: NIGPIBDD: SendGPIB: TR
8:15:32.468: NIGPIBDD: ReceiveGPIB: 0,-0.97,0,-7.36
8:15:32.468: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.61 MHz, (Power) -0.97 dBm)
8:15:32.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:15:32.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:32.484: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.484: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.61 MHz, (Attenuation) 40 dB)
8:15:32.500: NIGPIBDD: SendGPIB: TR
8:15:32.500: NIGPIBDD: ReceiveGPIB: 0,-0.97,0,-7.36
8:15:32.546: NIGPIBDD: SendGPIB: TR
8:15:32.546: NIGPIBDD: ReceiveGPIB: 0,-0.97,0,-7.36
8:15:32.562: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.61 MHz, (Power) -7.36 dBm)
8:15:32.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:15:32.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -4.67177E-012)
8:15:32.578: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.64 MHz)
8:15:32.578: NIGPIBDD: SaveSendGPIB function entered
8:15:32.578: NIGPIBDD: Assigning zero string to sCommand
8:15:32.593: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.593: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.609: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:32.609: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.64 MHz;*OPC?

8:15:32.609: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.609: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:32.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:32.625: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:32.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.640: NIGPIBDD: ReceiveGPIB: 1

8:15:32.640: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:32.640: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:32.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.656: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:32.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.671: NIGPIBDD: Just before returning the error code
8:15:32.671: NIGPIBDD: SaveSendGPIB function entered
8:15:32.687: NIGPIBDD: Assigning zero string to sCommand
8:15:32.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.687: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:32.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.703: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.703: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:32.703: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:32.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:32.718: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:32.734: NIGPIBDD: Just before returning the error code
8:15:32.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 89129)
8:15:32.734: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:32.765: NIGPIBDD: ReceiveGPIB: NO

8:15:32.796: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:32.843: NIGPIBDD: ReceiveGPIB: NO

8:15:32.859: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:32.906: NIGPIBDD: ReceiveGPIB: NO

8:15:32.921: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:32.968: NIGPIBDD: ReceiveGPIB: NO

8:15:33.000: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:33.031: NIGPIBDD: ReceiveGPIB: NO

8:15:33.062: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:33.078: NIGPIBDD: ReceiveGPIB: NO

8:15:33.109: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:33.140: NIGPIBDD: ReceiveGPIB: NO

8:15:33.171: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:33.218: NIGPIBDD: ReceiveGPIB: NO

8:15:33.234: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:33.265: NIGPIBDD: ReceiveGPIB: NC

8:15:33.296: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:33.328: NIGPIBDD: ReceiveGPIB: NC

8:15:33.343: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:33.390: NIGPIBDD: ReceiveGPIB: NC

8:15:33.406: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:33.453: NIGPIBDD: ReceiveGPIB: NC

8:15:33.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:33.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)

8:15:33.468: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)

8:15:33.468: NIGPIBDD: SendGPIB: TR

8:15:33.500: NIGPIBDD: ReceiveGPIB: 0,-0.95,0,-7.36

8:15:33.515: NIGPIBDD: SendGPIB: TR

8:15:33.546: NIGPIBDD: ReceiveGPIB: 0,-0.95,0,-7.36

8:15:33.546: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.64 MHz, (Power) -0.95 dBm)

8:15:33.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:15:33.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:33.562: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)

8:15:33.562: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)

8:15:33.578: NIGPIBDD: SendGPIB: TR

8:15:33.593: NIGPIBDD: ReceiveGPIB: 0,-0.95,0,-7.36

8:15:33.625: NIGPIBDD: SendGPIB: TR

8:15:33.640: NIGPIBDD: ReceiveGPIB: 0,-0.95,0,-7.37

8:15:33.656: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.64 MHz, (Power) -7.37 dBm)

8:15:33.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)

8:15:33.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -3.64046E+034)

8:15:33.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:15:33.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:15:33.687: NIGPIBDD: SendGPIO: 1N
8:15:33.843: NIGPIBDD: ReceiveGPIO: DBA+0000E+0,3,0

8:15:33.843: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.64 MHz, (Power) -150 dBm)
8:15:33.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:33.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 2.96113E+037)
8:15:33.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:35.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:35.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:35.875: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:35.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:35.890: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:15:35.937: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:15:35.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:35.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:35.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:35.953: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:35.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:35.968: NIGPIBDD: SendGPIO: :MEASU:MEAS2:VAL?

8:15:35.984: NIGPIBDD: ReceiveGPIO: 560.0E-3

8:15:36.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.56)
8:15:36.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:36.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:36.015: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:36.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:36.015: NIGPIBDD: SendGPIO: :MEASU:MEAS3:VAL?

8:15:36.046: NIGPIBDD: ReceiveGPIO: 200.0E-3

8:15:36.046: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:15:36.046: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:36.062: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:36.062: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:36.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:36.109: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:36.125: NIGPIBDD: ReceiveGPIB: 53.943E+0

8:15:36.140: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.943)
8:15:36.140: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:15:36.156: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:36.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:36.171: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.171: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.187: NIGPIBDD: SendGPIB: TR
8:15:36.187: NIGPIBDD: ReceiveGPIB: 0,-0.96,0,-7.37
8:15:36.218: NIGPIBDD: SendGPIB: TR
8:15:36.234: NIGPIBDD: ReceiveGPIB: 0,-0.96,0,-7.37
8:15:36.250: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.64 MHz, (Power) -0.96 dBm)
8:15:36.250: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:15:36.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:36.265: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.265: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.281: NIGPIBDD: SendGPIB: TR
8:15:36.296: NIGPIBDD: ReceiveGPIB: 0,-0.96,0,-7.37
8:15:36.312: NIGPIBDD: SendGPIB: TR
8:15:36.343: NIGPIBDD: ReceiveGPIB: 0,-0.96,0,-7.37
8:15:36.343: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.64 MHz, (Power) -7.37 dBm)
8:15:36.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:15:36.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -3.64046E+034)
8:15:36.375: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -16.4304 dBm)
8:15:36.375: NIGPIBDD: SaveSendGPIB function entered
8:15:36.375: NIGPIBDD: Assigning zero string to sCommand
8:15:36.375: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.390: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.390: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0

8:15:36.390: NIGPIBDD: SendGPIB: SOURCE:POWER -16.4304 DBM;*OPC?

8:15:36.406: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.406: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.406: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.421: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.421: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.421: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:36.421: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:36.421: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.437: NIGPIBDD: Just before returning the error code
8:15:36.437: NIGPIBDD: ReceiveGPIB: 1

8:15:36.437: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:36.453: NIGPIBDD: SaveSendGPIB function entered
8:15:36.453: NIGPIBDD: Assigning zero string to sCommand
8:15:36.453: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:36.468: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:36.468: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.468: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.484: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:15:36.484: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.484: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.515: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.515: NIGPIBDD: Just before returning the error code
8:15:36.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 8.5285E-030)
8:15:36.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:36.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.546: NIGPIBDD: SendGPIB: TR
8:15:36.546: NIGPIBDD: ReceiveGPIB: 0,-1.18,0,-7.59
8:15:36.593: NIGPIBDD: SendGPIB: TR
8:15:36.593: NIGPIBDD: ReceiveGPIB: 0,-1.18,0,-7.59
8:15:36.609: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.64 MHz, (Power) -1.18 dBm)
8:15:36.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:15:36.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:36.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.64 MHz, (Attenuation) 40 dB)
8:15:36.625: NIGPIBDD: SendGPIB: TR
8:15:36.640: NIGPIBDD: ReceiveGPIB: 0,-1.18,0,-7.59

8:15:36.671: NIGPIBDD: SendGPIB: TR
8:15:36.687: NIGPIBDD: ReceiveGPIB: 0,-1.18,0,-7.59
8:15:36.687: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.64 MHz, (Power) -7.59 dBm)
8:15:36.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:36.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -3.64046E+034)
8:15:36.718: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.67 MHz)
8:15:36.718: NIGPIBDD: SaveSendGPIB function entered
8:15:36.734: NIGPIBDD: Assigning zero string to sCommand
8:15:36.734: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.734: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.734: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:36.750: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.67 MHZ;*OPC?

8:15:36.750: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.750: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.750: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.765: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:36.765: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:36.781: NIGPIBDD: ReceiveGPIB: 1

8:15:36.781: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:36.781: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:36.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.781: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:36.796: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.812: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.812: NIGPIBDD: Just before returning the error code
8:15:36.812: NIGPIBDD: SaveSendGPIB function entered
8:15:36.812: NIGPIBDD: Assigning zero string to sCommand
8:15:36.828: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.828: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.828: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:36.828: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.843: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.843: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:36.859: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:36.859: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:36.859: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:36.859: NIGPIBDD: Just before returning the error code
8:15:36.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -1.51997E+014)
8:15:36.875: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:36.906: NIGPIBDD: ReceiveGPIB: NO

8:15:36.921: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:36.968: NIGPIBDD: ReceiveGPIB: NO

8:15:36.984: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?
8:15:37.031: NIGPIBDD: ReceiveGPIB: NO
8:15:37.062: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?
8:15:37.093: NIGPIBDD: ReceiveGPIB: NO
8:15:37.109: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:37.140: NIGPIBDD: ReceiveGPIB: NO
8:15:37.171: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:37.203: NIGPIBDD: ReceiveGPIB: NO
8:15:37.234: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:37.281: NIGPIBDD: ReceiveGPIB: NO
8:15:37.296: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:37.343: NIGPIBDD: ReceiveGPIB: NO
8:15:37.375: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:37.406: NIGPIBDD: ReceiveGPIB: NC
8:15:37.421: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:37.453: NIGPIBDD: ReceiveGPIB: NC
8:15:37.468: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:37.515: NIGPIBDD: ReceiveGPIB: NC
8:15:37.531: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:37.578: NIGPIBDD: ReceiveGPIB: NC
8:15:37.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:37.593: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:37.593: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:37.609: NIGPIBDD: SendGPIB: TR
8:15:37.609: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:37.640: NIGPIBDD: SendGPIB: TR
8:15:37.656: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60

8:15:37.656: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.67 MHz, (Power) -1.17 dBm)
8:15:37.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -3.68935E+019)
8:15:37.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:37.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:37.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:37.687: NIGPIBDD: SendGPIB: TR
8:15:37.703: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:37.734: NIGPIBDD: SendGPIB: TR
8:15:37.750: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:37.750: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.67 MHz, (Power) -7.6 dBm)
8:15:37.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:15:37.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.65378E-022)
8:15:37.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:15:37.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:15:37.796: NIGPIBDD: SendGPIB: 1N
8:15:37.937: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:37.953: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.67 MHz, (Power) -150 dBm)
8:15:37.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:37.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.30532E+010)
8:15:37.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:39.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:39.968: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:39.968: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:39.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:39.984: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:40.015: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:40.015: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:40.015: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:40.031: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:40.031: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:15:40.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:40.046: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:40.062: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:40.062: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 1.4013E-045, (Data2) 0.58)
8:15:40.078: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 1.4013E-045, (Data2) 100)
8:15:40.078: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:40.093: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:40.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:40.109: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:40.125: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:40.125: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 2.8026E-045, (Data2) 0.2)
8:15:40.140: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 2.8026E-045, (Data2) 100)
8:15:40.140: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:40.140: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:40.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:15:40.187: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:40.218: NIGPIBDD: ReceiveGPIB: 53.995E+0

8:15:40.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 4.2039E-045, (Data2) 53.995)
8:15:40.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 4.2039E-045, (Data2) 100)
8:15:40.218: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:40.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.22299E-044, (Data2) 0)
8:15:40.234: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.250: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.250: NIGPIBDD: SendGPIB: TR
8:15:40.265: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:40.296: NIGPIBDD: SendGPIB: TR
8:15:40.312: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:40.312: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.67 MHz, (Power) -1.17 dBm)
8:15:40.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) -3.68935E+019)
8:15:40.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)

8:15:40.328: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.343: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.343: NIGPIBDD: SendGPIB: TR
8:15:40.359: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:40.390: NIGPIBDD: SendGPIB: TR
8:15:40.390: NIGPIBDD: ReceiveGPIB: 0,-1.17,0,-7.60
8:15:40.406: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.67 MHz, (Power) -7.6 dBm)
8:15:40.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) 3.68935E+019)
8:15:40.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) -2.65378E-022)
8:15:40.421: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -16.6713 dBm)
8:15:40.437: NIGPIBDD: SaveSendGPIB function entered
8:15:40.437: NIGPIBDD: Assigning zero string to sCommand
8:15:40.437: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.437: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.453: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:40.453: NIGPIBDD: SendGPIB: SOURCE:POWER -16.6713 DBM;*OPC?

8:15:40.468: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.468: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.468: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:40.468: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:40.468: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.484: NIGPIBDD: ReceiveGPIB: 1

8:15:40.500: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:40.500: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:40.500: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.500: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:40.515: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.515: NIGPIBDD: Just before returning the error code
8:15:40.515: NIGPIBDD: SaveSendGPIB function entered
8:15:40.531: NIGPIBDD: Assigning zero string to sCommand
8:15:40.531: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.546: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:40.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.546: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.562: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.562: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.562: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.578: NIGPIBDD: Just before returning the error code
8:15:40.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
1.12104E-044, (Data2) -1.6685)

8:15:40.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:40.593: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.609: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.609: NIGPIBDD: SendGPIB: TR
8:15:40.625: NIGPIBDD: ReceiveGPIB: 0,-1.39,0,-7.82
8:15:40.640: NIGPIBDD: SendGPIB: TR
8:15:40.656: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.83
8:15:40.656: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.67 MHz, (Power) -1.4 dBm)
8:15:40.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)
8:15:40.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:40.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.67 MHz, (Attenuation) 40 dB)
8:15:40.703: NIGPIBDD: SendGPIB: TR
8:15:40.703: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.83
8:15:40.734: NIGPIBDD: SendGPIB: TR
8:15:40.750: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.83
8:15:40.750: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.67 MHz, (Power) -7.83 dBm)
8:15:40.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:40.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.65378E-022)
8:15:40.781: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.7 MHz)
8:15:40.781: NIGPIBDD: SaveSendGPIB function entered
8:15:40.781: NIGPIBDD: Assigning zero string to sCommand
8:15:40.796: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.796: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.812: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:40.812: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.7 MHZ;*OPC?

8:15:40.812: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.812: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.828: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.828: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.828: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:40.843: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.843: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:40.843: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.843: NIGPIBDD: ReceiveGPIB: 1

8:15:40.859: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:40.859: NIGPIBDD: Just before returning the error code
8:15:40.859: NIGPIBDD: SaveSendGPIB function entered

8:15:40.859: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:40.875: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:40.875: NIGPIBDD: Assigning zero string to sCommand
8:15:40.875: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.890: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.890: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:15:40.906: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.906: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:40.906: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:40.921: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:40.921: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:40.921: NIGPIBDD: Just before returning the error code
8:15:40.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 2.72008E+023)
8:15:40.937: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:40.984: NIGPIBDD: ReceiveGPIB: NO

8:15:41.000: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:41.046: NIGPIBDD: ReceiveGPIB: NO

8:15:41.078: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:41.125: NIGPIBDD: ReceiveGPIB: NO

8:15:41.140: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:41.187: NIGPIBDD: ReceiveGPIB: NO

8:15:41.218: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:41.250: NIGPIBDD: ReceiveGPIB: NO

8:15:41.265: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:41.296: NIGPIBDD: ReceiveGPIB: NO

8:15:41.328: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:41.359: NIGPIBDD: ReceiveGPIB: NO

8:15:41.375: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:41.421: NIGPIBDD: ReceiveGPIB: NO

8:15:41.453: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:41.484: NIGPIBDD: ReceiveGPIB: NC

8:15:41.515: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:41.531: NIGPIBDD: ReceiveGPIB: NC

8:15:41.562: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:41.593: NIGPIBDD: ReceiveGPIB: NC

8:15:41.625: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:41.671: NIGPIBDD: ReceiveGPIB: NC

8:15:41.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:41.671: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)

8:15:41.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)

8:15:41.687: NIGPIBDD: SendGPIB: TR

8:15:41.703: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.85

8:15:41.734: NIGPIBDD: SendGPIB: TR

8:15:41.750: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.86

8:15:41.750: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.7 MHz, (Power) -1.4 dBm)

8:15:41.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:15:41.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:41.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)

8:15:41.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)

8:15:41.781: NIGPIBDD: SendGPIB: TR

8:15:41.796: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.86

8:15:41.828: NIGPIBDD: SendGPIB: TR

8:15:41.843: NIGPIBDD: ReceiveGPIB: 0,-1.40,0,-7.86

8:15:41.843: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.7 MHz, (Power) -7.86 dBm)

8:15:41.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)

8:15:41.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 2.93633E+035)

8:15:41.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)

8:15:41.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:15:41.890: NIGPIBDD: SendGPIB: 1N

8:15:42.046: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:42.046: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.7 MHz, (Power) -150 dBm)

8:15:42.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)

8:15:42.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.276E-039)
8:15:42.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:44.078: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:44.078: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:44.078: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:44.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:44.093: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:44.156: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:44.156: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:44.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:44.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:44.171: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:44.187: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:44.187: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:44.234: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:44.250: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:15:44.250: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:44.281: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:44.296: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:44.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:44.296: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:44.328: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:44.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:15:44.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:44.343: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:44.343: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:44.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:44.359: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:44.375: NIGPIBDD: ReceiveGPIB: 53.990E+0

8:15:44.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.99)

8:15:44.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:15:44.406: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:44.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:44.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.437: NIGPIBDD: SendGPIB: TR
8:15:44.437: NIGPIBDD: ReceiveGPIB: 0,-1.41,0,-7.86
8:15:44.468: NIGPIBDD: SendGPIB: TR
8:15:44.484: NIGPIBDD: ReceiveGPIB: 0,-1.41,0,-7.86
8:15:44.484: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.7 MHz, (Power) -1.41 dBm)
8:15:44.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 1.0842E-019)
8:15:44.500: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:44.500: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.515: NIGPIBDD: SendGPIB: TR
8:15:44.531: NIGPIBDD: ReceiveGPIB: 0,-1.41,0,-7.86
8:15:44.562: NIGPIBDD: SendGPIB: TR
8:15:44.578: NIGPIBDD: ReceiveGPIB: 0,-1.41,0,-7.86
8:15:44.578: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.7 MHz, (Power) -7.86 dBm)
8:15:44.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)
8:15:44.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 2.93633E+035)
8:15:44.609: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -16.811 dBm)
8:15:44.609: NIGPIBDD: SaveSendGPIB function entered
8:15:44.609: NIGPIBDD: Assigning zero string to sCommand
8:15:44.609: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:44.625: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:44.625: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:15:44.640: NIGPIBDD: SendGPIB: SOURCE:POWER -16.811 DBM;*OPC?

8:15:44.640: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:44.640: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:44.640: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:44.656: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:44.656: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:44.671: NIGPIBDD: ReceiveGPIB: 1

8:15:44.671: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:44.671: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:44.671: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:44.671: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:44.687: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:44.687: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:44.687: NIGPIBDD: Just before returning the error code
8:15:44.703: NIGPIBDD: SaveSendGPIB function entered
8:15:44.703: NIGPIBDD: Assigning zero string to sCommand
8:15:44.718: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:44.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:44.718: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:44.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:44.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:44.734: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:44.734: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:44.734: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:44.750: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:44.750: NIGPIBDD: Just before returning the error code
8:15:44.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -5.41888E+036)
8:15:44.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:44.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.781: NIGPIBDD: SendGPIB: TR
8:15:44.796: NIGPIBDD: ReceiveGPIB: 0,-1.55,0,-7.99
8:15:44.828: NIGPIBDD: SendGPIB: TR
8:15:44.828: NIGPIBDD: ReceiveGPIB: 0,-1.55,0,-7.99
8:15:44.843: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.7 MHz, (Power) -1.55 dBm)
8:15:44.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)
8:15:44.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:44.859: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.875: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.7 MHz, (Attenuation) 40 dB)
8:15:44.875: NIGPIBDD: SendGPIB: TR
8:15:44.890: NIGPIBDD: ReceiveGPIB: 0,-1.55,0,-7.99
8:15:44.921: NIGPIBDD: SendGPIB: TR
8:15:44.937: NIGPIBDD: ReceiveGPIB: 0,-1.55,0,-7.99
8:15:44.937: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.7 MHz, (Power) -7.99 dBm)
8:15:44.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:44.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 2.93633E+035)
8:15:44.968: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.73 MHz)
8:15:44.968: NIGPIBDD: SaveSendGPIB function entered
8:15:44.968: NIGPIBDD: Assigning zero string to sCommand

8:15:44.968: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:44.984: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:44.984: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:15:44.984: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.73 MHZ;*OPC?

8:15:44.984: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:45.000: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:45.000: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:45.015: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:45.015: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:45.015: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:45.015: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:45.015: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:45.031: NIGPIBDD: Just before returning the error code
8:15:45.031: NIGPIBDD: ReceiveGPIB: 1

8:15:45.031: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:45.031: NIGPIBDD: SaveSendGPIB function entered
8:15:45.046: NIGPIBDD: Assigning zero string to sCommand
8:15:45.046: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:45.062: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:45.062: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:45.062: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:45.078: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
8:15:45.078: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:45.078: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:45.078: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:45.093: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:45.093: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:45.093: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:45.109: NIGPIBDD: Just before returning the error code
8:15:45.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -4.93268E+032)
8:15:45.109: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:45.140: NIGPIBDD: ReceiveGPIB: NO

8:15:45.171: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:45.203: NIGPIBDD: ReceiveGPIB: NO

8:15:45.218: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:45.250: NIGPIBDD: ReceiveGPIB: NO

8:15:45.281: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:45.328: NIGPIBDD: ReceiveGPIB: NO

8:15:45.343: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:45.375: NIGPIBDD: ReceiveGPIB: NO

8:15:45.406: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:45.437: NIGPIBDD: ReceiveGPIB: NO
8:15:45.453: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:45.500: NIGPIBDD: ReceiveGPIB: NO
8:15:45.515: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?
8:15:45.562: NIGPIBDD: ReceiveGPIB: NO
8:15:45.578: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:45.625: NIGPIBDD: ReceiveGPIB: NC
8:15:45.640: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:45.671: NIGPIBDD: ReceiveGPIB: NC
8:15:45.687: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:45.734: NIGPIBDD: ReceiveGPIB: NC
8:15:45.750: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?
8:15:45.796: NIGPIBDD: ReceiveGPIB: NC

8:15:45.812: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:45.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)
8:15:45.812: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)
8:15:45.828: NIGPIBDD: SendGPIB: TR
8:15:45.828: NIGPIBDD: ReceiveGPIB: 0,-1.53,0,-8.01
8:15:45.875: NIGPIBDD: SendGPIB: TR
8:15:45.875: NIGPIBDD: ReceiveGPIB: 0,-1.53,0,-8.01
8:15:45.890: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.73 MHz, (Power) -1.53 dBm)
8:15:45.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)
8:15:45.906: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:45.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)
8:15:45.906: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)
8:15:45.921: NIGPIBDD: SendGPIB: TR
8:15:45.937: NIGPIBDD: ReceiveGPIB: 0,-1.53,0,-8.01
8:15:45.953: NIGPIBDD: SendGPIB: TR

8:15:45.968: NIGPIBDD: ReceiveGPIO: 0,-1.53,0,-8.01
8:15:45.968: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.73 MHz, (Power) -8.01 dBm)
8:15:45.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:15:45.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 4.34862E+029)
8:15:46.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:15:46.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:15:46.015: NIGPIBDD: SendGPIO: 1N
8:15:46.187: NIGPIBDD: ReceiveGPIO: DBA+0000E+0,3,0

8:15:46.203: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.73 MHz, (Power) -150 dBm)
8:15:46.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:46.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 2.79835E-038)
8:15:46.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:48.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:48.218: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:48.218: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:48.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:48.234: NIGPIBDD: SendGPIO: :MEASU:MEAS1:VAL?

8:15:48.265: NIGPIBDD: ReceiveGPIO: 3.70E+0

8:15:48.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:48.265: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:48.281: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:48.281: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:48.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:48.296: NIGPIBDD: SendGPIO: :MEASU:MEAS2:VAL?

8:15:48.312: NIGPIBDD: ReceiveGPIO: 580.0E-3

8:15:48.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:15:48.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:48.328: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:48.343: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:48.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:15:48.343: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:48.375: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:48.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)

8:15:48.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)

8:15:48.390: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:15:48.390: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:15:48.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)

8:15:48.406: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:48.421: NIGPIBDD: ReceiveGPIB: 53.350E+0

8:15:48.421: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.35)

8:15:48.437: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)

8:15:48.468: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)

8:15:48.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:48.484: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)

8:15:48.500: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)

8:15:48.500: NIGPIBDD: SendGPIB: TR

8:15:48.515: NIGPIBDD: ReceiveGPIB: 0,-1.54,0,-8.01

8:15:48.546: NIGPIBDD: SendGPIB: TR

8:15:48.562: NIGPIBDD: ReceiveGPIB: 0,-1.54,0,-8.01

8:15:48.562: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.73 MHz, (Power) -1.54 dBm)

8:15:48.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)

8:15:48.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:48.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)

8:15:48.578: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)

8:15:48.593: NIGPIBDD: SendGPIB: TR

8:15:48.593: NIGPIBDD: ReceiveGPIB: 0,-1.54,0,-8.01

8:15:48.640: NIGPIBDD: SendGPIB: TR

8:15:48.640: NIGPIBDD: ReceiveGPIB: 0,-1.54,0,-8.01

8:15:48.656: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.73 MHz, (Power) -8.01 dBm)

8:15:48.656: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)

8:15:48.671: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 4.34862E+029)

8:15:48.671: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -16.9595 dBm)

8:15:48.687: NIGPIBDD: SaveSendGPIB function entered

8:15:48.687: NIGPIBDD: Assigning zero string to sCommand

8:15:48.687: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:48.687: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:48.703: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:15:48.703: NIGPIBDD: SendGPIB: SOURCE:POWER -16.9595 DBM;*OPC?

8:15:48.718: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:48.718: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:48.718: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:15:48.718: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:15:48.718: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:48.734: NIGPIBDD: ReceiveGPIB: 1

8:15:48.734: NIGPIBDD: After CheckDeviceSpecificStatusRegister

8:15:48.734: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()

8:15:48.750: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:48.750: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:48.750: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()

8:15:48.765: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:48.765: NIGPIBDD: Just before returning the error code

8:15:48.765: NIGPIBDD: SaveSendGPIB function entered

8:15:48.781: NIGPIBDD: Assigning zero string to sCommand

8:15:48.781: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:48.781: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:48.781: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10

8:15:48.796: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:48.796: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:48.812: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:48.812: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:48.812: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:48.812: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:48.828: NIGPIBDD: Just before returning the error code

8:15:48.828: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -1.92038E+031)

8:15:48.843: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:48.843: DVDRSYS.DLL: GetValue((ID) 393216, (Function)

CP_GetForwardAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)

8:15:48.843: DVDRSYS.DLL: GetValue((ID) 393216, (Function)

CP_GetReflectedAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)

8:15:48.843: NIGPIBDD: SendGPIB: TR

8:15:48.875: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.15

8:15:48.906: NIGPIBDD: SendGPIB: TR

8:15:48.921: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.15

8:15:48.921: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.73 MHz, (Power) -1.68 dBm)

8:15:48.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)

8:15:48.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:48.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)
8:15:48.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.73 MHz, (Attenuation) 40 dB)
8:15:48.953: NIGPIBDD: SendGPIO: TR
8:15:48.968: NIGPIBDD: ReceiveGPIO: 0,-1.68,0,-8.15
8:15:49.000: NIGPIBDD: SendGPIO: TR
8:15:49.015: NIGPIBDD: ReceiveGPIO: 0,-1.68,0,-8.15
8:15:49.031: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.73 MHz, (Power) -8.15 dBm)
8:15:49.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:15:49.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 4.34862E+029)
8:15:49.046: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.76 MHz)
8:15:49.062: NIGPIBDD: SaveSendGPIO function entered
8:15:49.062: NIGPIBDD: Assigning zero string to sCommand
8:15:49.062: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:15:49.062: NIGPIBDD: After mcGPIOCommunication.Enter()
8:15:49.078: NIGPIBDD::SaveSendGPIO: mlSuggestedReadSize: 0
8:15:49.078: NIGPIBDD: SendGPIO: SOURCE:FREQ 0.76 MHZ;*OPC?

8:15:49.093: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:15:49.093: NIGPIBDD: After mcGPIOCommunication.Leave()
8:15:49.093: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Enter()
8:15:49.093: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Enter()
8:15:49.109: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:15:49.109: NIGPIBDD: ReceiveGPIO: 1

8:15:49.125: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:49.125: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Leave()
8:15:49.125: NIGPIBDD: After mcGPIOCommunication.Enter()
8:15:49.125: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:15:49.125: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Leave()
8:15:49.140: NIGPIBDD: After mcGPIOCommunication.Leave()
8:15:49.156: NIGPIBDD: Just before returning the error code
8:15:49.156: NIGPIBDD: SaveSendGPIO function entered
8:15:49.156: NIGPIBDD: Assigning zero string to sCommand
8:15:49.156: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:15:49.171: NIGPIBDD: After mcGPIOCommunication.Enter()
8:15:49.171: NIGPIBDD::SaveSendGPIO: mlSuggestedReadSize: 10
8:15:49.171: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:15:49.171: NIGPIBDD: After mcGPIOCommunication.Leave()
8:15:49.187: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:15:49.187: NIGPIBDD: After mcGPIOCommunication.Enter()
8:15:49.203: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:15:49.203: NIGPIBDD: After mcGPIOCommunication.Leave()
8:15:49.203: NIGPIBDD: Just before returning the error code

8:15:49.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -7.46298E-036)
8:15:49.218: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:49.250: NIGPIBDD: ReceiveGPIB: NO

8:15:49.265: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:49.312: NIGPIBDD: ReceiveGPIB: NO

8:15:49.328: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:49.375: NIGPIBDD: ReceiveGPIB: NO

8:15:49.406: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:49.453: NIGPIBDD: ReceiveGPIB: NO

8:15:49.468: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:49.515: NIGPIBDD: ReceiveGPIB: NO

8:15:49.531: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:49.562: NIGPIBDD: ReceiveGPIB: NO

8:15:49.578: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:49.625: NIGPIBDD: ReceiveGPIB: NO

8:15:49.640: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:49.687: NIGPIBDD: ReceiveGPIB: NO

8:15:49.703: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:49.750: NIGPIBDD: ReceiveGPIB: NC

8:15:49.765: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:49.796: NIGPIBDD: ReceiveGPIB: NC

8:15:49.812: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:49.859: NIGPIBDD: ReceiveGPIB: NC

8:15:49.875: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:49.921: NIGPIBDD: ReceiveGPIB: NC

8:15:49.937: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:49.937: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:49.953: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:49.953: NIGPIBDD: SendGPIB: TR
8:15:49.968: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:50.000: NIGPIBDD: SendGPIB: TR
8:15:50.015: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:50.015: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.76 MHz, (Power) -1.68 dBm)
8:15:50.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:15:50.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:50.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:50.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:50.046: NIGPIBDD: SendGPIB: TR
8:15:50.062: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:50.109: NIGPIBDD: SendGPIB: TR
8:15:50.109: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:50.125: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.76 MHz, (Power) -8.18 dBm)
8:15:50.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:50.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.61159E+023)
8:15:50.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:15:50.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:15:50.171: NIGPIBDD: SendGPIB: 1N
8:15:50.281: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:50.281: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.76 MHz, (Power) -150 dBm)
8:15:50.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:50.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 8.37873E-017)
8:15:50.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:52.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:52.312: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:52.312: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:52.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:52.328: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:52.375: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:52.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:52.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:52.375: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:52.390: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:52.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:52.406: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:52.453: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:52.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:15:52.453: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:52.468: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:52.468: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:52.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:52.515: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:52.531: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:52.531: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:15:52.546: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:52.546: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:52.562: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:52.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:52.578: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:52.593: NIGPIBDD: ReceiveGPIB: 52.658E+0

8:15:52.609: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 52.658)
8:15:52.609: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:15:52.609: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:15:52.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:52.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:52.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:52.640: NIGPIBDD: SendGPIB: TR
8:15:52.656: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:52.687: NIGPIBDD: SendGPIB: TR
8:15:52.687: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18

8:15:52.703: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.76 MHz, (Power) -1.68 dBm)
8:15:52.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:15:52.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:52.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:52.718: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:52.734: NIGPIBDD: SendGPIB: TR
8:15:52.750: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:52.765: NIGPIBDD: SendGPIB: TR
8:15:52.781: NIGPIBDD: ReceiveGPIB: 0,-1.68,0,-8.18
8:15:52.781: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.76 MHz, (Power) -8.18 dBm)
8:15:52.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:52.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.61159E+023)
8:15:52.812: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -17.109 dBm)
8:15:52.812: NIGPIBDD: SaveSendGPIB function entered
8:15:52.828: NIGPIBDD: Assigning zero string to sCommand
8:15:52.828: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:52.828: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:52.828: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:52.843: NIGPIBDD: SendGPIB: SOURCE:POWER -17.109 DBM;*OPC?

8:15:52.843: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:52.859: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:52.859: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:52.859: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:52.859: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:52.875: NIGPIBDD: ReceiveGPIB: 1

8:15:52.875: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:52.890: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:52.890: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:52.890: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:52.890: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:52.906: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:52.906: NIGPIBDD: Just before returning the error code
8:15:52.906: NIGPIBDD: SaveSendGPIB function entered
8:15:52.906: NIGPIBDD: Assigning zero string to sCommand
8:15:52.921: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:52.921: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:52.937: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:52.937: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:52.937: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:52.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:52.953: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:52.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:52.953: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:52.953: NIGPIBDD: Just before returning the error code
8:15:52.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0.000169943)
8:15:52.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:15:52.984: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:52.984: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:53.000: NIGPIBDD: SendGPIB: TR
8:15:53.000: NIGPIBDD: ReceiveGPIB: 0,-1.81,0,-8.19
8:15:53.031: NIGPIBDD: SendGPIB: TR
8:15:53.046: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.32
8:15:53.046: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.76 MHz, (Power) -1.82 dBm)
8:15:53.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)
8:15:53.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:15:53.062: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:53.078: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.76 MHz, (Attenuation) 40 dB)
8:15:53.078: NIGPIBDD: SendGPIB: TR
8:15:53.093: NIGPIBDD: ReceiveGPIB: 0,-1.83,0,-8.32
8:15:53.125: NIGPIBDD: SendGPIB: TR
8:15:53.140: NIGPIBDD: ReceiveGPIB: 0,-1.83,0,-8.32
8:15:53.140: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.76 MHz, (Power) -8.32 dBm)
8:15:53.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:15:53.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.61159E+023)
8:15:53.171: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.79 MHz)
8:15:53.171: NIGPIBDD: SaveSendGPIB function entered
8:15:53.171: NIGPIBDD: Assigning zero string to sCommand
8:15:53.171: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:53.187: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:53.187: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:53.203: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.79 MHZ,*OPC?

8:15:53.203: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:53.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:53.203: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:53.218: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:53.218: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:53.218: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:53.218: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:53.218: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:53.234: NIGPIBDD: Just before returning the error code
8:15:53.234: NIGPIBDD: ReceiveGPIO: 1

8:15:53.250: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:53.250: NIGPIBDD: SaveSendGPIO function entered
8:15:53.250: NIGPIBDD: Assigning zero string to sCommand
8:15:53.250: NIGPIBDD::SRQHandler: Before mcGPIOCommunication.Leave()
8:15:53.265: NIGPIBDD::SRQHandler: After mcGPIOCommunication.Leave()
8:15:53.265: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:15:53.265: NIGPIBDD: After mcGPIOCommunication.Enter()
8:15:53.281: NIGPIBDD::SaveSendGPIO: mISuggestedReadSize: 10
8:15:53.281: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:15:53.281: NIGPIBDD: After mcGPIOCommunication.Leave()
8:15:53.296: NIGPIBDD: Before mcGPIOCommunication.Enter()
8:15:53.296: NIGPIBDD: After mcGPIOCommunication.Enter()
8:15:53.296: NIGPIBDD: Before mcGPIOCommunication.Leave()
8:15:53.312: NIGPIBDD: After mcGPIOCommunication.Leave()
8:15:53.312: NIGPIBDD: Just before returning the error code
8:15:53.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) 1.26662E-026)
8:15:53.312: NIGPIBDD: SendGPIO: S2:INT_RELAY_A?

8:15:53.343: NIGPIBDD: ReceiveGPIO: NO

8:15:53.375: NIGPIBDD: SendGPIO: S2:INT_RELAY_A?

8:15:53.406: NIGPIBDD: ReceiveGPIO: NO

8:15:53.421: NIGPIBDD: SendGPIO: S2:INT_RELAY_A?

8:15:53.468: NIGPIBDD: ReceiveGPIO: NO

8:15:53.500: NIGPIBDD: SendGPIO: S2:INT_RELAY_A?

8:15:53.546: NIGPIBDD: ReceiveGPIO: NO

8:15:53.562: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:15:53.609: NIGPIBDD: ReceiveGPIO: NO

8:15:53.625: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:15:53.656: NIGPIBDD: ReceiveGPIO: NO

8:15:53.671: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:15:53.718: NIGPIBDD: ReceiveGPIO: NO

8:15:53.734: NIGPIBDD: SendGPIO: S3:INT_RELAY_A?

8:15:53.781: NIGPIBDD: ReceiveGPIO: NO

8:15:53.796: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:53.843: NIGPIBDD: ReceiveGPIB: NC

8:15:53.859: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:53.890: NIGPIBDD: ReceiveGPIB: NC

8:15:53.921: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:53.953: NIGPIBDD: ReceiveGPIB: NC

8:15:53.968: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:54.015: NIGPIBDD: ReceiveGPIB: NC

8:15:54.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:54.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:54.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:54.046: NIGPIBDD: SendGPIB: TR

8:15:54.046: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:54.093: NIGPIBDD: SendGPIB: TR

8:15:54.093: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:54.109: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.79 MHz, (Power) -1.82 dBm)

8:15:54.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:15:54.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:54.125: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:54.140: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:54.140: NIGPIBDD: SendGPIB: TR

8:15:54.156: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:54.171: NIGPIBDD: SendGPIB: TR

8:15:54.187: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:54.187: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.79 MHz, (Power) -8.34 dBm)

8:15:54.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)

8:15:54.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.41648E+030)

8:15:54.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)

8:15:54.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:15:54.250: NIGPIBDD: SendGPIB: 1N

8:15:54.390: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:54.390: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.79 MHz, (Power) -150 dBm)
8:15:54.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:54.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -1.51802E-014)
8:15:54.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:15:56.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:15:56.421: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:56.421: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:56.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:56.437: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:15:56.468: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:15:56.468: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:15:56.468: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:15:56.484: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:56.484: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:56.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:56.500: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:15:56.515: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:15:56.515: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:15:56.531: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:15:56.531: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:56.531: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:56.546: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:56.546: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:15:56.578: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:15:56.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:15:56.578: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:15:56.593: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:15:56.593: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:15:56.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:15:56.640: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:15:56.656: NIGPIBDD: ReceiveGPIB: 52.803E+0

8:15:56.656: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 52.803)

8:15:56.671: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)

8:15:56.671: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)

8:15:56.687: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:56.687: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:56.703: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:56.703: NIGPIBDD: SendGPIB: TR

8:15:56.718: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:56.750: NIGPIBDD: SendGPIB: TR

8:15:56.765: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:56.765: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.79 MHz, (Power) -1.82 dBm)

8:15:56.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 3.68935E+019)

8:15:56.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:56.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:56.781: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)

8:15:56.796: NIGPIBDD: SendGPIB: TR

8:15:56.812: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:56.843: NIGPIBDD: SendGPIB: TR

8:15:56.859: NIGPIBDD: ReceiveGPIB: 0,-1.82,0,-8.34

8:15:56.859: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.79 MHz, (Power) -8.34 dBm)

8:15:56.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)

8:15:56.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.41648E+030)

8:15:56.890: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -17.2537 dBm)

8:15:56.890: NIGPIBDD: SaveSendGPIB function entered

8:15:56.890: NIGPIBDD: Assigning zero string to sCommand

8:15:56.906: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:56.906: NIGPIBDD: After mcGPIBCommunication.Enter()

8:15:56.921: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:15:56.921: NIGPIBDD: SendGPIB: SOURCE:POWER -17.2537 DBM;*OPC?

8:15:56.921: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:15:56.921: NIGPIBDD: After mcGPIBCommunication.Leave()

8:15:56.937: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:15:56.937: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:15:56.937: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:15:56.937: NIGPIBDD: ReceiveGPIB: 1

 8:15:56.953: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:15:56.953: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:15:56.968: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:15:56.968: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:15:56.968: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:15:56.968: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:15:56.984: NIGPIBDD: Just before returning the error code
 8:15:56.984: NIGPIBDD: SaveSendGPIB function entered
 8:15:56.984: NIGPIBDD: Assigning zero string to sCommand
 8:15:57.000: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:15:57.000: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:15:57.000: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 10
 8:15:57.015: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:15:57.015: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:15:57.015: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:15:57.015: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:15:57.031: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:15:57.031: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:15:57.046: NIGPIBDD: Just before returning the error code
 8:15:57.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.05733E-035)
 8:15:57.046: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
 8:15:57.046: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)
 8:15:57.062: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)
 8:15:57.062: NIGPIBDD: SendGPIB: TR
 8:15:57.078: NIGPIBDD: ReceiveGPIB: 0,-1.95,0,-8.47
 8:15:57.109: NIGPIBDD: SendGPIB: TR
 8:15:57.125: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.47
 8:15:57.125: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.79 MHz, (Power) -1.96 dBm)
 8:15:57.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
 8:15:57.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
 8:15:57.156: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)
 8:15:57.156: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.79 MHz, (Attenuation) 40 dB)
 8:15:57.156: NIGPIBDD: SendGPIB: TR
 8:15:57.171: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.47
 8:15:57.203: NIGPIBDD: SendGPIB: TR
 8:15:57.218: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.47
 8:15:57.218: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.79 MHz, (Power) -8.47 dBm)
 8:15:57.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -3.68935E+019)

8:15:57.234: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) -2.41648E+030)
8:15:57.234: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.82 MHz)
8:15:57.250: NIGPIBDD: SaveSendGPIB function entered
8:15:57.250: NIGPIBDD: Assigning zero string to sCommand
8:15:57.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:57.265: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:57.265: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:15:57.265: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.82 MHZ,*OPC?

8:15:57.281: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:57.281: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:57.281: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:15:57.281: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:15:57.281: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:57.296: NIGPIBDD: ReceiveGPIB: 1

8:15:57.312: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:15:57.312: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:15:57.312: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:57.312: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:57.312: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:15:57.328: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:57.328: NIGPIBDD: Just before returning the error code
8:15:57.343: NIGPIBDD: SaveSendGPIB function entered
8:15:57.343: NIGPIBDD: Assigning zero string to sCommand
8:15:57.343: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:57.359: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:57.359: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:15:57.359: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:57.359: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:57.375: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:15:57.375: NIGPIBDD: After mcGPIBCommunication.Enter()
8:15:57.390: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:15:57.390: NIGPIBDD: After mcGPIBCommunication.Leave()
8:15:57.390: NIGPIBDD: Just before returning the error code
8:15:57.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -2.33147E-017)
8:15:57.406: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:57.453: NIGPIBDD: ReceiveGPIB: NO

8:15:57.484: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:57.500: NIGPIBDD: ReceiveGPIB: NO

8:15:57.531: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:57.562: NIGPIBDD: ReceiveGPIB: NO

8:15:57.593: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:15:57.640: NIGPIBDD: ReceiveGPIB: NO

8:15:57.656: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:57.703: NIGPIBDD: ReceiveGPIB: NO

8:15:57.734: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:57.765: NIGPIBDD: ReceiveGPIB: NO

8:15:57.781: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:57.812: NIGPIBDD: ReceiveGPIB: NO

8:15:57.828: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:15:57.875: NIGPIBDD: ReceiveGPIB: NO

8:15:57.890: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:57.937: NIGPIBDD: ReceiveGPIB: NC

8:15:57.968: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:58.000: NIGPIBDD: ReceiveGPIB: NC

8:15:58.015: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:58.046: NIGPIBDD: ReceiveGPIB: NC

8:15:58.078: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:15:58.109: NIGPIBDD: ReceiveGPIB: NC

8:15:58.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:15:58.421: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)

8:15:58.437: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)

8:15:58.437: NIGPIBDD: SendGPIB: TR

8:15:58.453: NIGPIBDD: ReceiveGPIB: 0,-1.95,0,-8.50

8:15:58.484: NIGPIBDD: SendGPIB: TR

8:15:58.500: NIGPIBDD: ReceiveGPIB: 0,-1.95,0,-8.50

8:15:58.500: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.82 MHz, (Power) -1.95 dBm)

8:15:58.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 2)

8:15:58.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:15:58.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:15:58.515: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:15:58.531: NIGPIBDD: SendGPIB: TR
8:15:58.546: NIGPIBDD: ReceiveGPIB: 0,-1.95,0,-8.49
8:15:58.578: NIGPIBDD: SendGPIB: TR
8:15:58.578: NIGPIBDD: ReceiveGPIB: 0,-1.95,0,-8.49
8:15:58.593: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.82 MHz, (Power) -8.49 dBm)
8:15:58.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)
8:15:58.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.83405E-026)
8:15:58.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)
8:15:58.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)
8:15:58.625: NIGPIBDD: SendGPIB: 1N
8:15:58.734: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

8:15:58.734: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.82 MHz, (Power) -150 dBm)
8:15:58.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)
8:15:58.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) -134.441)
8:15:58.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)
8:16:00.765: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)
8:16:00.765: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:00.765: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:00.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:16:00.781: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:16:00.812: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:16:00.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 0, (Data2) 3.7)
8:16:00.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 0, (Data2) 100)
8:16:00.812: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:00.828: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:00.828: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:16:00.843: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:16:00.859: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:16:00.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 1.4013E-045, (Data2) 0.58)
8:16:00.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 1.4013E-045, (Data2) 100)
8:16:00.890: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:00.890: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:00.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:16:00.890: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:16:00.921: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:16:00.921: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 2.8026E-045, (Data2) 0.2)
8:16:00.921: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 2.8026E-045, (Data2) 100)
8:16:00.953: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:00.968: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:00.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.78351E-044, (Data2) 0)
8:16:00.968: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:16:01.000: NIGPIBDD: ReceiveGPIB: 53.103E+0

8:16:01.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue, (Data1) 4.2039E-045, (Data2) 53.103)
8:16:01.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue, (Data1) 4.2039E-045, (Data2) 100)
8:16:01.015: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:16:01.031: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:16:01.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.031: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.046: NIGPIBDD: SendGPIB: TR
8:16:01.062: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.50
8:16:01.093: NIGPIBDD: SendGPIB: TR
8:16:01.093: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.50
8:16:01.109: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.82 MHz, (Power) -1.96 dBm)
8:16:01.109: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:16:01.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:16:01.125: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.140: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.140: NIGPIBDD: SendGPIB: TR
8:16:01.156: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.50
8:16:01.171: NIGPIBDD: SendGPIB: TR

8:16:01.203: NIGPIBDD: ReceiveGPIB: 0,-1.96,0,-8.50
8:16:01.203: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.82 MHz, (Power) -8.5 dBm)
8:16:01.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 0)
8:16:01.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.83405E-026)
8:16:01.234: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -17.3982 dBm)
8:16:01.234: NIGPIBDD: SaveSendGPIB function entered
8:16:01.234: NIGPIBDD: Assigning zero string to sCommand
8:16:01.234: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.250: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.250: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:16:01.265: NIGPIBDD: SendGPIB: SOURCE:POWER -17.3982 DBM;*OPC?

8:16:01.265: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.265: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.265: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.281: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:16:01.281: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:16:01.281: NIGPIBDD: ReceiveGPIB: 1

8:16:01.281: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:16:01.296: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:16:01.296: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.296: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:16:01.312: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.312: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.312: NIGPIBDD: Just before returning the error code
8:16:01.328: NIGPIBDD: SaveSendGPIB function entered
8:16:01.328: NIGPIBDD: Assigning zero string to sCommand
8:16:01.328: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.343: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.343: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:16:01.343: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.359: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.359: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.359: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.359: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.375: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.375: NIGPIBDD: Just before returning the error code
8:16:01.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 1.57658E+010)
8:16:01.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:16:01.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.390: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.406: NIGPIBDD: SendGPIB: TR
8:16:01.421: NIGPIBDD: ReceiveGPIB: 0,-2.11,0,-8.65

8:16:01.453: NIGPIBDD: SendGPIB: TR
8:16:01.453: NIGPIBDD: ReceiveGPIB: 0,-2.11,0,-8.65
8:16:01.468: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.82 MHz, (Power) -2.11 dBm)
8:16:01.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -1.0842E-019)
8:16:01.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:16:01.484: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.500: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.82 MHz, (Attenuation) 40 dB)
8:16:01.500: NIGPIBDD: SendGPIB: TR
8:16:01.515: NIGPIBDD: ReceiveGPIB: 0,-2.11,0,-8.65
8:16:01.546: NIGPIBDD: SendGPIB: TR
8:16:01.562: NIGPIBDD: ReceiveGPIB: 0,-2.11,0,-8.65
8:16:01.562: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.82 MHz, (Power) -8.65 dBm)
8:16:01.562: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) -2)
8:16:01.578: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.83405E-026)
8:16:01.578: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.85 MHz)
8:16:01.578: NIGPIBDD: SaveSendGPIB function entered
8:16:01.593: NIGPIBDD: Assigning zero string to sCommand
8:16:01.593: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.609: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.609: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:16:01.609: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.85 MHZ;*OPC?

8:16:01.609: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.625: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.625: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.625: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:16:01.640: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:16:01.640: NIGPIBDD: ReceiveGPIB: 1

8:16:01.640: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:16:01.656: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:16:01.656: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.656: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:16:01.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.671: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.671: NIGPIBDD: Just before returning the error code
8:16:01.687: NIGPIBDD: SaveSendGPIB function entered
8:16:01.687: NIGPIBDD: Assigning zero string to sCommand
8:16:01.687: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.687: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.703: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:16:01.703: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.703: NIGPIBDD: After mcGPIBCommunication.Leave()

8:16:01.718: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:01.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:01.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:01.734: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:01.734: NIGPIBDD: Just before returning the error code
8:16:01.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
9.80909E-045, (Data2) 4.17233E-008)
8:16:01.734: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:01.765: NIGPIBDD: ReceiveGPIB: NO

8:16:01.796: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:01.843: NIGPIBDD: ReceiveGPIB: NO

8:16:01.859: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:01.906: NIGPIBDD: ReceiveGPIB: NO

8:16:01.937: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:01.984: NIGPIBDD: ReceiveGPIB: NO

8:16:02.000: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:02.046: NIGPIBDD: ReceiveGPIB: NO

8:16:02.062: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:02.109: NIGPIBDD: ReceiveGPIB: NO

8:16:02.125: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:02.156: NIGPIBDD: ReceiveGPIB: NO

8:16:02.187: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:02.218: NIGPIBDD: ReceiveGPIB: NO

8:16:02.234: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:02.281: NIGPIBDD: ReceiveGPIB: NC

8:16:02.312: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:02.375: NIGPIBDD: ReceiveGPIB: NC

8:16:02.390: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:02.437: NIGPIBDD: ReceiveGPIB: NC

8:16:02.468: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:02.515: NIGPIBDD: ReceiveGPIO: NC

8:16:02.515: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)

8:16:02.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)

8:16:02.531: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)

8:16:02.531: NIGPIBDD: SendGPIO: TR

8:16:02.546: NIGPIBDD: ReceiveGPIO: 0,-2.10,0,-8.67

8:16:02.578: NIGPIBDD: SendGPIO: TR

8:16:02.593: NIGPIBDD: ReceiveGPIO: 0,-2.10,0,-8.67

8:16:02.593: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.85 MHz, (Power) -2.1 dBm)

8:16:02.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) -2)

8:16:02.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)

8:16:02.609: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)

8:16:02.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)

8:16:02.625: NIGPIBDD: SendGPIO: TR

8:16:02.640: NIGPIBDD: ReceiveGPIO: 0,-2.10,0,-8.67

8:16:02.671: NIGPIBDD: SendGPIO: TR

8:16:02.687: NIGPIBDD: ReceiveGPIO: 0,-2.10,0,-8.67

8:16:02.687: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.85 MHz, (Power) -8.67 dBm)

8:16:02.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 2)

8:16:02.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.49167E-006)

8:16:02.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.94273E-044, (Data2) 0)

8:16:02.718: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.66247E-044, (Data2) 0)

8:16:02.734: NIGPIBDD: SendGPIO: 1N

8:16:02.843: NIGPIBDD: ReceiveGPIO: DBA+0000E+0,3,0

8:16:02.859: DVDRSYS.DLL: GetValue((ID) 589826, (Function) PM_GetPower, (Freq) 0.85 MHz, (Power) -150 dBm)

8:16:02.859: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.08286E-044, (Data2) 0)

8:16:02.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-044, (Data2) 1.33296E-012)

8:16:02.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.26117E-044, (Data2) 0)

8:16:04.875: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.4013E-044, (Data2) 0)

8:16:04.875: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)

8:16:04.875: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)

8:16:04.890: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:16:04.906: NIGPIBDD: SendGPIB: :MEASU:MEAS1:VAL?

8:16:04.921: NIGPIBDD: ReceiveGPIB: 3.70E+0

8:16:04.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 0, (Data2) 3.7)
8:16:04.937: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 0, (Data2) 100)
8:16:04.953: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:04.953: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:04.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:16:04.968: NIGPIBDD: SendGPIB: :MEASU:MEAS2:VAL?

8:16:05.000: NIGPIBDD: ReceiveGPIB: 580.0E-3

8:16:05.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 1.4013E-045, (Data2) 0.58)
8:16:05.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 1.4013E-045, (Data2) 100)
8:16:05.000: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:05.015: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:05.015: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:16:05.031: NIGPIBDD: SendGPIB: :MEASU:MEAS3:VAL?

8:16:05.062: NIGPIBDD: ReceiveGPIB: 200.0E-3

8:16:05.062: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 2.8026E-045, (Data2) 0.2)
8:16:05.078: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 2.8026E-045, (Data2) 100)
8:16:05.078: DVDRSYS.DLL: GetValue((ID) 720896, (Function) Unknown)
8:16:05.078: DVDRSYS.DLL: SetValue((ID) 720896, (Function) Unknown)
8:16:05.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.78351E-044, (Data2) 0)
8:16:05.140: NIGPIBDD: SendGPIB: :MEASU:MEAS4:VAL?

8:16:05.171: NIGPIBDD: ReceiveGPIB: 53.360E+0

8:16:05.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelValue,
(Data1) 4.2039E-045, (Data2) 53.36)
8:16:05.171: DVDRSYS.DLL: GetValue((ID) 720896, (Function) AD_GetChannelMaxValue,
(Data1) 4.2039E-045, (Data2) 100)
8:16:05.187: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:16:05.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.22299E-044, (Data2) 0)
8:16:05.203: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)

8:16:05.218: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.218: NIGPIBDD: SendGPIB: TR
8:16:05.234: NIGPIBDD: ReceiveGPIB: 0,-2.10,0,-8.67
8:16:05.265: NIGPIBDD: SendGPIB: TR
8:16:05.281: NIGPIBDD: ReceiveGPIB: 0,-2.10,0,-8.67
8:16:05.281: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq)
0.85 MHz, (Power) -2.1 dBm)
8:16:05.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.36312E-044, (Data2) -2)
8:16:05.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.50325E-044, (Data2) 0)
8:16:05.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetForwardAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.312: DVDRSYS.DLL: GetValue((ID) 393216, (Function)
CP_GetReflectedAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.328: NIGPIBDD: SendGPIB: TR
8:16:05.343: NIGPIBDD: ReceiveGPIB: 0,-2.10,0,-8.67
8:16:05.375: NIGPIBDD: SendGPIB: TR
8:16:05.375: NIGPIBDD: ReceiveGPIB: 0,-2.10,0,-8.67
8:16:05.390: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq)
0.85 MHz, (Power) -8.67 dBm)
8:16:05.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
3.64338E-044, (Data2) 2)
8:16:05.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
7.56701E-044, (Data2) 1.49167E-006)
8:16:05.421: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel,
(Carrier) -17.5504 dBm)
8:16:05.437: NIGPIBDD: SaveSendGPIB function entered
8:16:05.437: NIGPIBDD: Assigning zero string to sCommand
8:16:05.437: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.453: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.453: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 0
8:16:05.453: NIGPIBDD: SendGPIB: SOURCE:POWER -17.5504 DBM;*OPC?

8:16:05.468: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.468: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.484: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:16:05.484: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:16:05.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.500: NIGPIBDD: ReceiveGPIB: 1

8:16:05.515: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:16:05.515: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:16:05.515: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.515: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.515: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:16:05.531: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.546: NIGPIBDD: Just before returning the error code
8:16:05.546: NIGPIBDD: SaveSendGPIB function entered
8:16:05.546: NIGPIBDD: Assigning zero string to sCommand
8:16:05.546: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:16:05.562: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.562: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:16:05.562: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.578: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.578: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.593: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.593: NIGPIBDD: Just before returning the error code
8:16:05.593: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) -0.359361)
8:16:05.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.22299E-044, (Data2) 0)
8:16:05.609: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.625: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.625: NIGPIBDD: SendGPIB: TR
8:16:05.640: NIGPIBDD: ReceiveGPIB: 0,-2.25,0,-8.81
8:16:05.671: NIGPIBDD: SendGPIB: TR
8:16:05.687: NIGPIBDD: ReceiveGPIB: 0,-2.25,0,-8.81
8:16:05.687: DVDRSYS.DLL: GetValue((ID) 458752, (Function) PM_MeasurePower, (Freq) 0.85 MHz, (Power) -2.25 dBm)
8:16:05.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.36312E-044, (Data2) 0)
8:16:05.703: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.50325E-044, (Data2) 0)
8:16:05.703: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetForwardAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.703: DVDRSYS.DLL: GetValue((ID) 393216, (Function) CP_GetReflectedAttenuation, (Freq) 0.85 MHz, (Attenuation) 40 dB)
8:16:05.718: NIGPIBDD: SendGPIB: TR
8:16:05.734: NIGPIBDD: ReceiveGPIB: 0,-2.25,0,-8.81
8:16:05.765: NIGPIBDD: SendGPIB: TR
8:16:05.765: NIGPIBDD: ReceiveGPIB: 0,-2.25,0,-8.81
8:16:05.781: DVDRSYS.DLL: GetValue((ID) 524289, (Function) PM_MeasurePower, (Freq) 0.85 MHz, (Power) -8.81 dBm)
8:16:05.781: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 3.64338E-044, (Data2) 3.68935E+019)
8:16:05.796: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.56701E-044, (Data2) 1.49167E-006)
8:16:05.796: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetFrequency, (Frequency) 0.88 MHz)
8:16:05.812: NIGPIBDD: SaveSendGPIB function entered
8:16:05.812: NIGPIBDD: Assigning zero string to sCommand
8:16:05.812: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.812: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.828: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:16:05.828: NIGPIBDD: SendGPIB: SOURCE:FREQ 0.88 MHZ;*OPC?

8:16:05.843: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.843: NIGPIBDD: After mcGPIBCommunication.Leave()

8:16:05.843: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:16:05.843: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:16:05.843: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.859: NIGPIBDD: ReceiveGPIB: 1

8:16:05.875: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:16:05.875: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:16:05.875: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.875: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.875: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:16:05.890: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.890: NIGPIBDD: Just before returning the error code
8:16:05.890: NIGPIBDD: SaveSendGPIB function entered
8:16:05.906: NIGPIBDD: Assigning zero string to sCommand
8:16:05.906: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.921: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.921: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:16:05.921: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.921: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:05.937: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:05.937: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:05.937: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:05.953: NIGPIBDD: Just before returning the error code
8:16:05.953: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 9.80909E-045, (Data2) -71.68)
8:16:05.968: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:06.000: NIGPIBDD: ReceiveGPIB: NO

8:16:06.015: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:06.046: NIGPIBDD: ReceiveGPIB: NO

8:16:06.078: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:06.125: NIGPIBDD: ReceiveGPIB: NO

8:16:06.140: NIGPIBDD: SendGPIB: S2:INT_RELAY_A?

8:16:06.187: NIGPIBDD: ReceiveGPIB: NO

8:16:06.218: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:06.250: NIGPIBDD: ReceiveGPIB: NO

8:16:06.265: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:06.296: NIGPIBDD: ReceiveGPIB: NO

8:16:06.328: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:06.359: NIGPIBDD: ReceiveGPIB: NO

8:16:06.375: NIGPIBDD: SendGPIB: S3:INT_RELAY_A?

8:16:06.421: NIGPIBDD: ReceiveGPIB: NO

8:16:06.453: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:06.484: NIGPIBDD: ReceiveGPIB: NC

8:16:06.515: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:06.546: NIGPIBDD: ReceiveGPIB: NC

8:16:06.562: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:06.593: NIGPIBDD: ReceiveGPIB: NC

8:16:06.625: NIGPIBDD: SendGPIB: S4:INT_RELAY_A?

8:16:06.671: NIGPIBDD: ReceiveGPIB: NC

8:16:06.968: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierOff)

8:16:06.968: NIGPIBDD: SaveSendGPIB function entered

8:16:06.984: NIGPIBDD: Assigning zero string to sCommand

8:16:06.984: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:16:06.984: NIGPIBDD: After mcGPIBCommunication.Enter()

8:16:06.984: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0

8:16:07.000: NIGPIBDD: SendGPIB: OUTPUT OFF;*OPC?

8:16:07.000: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:16:07.015: NIGPIBDD: After mcGPIBCommunication.Leave()

8:16:07.015: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:16:07.015: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()

8:16:07.015: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()

8:16:07.031: NIGPIBDD: ReceiveGPIB: 1

8:16:07.031: NIGPIBDD: After CheckDeviceSpecificStatusRegister

8:16:07.031: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()

8:16:07.031: NIGPIBDD: After mcGPIBCommunication.Enter()

8:16:07.031: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()

8:16:07.046: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:16:07.062: NIGPIBDD: After mcGPIBCommunication.Leave()

8:16:07.062: NIGPIBDD: Just before returning the error code

8:16:07.078: NIGPIBDD: SaveSendGPIB function entered

8:16:07.078: NIGPIBDD: Assigning zero string to sCommand

8:16:07.078: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:16:07.078: NIGPIBDD: After mcGPIBCommunication.Enter()

8:16:07.093: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10

8:16:07.093: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:16:07.109: NIGPIBDD: After mcGPIBCommunication.Leave()

8:16:07.109: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:16:07.109: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:07.109: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:07.125: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:07.125: NIGPIBDD: Just before returning the error code
8:16:07.140: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:07.140: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:07.156: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:07.156: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:07.171: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 7.00649E-045, (Data2) 0)
8:16:07.828: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierOff)
8:16:08.921: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierOff)
8:16:08.921: DVDRSYS.DLL: SetValue((ID) 327680, (Function) SG_SetCarrierLevel, (Carrier) -80 dBm)
8:16:08.937: NIGPIBDD: SaveSendGPIB function entered
8:16:08.937: NIGPIBDD: Assigning zero string to sCommand
8:16:08.953: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:08.953: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:08.953: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:16:08.953: NIGPIBDD: SendGPIB: SOURCE:POWER -80 DBM;*OPC?

8:16:08.968: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:08.968: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:08.984: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:08.984: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:08.984: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:16:09.000: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:09.015: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:16:09.015: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:09.015: NIGPIBDD: ReceiveGPIB: 1

8:16:09.015: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:16:09.015: NIGPIBDD: Just before returning the error code
8:16:09.031: NIGPIBDD: SaveSendGPIB function entered
8:16:09.031: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:16:09.046: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:16:09.046: NIGPIBDD: Assigning zero string to sCommand
8:16:09.046: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:09.062: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:09.062: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:16:09.062: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:09.062: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:09.078: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:16:09.078: NIGPIBDD: After mcGPIBCommunication.Enter()
8:16:09.078: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:16:09.093: NIGPIBDD: After mcGPIBCommunication.Leave()
8:16:09.093: NIGPIBDD: Just before returning the error code
8:16:09.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 1.12104E-044, (Data2) 0)
8:16:09.109: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_StandBy)
8:16:09.109: NIGPIBDD: SendGPIB: S

8:16:09.312: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:09.312: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:09.328: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:09.328: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:09.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.8026E-045, (Data2) 0)
8:16:09.375: NIGPIBDD: SendGPIO: S2:INT_RELAY_A_NC

8:16:09.453: NIGPIBDD: ReceiveGPIO: NC

8:16:09.468: NIGPIBDD: SendGPIO: S2:INT_RELAY_B_NC

8:16:09.593: NIGPIBDD: ReceiveGPIO: NC

8:16:09.609: NIGPIBDD: SendGPIO: S3:INT_RELAY_A_NC

8:16:09.703: NIGPIBDD: ReceiveGPIO: NC

8:16:09.718: NIGPIBDD: SendGPIO: S3:INT_RELAY_B_NC

8:16:09.812: NIGPIBDD: ReceiveGPIO: NC

8:16:09.812: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_StandBy)
8:16:13.312: NIGPIBDD: SendGPIO: S

8:16:13.515: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:13.531: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:13.531: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:13.546: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:13.546: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_PowerOff)
8:16:17.718: NIGPIBDD: SendGPIO: P0

8:16:17.921: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:17.953: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:17.953: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:17.968: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:17.968: DVDRSYS.DLL: SetValue((ID) 196611, (Function) Unknown)
8:16:18.109: DVDRSYS.DLL: DelInitDevice((ID) 262144)
8:16:18.140: NIGPIBDD: SendGPIO: S2LOCAL

8:16:18.171: NIGPIBDD: ReceiveGPIO: OK

8:16:18.296: NIGPIBDD: SendGPIO: S3LOCAL

8:16:18.359: NIGPIBDD: ReceiveGPIO: OK

8:16:18.500: NIGPIBDD: SendGPIO: S4LOCAL

8:16:18.578: NIGPIBDD: ReceiveGPIO: OK

8:16:18.671: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 262144)
8:16:18.671: DVDRSYS.DLL: Going to call CallUnregistered()

8:16:18.671: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.687: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:18.687: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.687: DVDRSYS.DLL: Going to unload Library
8:16:18.703: DVDRSYS.DLL: Going to release names
8:16:18.703: DVDRSYS.DLL: DelnitDevice((ID) 327680)
8:16:18.703: NIGPIBDD: SendGPIB: *SRE 0
8:16:18.718: NIGPIBDD: SendGPIB: *ESE 0
8:16:18.718: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 327680)
8:16:18.734: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.734: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.734: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:18.734: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.750: DVDRSYS.DLL: Going to unload Library
8:16:18.750: DVDRSYS.DLL: Going to release names
8:16:18.765: DVDRSYS.DLL: DelnitDevice((ID) 393216)
8:16:18.765: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 393216)
8:16:18.765: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.765: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.781: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:18.781: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.781: DVDRSYS.DLL: Going to unload Library
8:16:18.796: DVDRSYS.DLL: Going to release names
8:16:18.796: DVDRSYS.DLL: DelnitDevice((ID) 458752)
8:16:18.812: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 458752)
8:16:18.812: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.812: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.828: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:18.828: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.843: DVDRSYS.DLL: Going to unload Library
8:16:18.843: DVDRSYS.DLL: Going to release names
8:16:18.843: DVDRSYS.DLL: DelnitDevice((ID) 524289)
8:16:18.859: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 524289)
8:16:18.875: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.875: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.875: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:18.875: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.890: DVDRSYS.DLL: Going to unload Library
8:16:18.890: DVDRSYS.DLL: Going to release names
8:16:18.890: DVDRSYS.DLL: DelnitDevice((ID) 589826)
8:16:18.906: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 589826)
8:16:18.906: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.906: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.921: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:18.921: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.921: DVDRSYS.DLL: Going to unload Library
8:16:18.921: DVDRSYS.DLL: Going to release names
8:16:18.937: DVDRSYS.DLL: DelnitDevice((ID) 655360)
8:16:18.937: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 655360)
8:16:18.953: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.953: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:18.953: DVDRSYS.DLL: Going to call ClearFunctionPointers()

8:16:18.953: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:18.968: DVDRSYS.DLL: Going to unload Library
8:16:18.968: DVDRSYS.DLL: Going to release names
8:16:18.984: DVDRSYS.DLL: DelnitDevice((ID) 720896)
8:16:18.984: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 720896)
8:16:18.984: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:18.984: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:19.000: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:19.000: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:19.015: DVDRSYS.DLL: Going to unload Library
8:16:19.015: DVDRSYS.DLL: Going to release names
8:16:19.015: DVDRSYS.DLL: DelnitDevice((ID) 786433)
8:16:19.015: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 786433)
8:16:19.031: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:19.031: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:19.031: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:19.046: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:19.046: DVDRSYS.DLL: Going to unload Library
8:16:19.046: DVDRSYS.DLL: Going to release names
8:16:19.062: DVDRSYS.DLL: DelnitDevice((ID) 851972)
8:16:19.062: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 851972)
8:16:19.062: DVDRSYS.DLL: Going to call CallUnregistered()
8:16:19.078: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:16:19.078: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:16:19.078: DVDRSYS.DLL: Going to call SetLowHandleID()
8:16:19.093: DVDRSYS.DLL: Going to unload Library
8:16:19.093: DVDRSYS.DLL: Going to release names
8:16:23.093: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:23.093: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:23.093: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:23.093: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:28.109: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:28.109: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:28.109: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:28.109: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:33.125: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:33.125: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:33.125: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:33.125: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:38.140: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:38.140: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:38.140: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:38.140: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:43.156: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:43.156: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:43.156: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:43.156: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:48.171: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:16:48.171: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:16:48.171: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:16:48.171: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:16:53.187: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)

[illegible]

[illegible]

[illegible]

8:20:08.796: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:08.796: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:08.796: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:13.812: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:20:13.812: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:13.812: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:13.812: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:18.828: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:20:18.828: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:18.828: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:18.828: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:23.843: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:20:23.843: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:23.843: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:23.843: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:28.859: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:20:28.859: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:28.859: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:28.859: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:33.875: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:20:33.875: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:33.875: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:33.875: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:39.171: DVDRSYS.DLL: Going to re-use already existing unused device driver data
on index: 4
8:20:39.171: DVDRSYS.DLL: Going to call LoadLibrary for the 15th time
8:20:39.171: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE
Development\RadiMation\Version 5.8.37\RADSWTCH.DLL
8:20:39.234: DVDRSYS.DLL: Going to create device driver: RADICENTREMULTISWITCH
8:20:39.250: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:20:39.250: DVDRSYS.DLL: RegisterDeviceDriver((Device)
RADICENTREMULTISWITCH, (DLL) C:\Programme\DARE
Development\RadiMation\Version 5.8.37\RADSWTCH.DLL) returns (ID) 262144
8:20:39.250: DVDRSYS.DLL: LoadConfiguration((ID) 262144, (FileName)
C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC44757.INI)
8:20:39.296: DVDRSYS.DLL: CheckDevice((ID) 262144)
8:20:40.468: NIGPIBDD: SendGPIB: S2:*IDN?

8:20:40.531: NIGPIBDD: ReceiveGPIB: RSW1002A, Version 2.0.12

8:20:40.562: NIGPIBDD: SendGPIB: S2LOCAL

8:20:40.765: NIGPIBDD: ReceiveGPIB: OK

8:20:42.000: NIGPIBDD: SendGPIB: S3:*IDN?

8:20:42.062: NIGPIBDD: ReceiveGPIB: RSW1004A, Version 2.0.12

8:20:42.109: NIGPIBDD: SendGPIB: S3LOCAL

8:20:42.343: NIGPIBDD: ReceiveGPIB: OK

8:20:43.578: NIGPIBDD: SendGPIB: S4:*IDN?

8:20:43.640: NIGPIBDD: ReceiveGPIB: RSW1002A, Version 3.2.0

8:20:43.687: NIGPIBDD: SendGPIB: S4LOCAL

8:20:43.921: NIGPIBDD: ReceiveGPIB: OK

8:20:44.015: DVDRSYS.DLL: InitDevice((ID) 262144)

8:20:47.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 4.2039E-045, (Data2) 0)

8:20:47.468: NIGPIBDD: SendGPIB: S2:INT_RELAY_A_NO

8:20:47.562: NIGPIBDD: ReceiveGPIB: NO

8:20:47.578: NIGPIBDD: SendGPIB: S2:INT_RELAY_B_NO

8:20:47.656: NIGPIBDD: ReceiveGPIB: NO

8:20:47.687: NIGPIBDD: SendGPIB: S3:INT_RELAY_A_NO

8:20:47.968: NIGPIBDD: ReceiveGPIB: NO

8:20:48.000: NIGPIBDD: SendGPIB: S3:INT_RELAY_B_NO

8:20:48.078: NIGPIBDD: ReceiveGPIB: NO

8:20:48.093: NIGPIBDD: SendGPIB: S4:INT_RELAY_A_NC

8:20:48.203: NIGPIBDD: ReceiveGPIB: NC

8:20:48.234: NIGPIBDD: SendGPIB: S4:INT_RELAY_B_NC

8:20:48.312: NIGPIBDD: ReceiveGPIB: NC

8:20:48.312: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)

8:20:48.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)

8:20:48.328: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 5

8:20:48.343: DVDRSYS.DLL: Going to call LoadLibrary for the 16th time

8:20:48.343: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADRSSG.DLL

8:20:48.421: DVDRSYS.DLL: Going to create device driver: RSSMA100A

8:20:48.421: DVDRSYS.DLL: Going to call 'Registered' of the device driver

8:20:48.437: DVDRSYS.DLL: RegisterDeviceDriver((Device) RSSMA100A, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADRSSG.DLL) returns (ID) 327680

8:20:48.437: DVDRSYS.DLL: LoadConfiguration((ID) 327680, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC78466.INI)

8:20:48.453: DVDRSYS.DLL: CheckDevice((ID) 327680)

8:20:48.468: NIGPIBDD: SendGPIB: *CLS
 8:20:48.484: NIGPIBDD: SendGPIB: *SRE 48
 8:20:48.484: NIGPIBDD: SendGPIB: *ESE 1
 8:20:48.484: NIGPIBDD: SaveSendGPIB function entered
 8:20:48.484: NIGPIBDD: Assigning zero string to sCommand
 8:20:48.500: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:20:48.500: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:20:48.500: NIGPIBDD::SaveSendGPIB: mISuggestedReadSize: 100
 8:20:48.515: NIGPIBDD: SendGPIB: *IDN?

 8:20:48.515: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:20:48.515: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:20:48.531: NIGPIBDD::SaveSendGPIB: mISendTimeoutMilliseconds: 10000
 8:20:48.531: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
 8:20:48.531: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
 8:20:48.546: NIGPIBDD::SRQHandler: mISuggestedReadSize: 100
 8:20:48.546: NIGPIBDD: ReceiveGPIB:
 Rohde&Schwarz,SMA100A,1400.0000k02/100580,2.2.2.3-2.05.220.02 (Release)

 8:20:48.546: NIGPIBDD: After CheckDeviceSpecificStatusRegister
 8:20:48.562: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:20:48.562: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
 8:20:48.562: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:20:48.562: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:20:48.578: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:20:48.578: NIGPIBDD: Just before returning the error code
 8:20:48.562: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
 8:20:48.593: NIGPIBDD: SendGPIB: *SRE 0
 8:20:48.593: NIGPIBDD: SendGPIB: *ESE 0
 8:20:48.609: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3001) returned: 9000
 8:20:48.609: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3002) returned: 6E+009
 8:20:48.609: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
 2.24208E-044, (Data2) 0)
 8:20:48.625: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
 2.10195E-044, (Data2) 0)
 8:20:48.625: DVDRSYS.DLL: Going to re-use already existing unused device driver data
 on index: 6
 8:20:48.640: DVDRSYS.DLL: Going to call LoadLibrary for the 17th time
 8:20:48.640: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE
 Development\RadiMation\Version 5.8.37\RADEEMPTY.DLL
 8:20:48.703: DVDRSYS.DLL: Going to create device driver: CONFIGCO
 8:20:48.703: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:20:48.718: DVDRSYS.DLL: RegisterDeviceDriver((Device) CONFIGCO, (DLL)
 C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADEEMPTY.DLL) returns
 (ID) 393216
 8:20:48.718: DVDRSYS.DLL: LoadConfiguration((ID) 393216, (FileName)
 C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC58699.INI)
 8:20:48.718: DVDRSYS.DLL: CheckDevice((ID) 393216)
 8:20:48.718: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3001) returned: 1
 8:20:48.734: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3002) returned: 1E+009
 8:20:48.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
 2.24208E-044, (Data2) 0)

8:20:48.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:20:48.750: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 7
8:20:48.765: DVDRSYS.DLL: Going to call LoadLibrary for the 18th time
8:20:48.765: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTPM.DLL
8:20:48.796: DVDRSYS.DLL: Going to create device driver: ARPM20021
8:20:48.796: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:20:48.812: DVDRSYS.DLL: RegisterDeviceDriver((Device) ARPM20021, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTPM.DLL) returns (ID) 458752
8:20:48.812: DVDRSYS.DLL: LoadConfiguration((ID) 458752, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC17636.INI)
8:20:48.828: DVDRSYS.DLL: CheckDevice((ID) 458752)
8:20:49.437: NIGPIBDD: SendGPIB: *IDN?
8:20:49.468: NIGPIBDD: ReceiveGPIB: Amplifier Research,PM2002 RF Powermeter,321947,Ver 4.10
8:20:49.468: NIGPIBDD: SendGPIB: CH1;DB;FA;MN
8:20:49.578: NIGPIBDD: SendGPIB: TM3
8:20:49.687: NIGPIBDD: SendGPIB: TR
8:20:49.703: NIGPIBDD: ReceiveGPIB: 0,-68.05,0,-70.01
8:20:49.718: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3001) returned: 1000
8:20:49.734: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3002) returned: 4.01E+010
8:20:49.734: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
8:20:49.750: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
8:20:49.750: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 8
8:20:49.765: DVDRSYS.DLL: Going to call LoadLibrary for the 19th time
8:20:49.765: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTPM.DLL
8:20:49.781: DVDRSYS.DLL: Going to create device driver: ARPM20022
8:20:49.781: DVDRSYS.DLL: Going to call 'Registered' of the device driver
8:20:49.781: DVDRSYS.DLL: RegisterDeviceDriver((Device) ARPM20022, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTPM.DLL) returns (ID) 524289
8:20:49.781: DVDRSYS.DLL: LoadConfiguration((ID) 524289, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC91617.INI)
8:20:49.812: DVDRSYS.DLL: CheckDevice((ID) 524289)
8:20:50.546: NIGPIBDD: SendGPIB: *IDN?
8:20:50.562: NIGPIBDD: ReceiveGPIB: Amplifier Research,PM2002 RF Powermeter,321947,Ver 4.10
8:20:50.562: NIGPIBDD: SendGPIB: CH2;DB;FA;MN
8:20:50.687: NIGPIBDD: SendGPIB: TM3
8:20:50.781: NIGPIBDD: SendGPIB: TR
8:20:51.234: NIGPIBDD: ReceiveGPIB: 0,-68.05,0,-65.10
8:20:51.250: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3001) returned: 1000
8:20:51.265: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3002) returned: 4.01E+010

8:20:51.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:20:51.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:20:51.296: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 9
 8:20:51.296: DVDRSYS.DLL: Going to call LoadLibrary for the 20th time
 8:20:51.296: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTPM.DLL
 8:20:51.312: DVDRSYS.DLL: Going to create device driver: BT9200B1
 8:20:51.312: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:20:51.328: DVDRSYS.DLL: RegisterDeviceDriver((Device) BT9200B1, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBTPM.DLL) returns (ID) 589826
 8:20:51.328: DVDRSYS.DLL: LoadConfiguration((ID) 589826, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC13072.INI)
 8:20:51.343: DVDRSYS.DLL: CheckDevice((ID) 589826)
 8:20:51.859: NIGPIBDD: SendGPIB: 1N
 8:20:51.968: NIGPIBDD: ReceiveGPIB: DBA+0000E+0,3,0

 8:20:51.968: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3001) returned: 1000
 8:20:51.984: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3002) returned: 1.81E+010
 8:20:51.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:20:52.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:20:52.015: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 10
 8:20:52.031: DVDRSYS.DLL: Going to call LoadLibrary for the 21th time
 8:20:52.031: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL
 8:20:52.078: DVDRSYS.DLL: Going to create device driver: FCCF65
 8:20:52.093: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:20:52.093: DVDRSYS.DLL: RegisterDeviceDriver((Device) FCCF65, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL) returns (ID) 655360
 8:20:52.093: DVDRSYS.DLL: LoadConfiguration((ID) 655360, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC82044.INI)
 8:20:52.109: DVDRSYS.DLL: CheckDevice((ID) 655360)
 8:20:52.109: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3001) returned: 100000
 8:20:52.125: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3002) returned: 1E+009
 8:20:52.125: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:20:52.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:20:52.140: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 11
 8:20:52.156: DVDRSYS.DLL: Going to call LoadLibrary for the 22th time
 8:20:52.156: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADAD.DLL
 8:20:52.234: DVDRSYS.DLL: Going to create device driver: TEKTRONIXTDS500A

8:20:52.234: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:20:52.234: DVDRSYS.DLL: RegisterDeviceDriver((Device) TEKTRONIXTDS500A, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADAD.DLL) returns (ID) 720896
 8:20:52.234: DVDRSYS.DLL: LoadConfiguration((ID) 720896, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC39053.INI)
 8:20:52.250: DVDRSYS.DLL: CheckDevice((ID) 720896)
 8:20:52.265: NIGPIBDD: SendGPIB: *IDN?
 8:20:52.281: NIGPIBDD: ReceiveGPIB: TEKTRONIX,TDS 544A,0,CF:91.1CT FV:v3.7e

 8:20:52.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:20:52.296: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:20:52.296: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 12
 8:20:52.312: DVDRSYS.DLL: Going to call LoadLibrary for the 23th time
 8:20:52.312: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL
 8:20:52.312: DVDRSYS.DLL: Going to create device driver: FCCF140A
 8:20:52.312: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:20:52.328: DVDRSYS.DLL: RegisterDeviceDriver((Device) FCCF140A, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\RADBCI.DLL) returns (ID) 786433
 8:20:52.328: DVDRSYS.DLL: LoadConfiguration((ID) 786433, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC61487.INI)
 8:20:52.343: DVDRSYS.DLL: CheckDevice((ID) 786433)
 8:20:52.343: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3001) returned: 100000
 8:20:52.343: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3002) returned: 1.3E+009
 8:20:52.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:20:52.359: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.10195E-044, (Data2) 0)
 8:20:52.375: DVDRSYS.DLL: Going to re-use already existing unused device driver data on index: 13
 8:20:52.375: DVDRSYS.DLL: Going to call LoadLibrary for the 24th time
 8:20:52.375: DVDRSYS.DLL: Going to load Library: C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL
 8:20:52.390: DVDRSYS.DLL: Going to create device driver: AR150A100BC
 8:20:52.390: DVDRSYS.DLL: Going to call 'Registered' of the device driver
 8:20:52.390: DVDRSYS.DLL: RegisterDeviceDriver((Device) AR150A100BC, (DLL) C:\Programme\DARE Development\RadiMation\Version 5.8.37\ARAMP.DLL) returns (ID) 851972
 8:20:52.390: DVDRSYS.DLL: LoadConfiguration((ID) 851972, (FileName) C:\Programme\DARE Development\RadiMation\CONFDVDR\RDC79755.INI)
 8:20:52.406: DVDRSYS.DLL: CheckDevice((ID) 851972)
 8:20:52.421: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3001) returned: 10000
 8:20:52.437: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3002) returned: 100000000
 8:20:52.437: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.24208E-044, (Data2) 0)
 8:20:52.453: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)

8:20:52.453: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:52.453: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:52.453: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:52.468: DVDRSYS.DLL: GetValue((ID) 262144, (Function) Unknown)
8:20:52.468: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:20:52.484: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
4.2039E-045, (Data2) 0)
8:20:52.484: NIGPIBDD: SendGPIB: S2:INT_RELAY_A_NO

8:20:52.562: NIGPIBDD: ReceiveGPIB: NO

8:20:52.578: NIGPIBDD: SendGPIB: S2:INT_RELAY_B_NO

8:20:52.656: NIGPIBDD: ReceiveGPIB: NO

8:20:52.671: NIGPIBDD: SendGPIB: S3:INT_RELAY_A_NO

8:20:52.765: NIGPIBDD: ReceiveGPIB: NO

8:20:52.781: NIGPIBDD: SendGPIB: S3:INT_RELAY_B_NO

8:20:52.859: NIGPIBDD: ReceiveGPIB: NO

8:20:52.890: NIGPIBDD: SendGPIB: S4:INT_RELAY_A_NC

8:20:52.953: NIGPIBDD: ReceiveGPIB: NC

8:20:52.984: NIGPIBDD: SendGPIB: S4:INT_RELAY_B_NC

8:20:53.062: NIGPIBDD: ReceiveGPIB: NC

8:20:53.062: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:20:53.093: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:20:53.093: DVDRSYS.DLL: InitDevice((ID) 327680)
8:20:53.125: NIGPIBDD: SendGPIB: *CLS
8:20:53.125: NIGPIBDD: SendGPIB: *SRE 48
8:20:53.125: NIGPIBDD: SendGPIB: *ESE 1
8:20:53.140: NIGPIBDD: SaveSendGPIB function entered
8:20:53.140: NIGPIBDD: Assigning zero string to sCommand
8:20:53.140: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.156: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.156: NIGPIBDD: SaveSendGPIB: mlSuggestedReadSize: 0
8:20:53.171: NIGPIBDD: SendGPIB: *RST

8:20:53.171: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.187: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.187: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.203: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.203: NIGPIBDD: Before mcGPIBCommunication.Leave()

8:20:53.203: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.203: NIGPIBDD: Just before returning the error code
8:20:53.312: NIGPIBDD: SaveSendGPIB function entered
8:20:53.328: NIGPIBDD: Assigning zero string to sCommand
8:20:53.328: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.328: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.343: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:20:53.343: NIGPIBDD: SendGPIB: *OPT?

8:20:53.359: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.359: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.375: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:20:53.375: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:20:53.390: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.390: NIGPIBDD: ReceiveGPIB: SMA-B20, SMA-B81, SMA-B106

8:20:53.390: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:20:53.390: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:20:53.406: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.406: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.406: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:20:53.421: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.437: NIGPIBDD: Just before returning the error code
8:20:53.437: NIGPIBDD: SaveSendGPIB function entered
8:20:53.453: NIGPIBDD: Assigning zero string to sCommand
8:20:53.453: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.453: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.453: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 99
8:20:53.468: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.468: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.484: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.484: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.500: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.500: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.500: NIGPIBDD: Just before returning the error code
8:20:53.500: NIGPIBDD: SaveSendGPIB function entered
8:20:53.515: NIGPIBDD: Assigning zero string to sCommand
8:20:53.515: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.515: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.515: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:20:53.531: NIGPIBDD: SendGPIB: :ROSC:SOUR INT;*OPC?

8:20:53.531: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.546: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.546: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.546: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.546: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.562: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.562: NIGPIBDD: Just before returning the error code
8:20:53.562: NIGPIBDD: SaveSendGPIB function entered
8:20:53.578: NIGPIBDD: Assigning zero string to sCommand
8:20:53.578: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:20:53.578: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.593: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:20:53.593: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.593: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.593: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.609: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.609: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.625: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.625: NIGPIBDD: Just before returning the error code
8:20:53.625: NIGPIBDD: SaveSendGPIB function entered
8:20:53.625: NIGPIBDD: Assigning zero string to sCommand
8:20:53.640: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.640: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.640: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:20:53.640: NIGPIBDD: SendGPIB: SOURCE:FREQ:MODE CW;*OPC?

8:20:53.656: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.656: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.671: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.671: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.671: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.671: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.687: NIGPIBDD: Just before returning the error code
8:20:53.687: NIGPIBDD: SaveSendGPIB function entered
8:20:53.703: NIGPIBDD: Assigning zero string to sCommand
8:20:53.703: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.703: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.703: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:20:53.718: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.718: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.718: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.718: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.734: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:20:53.734: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.750: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:20:53.750: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.750: NIGPIBDD: Just before returning the error code
8:20:53.750: NIGPIBDD: SaveSendGPIB function entered
8:20:53.765: NIGPIBDD: ReceiveGPIB: 1

8:20:53.765: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:20:53.765: NIGPIBDD: Assigning zero string to sCommand
8:20:53.765: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.781: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:20:53.781: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:20:53.781: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.796: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:20:53.796: NIGPIBDD: SendGPIB: OUTPUT OFF;*OPC?

8:20:53.796: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.812: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.812: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:20:53.812: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.828: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.828: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.828: NIGPIBDD: Just before returning the error code
8:20:53.843: NIGPIBDD: SaveSendGPIB function entered
8:20:53.843: NIGPIBDD: Assigning zero string to sCommand
8:20:53.843: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.843: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.859: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:20:53.859: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:20:53.875: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.875: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:20:53.875: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.875: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.890: NIGPIBDD: ReceiveGPIB: 1

8:20:53.890: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:20:53.890: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:20:53.890: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.890: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:20:53.906: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.921: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.921: NIGPIBDD: Just before returning the error code
8:20:53.921: NIGPIBDD: SaveSendGPIB function entered
8:20:53.921: NIGPIBDD: Assigning zero string to sCommand
8:20:53.937: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.937: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.937: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 0
8:20:53.953: NIGPIBDD: SendGPIB: SOURCE:AM:STATE OFF;*OPC?

8:20:53.953: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.953: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.968: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:53.968: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:53.968: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Enter()
8:20:53.968: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:53.984: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Enter()
8:20:53.984: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:53.984: NIGPIBDD: ReceiveGPIB: 1

8:20:54.000: NIGPIBDD: After CheckDeviceSpecificStatusRegister
8:20:54.000: NIGPIBDD: Just before returning the error code
8:20:54.000: NIGPIBDD: SaveSendGPIB function entered
8:20:54.015: NIGPIBDD::SRQHandler: Before mcGPIBCommunication.Leave()
8:20:54.015: NIGPIBDD::SRQHandler: After mcGPIBCommunication.Leave()
8:20:54.015: NIGPIBDD: Assigning zero string to sCommand
8:20:54.015: NIGPIBDD: Before mcGPIBCommunication.Enter()
8:20:54.031: NIGPIBDD: After mcGPIBCommunication.Enter()
8:20:54.031: NIGPIBDD::SaveSendGPIB: mlSuggestedReadSize: 10
8:20:54.046: NIGPIBDD: Before mcGPIBCommunication.Leave()
8:20:54.046: NIGPIBDD: After mcGPIBCommunication.Leave()
8:20:54.046: NIGPIBDD: Before mcGPIBCommunication.Enter()

8:20:54.046: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:20:54.062: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:20:54.062: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:20:54.062: NIGPIBDD: Just before returning the error code
 8:20:54.062: NIGPIBDD: SaveSendGPIB function entered
 8:20:54.078: NIGPIBDD: Assigning zero string to sCommand
 8:20:54.078: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:20:54.093: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:20:54.093: NIGPIBDD: SaveSendGPIB: mlSuggestedReadSize: 0
 8:20:54.093: NIGPIBDD: SendGPIB: :SYST:SEC ON

 8:20:54.093: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:20:54.109: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:20:54.109: NIGPIBDD: Before mcGPIBCommunication.Enter()
 8:20:54.109: NIGPIBDD: After mcGPIBCommunication.Enter()
 8:20:54.125: NIGPIBDD: Before mcGPIBCommunication.Leave()
 8:20:54.125: NIGPIBDD: After mcGPIBCommunication.Leave()
 8:20:54.125: NIGPIBDD: Just before returning the error code
 8:20:54.140: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3001) returned: 9000
 8:20:54.140: DVDRSYS.DLL: GetInfoString((ID) 327680, (InfoID) 3002) returned: 6E+009
 8:20:54.140: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
 8:20:54.156: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
 8:20:54.156: DVDRSYS.DLL: InitDevice((ID) 393216)
 8:20:54.187: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3001) returned: 1
 8:20:54.187: DVDRSYS.DLL: GetInfoString((ID) 393216, (InfoID) 3002) returned: 1E+009
 8:20:54.203: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
 8:20:54.218: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
 8:20:54.218: DVDRSYS.DLL: InitDevice((ID) 458752)
 8:20:54.531: NIGPIBDD: SendGPIB: CL;
 8:20:54.734: NIGPIBDD: SendGPIB: CH1;DB;FA;MN;TM3;
 8:20:54.953: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3001) returned: 1000
 8:20:54.953: DVDRSYS.DLL: GetInfoString((ID) 458752, (InfoID) 3002) returned: 4.01E+010
 8:20:54.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
 8:20:54.984: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
 8:20:55.000: DVDRSYS.DLL: InitDevice((ID) 524289)
 8:20:55.531: NIGPIBDD: SendGPIB: CL;
 8:20:55.750: NIGPIBDD: SendGPIB: CH2;DB;FA;MN;TM3;
 8:20:55.968: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3001) returned: 1000
 8:20:55.968: DVDRSYS.DLL: GetInfoString((ID) 524289, (InfoID) 3002) returned: 4.01E+010
 8:20:55.968: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.52234E-044, (Data2) 0)
 8:20:56.000: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1) 2.38221E-044, (Data2) 0)
 8:20:56.000: DVDRSYS.DLL: InitDevice((ID) 589826)

8:20:56.515: NIGPIBDD: SendGPIB: 0U0J0S0Q
8:20:56.734: NIGPIBDD: SendGPIB: 0K1X50ID0R
8:20:57.250: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3001) returned: 1000
8:20:57.250: DVDRSYS.DLL: GetInfoString((ID) 589826, (InfoID) 3002) returned:
1.81E+010
8:20:57.265: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:20:57.281: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:20:57.296: DVDRSYS.DLL: InitDevice((ID) 655360)
8:20:57.312: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3001) returned: 100000
8:20:57.328: DVDRSYS.DLL: GetInfoString((ID) 655360, (InfoID) 3002) returned: 1E+009
8:20:57.328: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:20:57.343: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:20:57.343: DVDRSYS.DLL: InitDevice((ID) 720896)
8:20:57.375: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:20:57.390: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:20:57.390: DVDRSYS.DLL: InitDevice((ID) 786433)
8:20:57.390: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3001) returned: 100000
8:20:57.406: DVDRSYS.DLL: GetInfoString((ID) 786433, (InfoID) 3002) returned: 1.3E+009
8:20:57.406: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:20:57.421: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.38221E-044, (Data2) 0)
8:20:57.421: DVDRSYS.DLL: InitDevice((ID) 851972)
8:20:57.437: NIGPIBDD: SendGPIB: R

8:20:57.437: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3001) returned: 10000
8:20:57.453: DVDRSYS.DLL: GetInfoString((ID) 851972, (InfoID) 3002) returned:
1000000000
8:20:57.453: DVDRSYS.DLL: SetValue((ID) 262144, (Function) SM_Event, (Data1)
2.52234E-044, (Data2) 0)
8:20:57.453: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:20:57.453: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:20:57.468: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:20:57.468: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:20:57.484: DVDRSYS.DLL: SetValue((ID) 196611, (Function) Unknown)
8:20:57.484: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_PowerOn)
8:20:58.000: NIGPIBDD: SendGPIB: R

8:21:02.203: NIGPIBDD: SendGPIB: P1

8:21:02.390: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:21:02.406: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:21:02.406: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:21:02.421: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:21:02.421: DVDRSYS.DLL: SetValue((ID) 196611, (Function) AMP_Operate)
8:21:02.437: NIGPIBDD: SendGPIB: R

8:21:06.593: NIGPIBDD: SendGPIB: MM

8:21:10.796: NIGPIBDD: SendGPIB: G4095

8:21:11.203: NIGPIBDD: SendGPIB: O

8:21:12.218: DVDRSYS.DLL: GetValue((ID) 0, (Function) Unknown)
8:21:12.218: DVDRSYS.DLL: GetValue((ID) 65537, (Function) Unknown)
8:21:12.234: DVDRSYS.DLL: GetValue((ID) 131074, (Function) Unknown)
8:21:12.234: DVDRSYS.DLL: GetValue((ID) 196611, (Function) Unknown)
8:21:13.046: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing all remaining 14
8:21:13.046: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 13
8:21:13.046: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 851972)
8:21:13.046: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.062: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.062: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.078: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.078: DVDRSYS.DLL: Going to unload Library
8:21:13.078: DVDRSYS.DLL: Going to release names
8:21:13.078: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 12
8:21:13.093: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 786433)
8:21:13.093: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.109: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.109: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.109: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.109: DVDRSYS.DLL: Going to unload Library
8:21:13.125: DVDRSYS.DLL: Going to release names
8:21:13.125: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 11
8:21:13.140: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 720896)
8:21:13.140: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.140: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.140: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.156: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.156: DVDRSYS.DLL: Going to unload Library
8:21:13.156: DVDRSYS.DLL: Going to release names
8:21:13.156: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 10
8:21:13.171: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 655360)
8:21:13.171: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.187: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.187: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.187: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.187: DVDRSYS.DLL: Going to unload Library
8:21:13.203: DVDRSYS.DLL: Going to release names
8:21:13.203: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 9
8:21:13.218: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 589826)
8:21:13.218: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.218: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.218: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.234: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.234: DVDRSYS.DLL: Going to unload Library
8:21:13.234: DVDRSYS.DLL: Going to release names

8:21:13.234: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 8
8:21:13.250: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 524289)
8:21:13.250: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.265: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.265: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.281: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.281: DVDRSYS.DLL: Going to unload Library
8:21:13.281: DVDRSYS.DLL: Going to release names
8:21:13.281: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 7
8:21:13.296: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 458752)
8:21:13.296: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.296: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.312: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.328: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.328: DVDRSYS.DLL: Going to unload Library
8:21:13.328: DVDRSYS.DLL: Going to release names
8:21:13.328: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 6
8:21:13.343: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 393216)
8:21:13.343: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.343: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.343: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.359: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.359: DVDRSYS.DLL: Going to unload Library
8:21:13.375: DVDRSYS.DLL: Going to release names
8:21:13.375: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 5
8:21:13.375: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 327680)
8:21:13.375: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.390: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.390: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.406: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.406: DVDRSYS.DLL: Going to unload Library
8:21:13.406: DVDRSYS.DLL: Going to release names
8:21:13.406: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 4
8:21:13.421: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 262144)
8:21:13.421: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.421: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.531: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.546: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.546: DVDRSYS.DLL: Going to unload Library
8:21:13.546: DVDRSYS.DLL: Going to release names
8:21:13.546: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 3
8:21:13.562: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 196611)
8:21:13.562: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.562: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.578: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.578: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.578: DVDRSYS.DLL: Going to unload Library
8:21:13.593: DVDRSYS.DLL: Going to release names
8:21:13.593: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 2
8:21:13.593: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 131074)
8:21:13.593: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.609: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()

8:21:13.609: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.625: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.625: DVDRSYS.DLL: Going to unload Library
8:21:13.625: DVDRSYS.DLL: Going to release names
8:21:13.625: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 1
8:21:13.640: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 65537)
8:21:13.640: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.640: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.656: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.656: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.656: DVDRSYS.DLL: Going to unload Library
8:21:13.671: DVDRSYS.DLL: Going to release names
8:21:13.671: DVDRSYS.DLL: UnloadAllDeviceDrivers() Removing: 0
8:21:13.671: DVDRSYS.DLL: UnRegisterDeviceDriver((ID) 0)
8:21:13.671: DVDRSYS.DLL: Going to call CallUnregistered()
8:21:13.687: DVDRSYS.DLL: Going to call CallRemoveDeviceDriver()
8:21:13.687: DVDRSYS.DLL: Going to call ClearFunctionPointers()
8:21:13.703: DVDRSYS.DLL: Going to call SetLowHandleID()
8:21:13.703: DVDRSYS.DLL: Going to unload Library
8:21:13.703: DVDRSYS.DLL: Going to release names